Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FEB 27 2014

Expires: July 31, 2010

SF-077085 SUNDRY NOTICES AND REPORTS ON WELLS Farming Moliftindian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enteran of Lind Managemen abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. **OMLER A 6E** 2. Name of Operator 9. API Well No. ConocoPhillips Company 30-045-24208 10. Field and Pool or Exploratory Area 3a. Address 3b. Phone No. (include area code) PO Box 4289, Farmington, NM 87499 (505) 326-9700 OTERO CHACRA/BASIN DAKOTA 4. Location of Well (Footage, Sec., T.R.M., or Survey Description) 11. Country or Parish, State UNIT D (NWNW), 990' FNL & 930' FWL, Sec. 36, T28N, R10W Surface San Juan New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Production (Start/Resume) Acidize Deepen Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity X Subsequent Report Casing Repair New Construction Recomplete Other Remove Packer Change Plans Plug and Abandon Temporarily Abandon & Commingle Plug Back Final Abandonment Notice Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) RCVD MAR a 1 a 2/13/14 MIRU A PLUS #7. NDWH. NU BOPE. PT BOPE. TEST OK. 2/14/14 TOOH w/ 1 1/4" long string tubing. 2/17/14 TOOH w/ 2 3/8" short tubing. Mill on Packer from 3' to 3333' without any success. Pulled packer above perf's. 2/18/14 TOOH w/ packer through wellhead. Cleaned out to PBTD @ 6514'. 2/20/14 TIH w/ 205 its., 2 3/8", 4.7#, J-55 tubing, set @ 6,404' w/ FN @ 6403' (new tubing size & set depth) 2/21/14 ND BOPE. NU WH. PT tubing to 500#. Good test. RD RR @ 11:00 hrs on 2/21/14. This well is now a Otero Chacra/Basin Dakota well being commingled per DHC Order 1952.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

DENISE JOURNEY

Title

REGULATORY TECHNICIAN

2/27/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

FEDIA 8 2014

Office

FARMINGTON FIELD OFFICE entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.