Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resou		
1625 N. French Dr., Hobbs, NM 87240	WELL API NO. 30-045-07822	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVIS	S. Indicate Type of Lease	
District III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505	STATE FEE 🗴	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.	
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B/ DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC PROPOSALS.)	ACK TO A CH 7. Lease Name or Unit Agreement Name: ABRAMS GAS COM D	
1. Type of Well: Oil Well Gas Well 🕱 Other	8. Well Number	
2. Name of Operator	9. OGRID Number	
XTO ENERGY INC.	#1	
3. Address of Operator	10. Pool name or Wildcat	
382 CR 3100 AZTEC, NM 87410 4. Well Location	AZTEC PC/AZTEC FS	
4. Wen Elocation		
Unit Letter <u>I</u> : <u>1650</u> feet from the <u>SOUTH</u> li	ne and990 feet from theAST line	
Section 29 Township 29N Range	10w NMPM san juan County nm	
11. Elevation (Show whether DR, RKB,		
5535' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
	CEMENT JOB CEMENT JOB OIL CONS. DIU.	
	DIST. 3	
	State La	
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
XTO Energy Inc. proposes to plug and abandon this well per the attached procedure and will be using a		
Closed Loop System. Please see also the attached current and proposed wellbore diagrams.		
Notify NMOCD 24 hrs prior to beginning		
operations		
Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my	v knowledge and belief.	
SIGNATURE SUMME TITLE LEAD REGILATORY ANALYST DATE		
C C Type or print name <u>SHERRY J. MORROW</u> E-mail address	PHONE <u>505-333-3630</u>	
For State Use Only Deputy Oil & Gas Inspector,		
APPROVED BY		
Conditions of Approval (if any):		

ML _	
MTG	
Approved	

PLUG AND ABANDONMENT PROCEDURE


· · ·

February 6, 2014

Abrams Gas Com D #1 (AFE# 1401372)

Aztec Pictured Cliffs / Fruitland Sand 1650' FSL and 990' FEL, Section 29, T29N, R10W San Juan County, New Mexico / API 30-045-07822

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.
 - 1. This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - Rods: Yes _____, No __X_, Unknown _____.
 PC Tubing: Yes _X_, No ____, Unknown _____, Size _1.5", Length <u>1812'</u>.
 FS Tubing: Yes _X_, No _____, Unknown _____, Size <u>1.25"</u>, Length <u>1657'</u>.
 Packer: Yes _X_, No _____, Unknown _____, Type <u>Baker D @ 1780'</u>
 If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
 - 4. Plug #1 (Pictured Cliffs perforations and top, 1763' 1663'): PU and TIH with 5.5" cement retainer, set at 1763'. Load casing above the CR with water and circulate well clean. Pressure test casing to 800#. If casing does not test, spot or tag subsequent plugs as appropriate. Mix and pump 18 sxs Class G cement above CR to isolate Pictured Cliffs interval. PUH.
 - 5. Plug #2 (Fruitland perforations and top, 1566' 1466'): Pressure test casing to 800#. *If casing does not test, spot or tag subsequent plugs as appropriate*. Mix and pump 18 sxs Class G cement inside casing to cover the Fruitland interval. PUH.
 - 6. Plug #3 (Kirtland and Ojo Alamo tops, 800' 516'): Mix and pump 39 sxs Class G cement inside casing to cover the Kirtland and Ojo Alamo tops. PUH.
 - 7. Plug #4 (8.265" Surface casing, 258' 0') Connect the pump line to the bradenhead valve. Pressure test the BH annulus to 300#; note the fluid volume to load. If the BH annulus tests, then mix 35 sxs Class G cement and spot a balanced plug inside the 5.5" casing to cover surface casing shoe, circulate cement to surface out the casing valve. TOH and LD the tubing. If the BH annulus does not test, then perforate at the appropriate depth to fill the bradenhead annulus to surface. TOH and LD tubing. Shut in well and WOC.
 - 8. ND cementing valves and cut off wellhead. Fill 5.5" casing with cement as necessary. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.



a. 1

,

