Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-013:
Expires: Info 31, 2011

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

phandanad well. The form 2160 3 (APD) for each proposals

5. Lease Serial No. NMNM0206995

abandoned we		6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well		8. Well Name and No. AZTEC 35 4					
☐ Oil Well ☑ Gas Well ☐ Ot 2. Name of Operator		J MORROW		9. API Well No.			
XTO ENERGY INC	E-Mail: sherry_morrow@xtoe			30-045-23869-00-S1			
3a. Address 382 ROAD 3100 AZTEC, NM 87410		e No. (include area code 5.333.3630)	10. Field and Pool, or Exploratory HARPER HILL FRUITLAND SAND PC			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parish, and State			
Sec 35 T30N R14W SESW 1 36.765990 N Lat, 108.281480				SAN JUAN COUNTY, NM			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACT				ON		
☐ Notice of Intent	☐ Acidize ☐ 1	Deepen	☐ Producti	on (Start/Resume)	■ Water Shut-Off		
	☐ Alter Casing ☐ ☐	Fracture Treat	□ Reclama	ntion	☐ Well Integrity		
Subsequent Report	☐ Casing Repair ☐ 1	New Construction	☐ Recomp	lete	☐ Other		
☐ Final Abandonment Notice	- ·	Plug and Abandon	-	arily Abandon			
<u> </u>	Convert to Injection	Plug Back	☐ Water D				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) XTO Energy Inc. has plugged and abandoned this well per the attached summary report. RCVD MAR 25 '14 OIL CONS. DIV. DIST. 3							
Electronic Submission #239514 verified by the BLM Well Information System For XTO ENERGY INC, sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 03/21/2014 (13SXM0483S)							
Name (Printed/Typed) SHERRY	JMORROW	Title REGUL	ATORY ANA	LYST			
Signature (Electronic S	Submission)	Date 03/20/20	014				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By ACCEPT	ED	STEPHEN TitlePETROLE	MASON UM ENGINE	ER	Date 03/21/2014		
ertify that the applicant holds legal or equivalent would entitle the applicant to condu		Office Farmingt	Office Farmington				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for an tatements or representations as to any matte	y person knowingly and r within its jurisdiction.	willfully to mal	te to any department or ag	gency of the United		

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

XTO Energy Inc. Aztec 35 #4

March 13, 2014 Page 1 of 1

1120' FNL and 1600' FWL, Section 35(N), T-30-N, R-14-W San Juan County, NM Lease Number: NMNM-0206995 API #30-045-23869

Plug and Abandonment Report Notified NMOCD and BLM on 3/11/14

Plug and Abandonment Summary:

Plug #1 with 38 sxs (44.84 cf) Class B cement 1) pump 28 sxs to circulate good cement out casing valve 2) TOH LD tubing to 289', 3) pump 10 sxs to circulate good cement out casing valve again filling well with cement from 1100' to surface to cover the Fruitland top, 7" casing shoe and surface.

Plug #2 with 26 sxs Class B cement top off casings with poly pipe and install P&A marker.

Plugging Work Details:

- 3/12/14 Rode rig and equipment to location. Spot in and RU. X-over for rods. Check well pressures: SITP 7 PSI, SICP 30 PSI and SIBHP 0 PSI. RU relief lines and open well to pit. Dig out bradenhead and install 2" plumbing to surface. LD PR and stuffing box, 2', 4' x 5-/8" rod subs, 44 5/8" rods and rod pump. X-over for tubing. ND wellhead. MU 2-7/8" 7-1/2" 3K flange, strip on and NU BOP. TOH and tally 1 jnt 1-1/2" IJ tubing, 10' x 1-1/2" IJ sub, 34 jnts 1-1/2" IJ, SN, 17' 1-1/2" IJ EMA (35 jnts 1-1/2" IJ tubing total 1116.74'). Note: 1 jnt had a hole. RU A-Plus wireline. RIH with 2.25" GR to 1113'. Set 2-7/8" PW CIBP at 1100'. SI well. SDFD.
- 3/13/14 Open up well; no pressures. TIH 1-1/2" IJ tubing open-ended and tag CIBP at 1100'. RU pump to bradenhead and load with ¾ bbl leaking nipple in casing head. Replace nipple in casing head. Pressure test bradenhead to 300 PSI, OK. Circulate well clean. Casing leaking above casing head, unable to pressure test casing. Spot plug #1 with calculated TOC at surface. TOH and LD all tubing. SI well. WOC. TIH and tag cement at 65'. ND BOP and companion flange. RU High Desert. Cut off wellhead. Found cement down 16' in 7" casing and 65' in 2-7/8" casing. Spot plug #2 and top off casings and install P&A marker. RD and MOL.

Dusty Meecham, XTO representative, was on location. Derrick McCuller, BLM representative, was on location