<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to accordance with 19.15.29 NMAC.

			Rele	ease Notific	ation	and Co	rrective A	ction	1					
		OPERA	ıl Report		Final Report									
Name of Co	mpany B	OPERATOR												
		th St, Farming	Telephone No.(505) 326-9837											
Facility Nar	ne: Ute 24	Facility Type: Gas Well												
Surface Owner Tribal Mineral Owner T							Tribal (1-22-IND-2772) API No.30-045-29156							
				LOCA	TION	OF REI	LEASE							
						South Line	1		West Line	County				
E	20	North	1630		West San Juan									
						_	e <u>-108.336680</u>							
Type of Pale	ase Hyd	rocarbon & I	Produced		UKE	OF REL			Voluma B	annuara d				
Type of Release Hydrocarbon & Produced Water							Volume of Release Volume Red 378.46BBLS Hydrocarbon & 195BBLS H					Hydrocarbon		
							14.46BBLS Produced Water							
Source of Release Oil Dump Line							Date and Hour of Occurrence Unknown Date and Hour of Discovery 12/14/13 at 2:00PM							
Was Immediate Notice Given?							If YES, To Whom?							
		COBLM (Ryan Joyner), UMU (Scott Clow) & NMOCD (Jonathan Kelly)												
By Whom? Crystal Tafoya							Date and Hour 12/15/2013 at 1:28PM							
Was a Watercourse Reached? ☐ Yes ☒ No							If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*									Dr.	YIN NEA	10:1			
N/A		. ,	,			RCVD DEC 19'13 OIL CONS. DIV.								
									· ·	DIST.				
Describe Cau	se of Probl	em and Remed	dial Actio	n Taken *					· · · · · · · · · · · · · · · · · · ·	91.11.	<u>, </u>			
					plug an	d broke allo	wing the tank to	backflo	ow out the	2" line into	the co	ntainment.		
The dump line from 500bbl Production Tank froze at the bull plug and broke allowing the tank to backflow out the 2" line into the containment. 378bbls of Hydrocarbon and 14bbls of Produced Water was released. The location was shut-in prior to this release and has remained shut-in.														
SPEC Trucks were called to location and 195bbls of Hydrocarbon was recovered.														
		and Cleanup A			l four aloue	· :6								
Conocorniii	ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.													
I hamahar aanti	futhat tha	information ai	van ahava	is true and comp	lote to th	a bast of my	knowledge and ur	ndorato	nd that nurs	uent to NIM	OCD r	ulas and		
							nd perform correct							
public health	or the envi	ronment. The	acceptano	ce of a C-141 repo	rt by the	NMOCD m	arked as "Final Re	eport" d	loes not reli	eve the ope	rator of	liability		
							on that pose a three							
				otance of a C-141	report ac	oes not reliev	e the operator of r	espons	ibility for co	ompiiance v	/ith any	otner		
federal, state, or local laws and/or regulations.							OIL CONSERVATION DIVISION							
Signature:							<u> </u>							
							· · · · · · · · · · · · · · · · · · ·							
Digitature.					/	Approved by Environmental Specialist. Kelly								
Printed Name	e: Crystal	Tafoya									V			
Title: Field Environmental Specialist							Approval Date: 4/11/2014 Ex			xpiration Date:				
E-mail Add-a	see orgatal	tafoya@conoc	onhilling	com		Conditions of Approval:				_				
15-man Audre	os. crystal.	anoy alayeonoe	Conditions of Approval.				Attached							
Date: 12/18/2013 Phone: (505) 326-9837														

NJK 1410139035