

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report


Name of Company: BP America Production Company	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Atlantic B LS 3A	Facility Type: Natural Gas Well	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004522989

**LOCATION OF RELEASE**

Unit Letter: I	Section: 04	Township: 30N	Range: 10W	Feet from the 1800	North/South Line South	Feet from the 825	East/West Line East	County: San Juan
-------------------	----------------	------------------	---------------	-----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.83839 Longitude 107.88203

**NATURE OF RELEASE**

Type of Release: Natural Gas	Volume of Release: 51.8 MCF	Volume Recovered: none
Source of Release: hung dump valve on separator	Date and Hour of Occurrence: 2/23/2014 11:30 am -2:30 pm	Date and Hour of Discovery: 2/23/2014 2:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Field technician found hung dump valve on separator blowing to the production tank which vents to atmosphere. Well is shut-in. Dump valves on HLP separator will be investigated to determine cause of malfunction.		
Describe Area Affected and Cleanup Action Taken.* No clean-up action is possible. Natural Gas dissipated to atmosphere.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 4/28/14	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	
Date: 2/25/2014 Phone: 505-326-9457	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Incident # NCS 1411839176