Form 3160-5 (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			OMB1	1 APPROVED NO. 1004-0135 s: July 31, 2010	
SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well			8. Well Name and No		
🗋 Oil Well 🛛 Gas Well 📋 Other				CANYON LARGO UNIT 455	
2. Name of Operator Contact: CATHERINE SMITH HUNTINGTON ENERGY LLC E-Mail: csmith@huntingtonenergy.com				30-039-27749-00-S1	
3a. Address 908 NW 71ST ST OKLAHOMA CITY, OK 7	3116	3b. Phone No. (include area ec Ph: 405-840-9876 Ext: 1 Fx: 405-840-2011		BASIN DAKOTA	
4. Location of Well (Footage, S	ec., T., R., M., or Survey Description	n)	11. County or Parish, and State		
Sec 1 T25N R7W SESE 2 36.424408 N Lat, 107.522			RIO ARRIBA C	OUNTY, NM	
12. CHECK A	APPROPRIATE BOX(ES) T	O INDICATE NATURE O	F NOTICE, REPORT, OR OTHI	ER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
		Deepen	□ Production (Start/Resume)	□ Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	□ Well Integrity	
Subsequent Report	🗖 Casing Repair	New Construction	Recomplete	□ Other	
Final Abandonment Notic	e 🗖 Change Plans	Plug and Abandon	🛛 Temporarily Abandon		
BP	Convert to Injection	Plug Back	Water Disposal		
If the proposal is to deepen dire Attach the Bond under which th following completion of the inv testing has been completed. Fin determined that the site is ready	ctionally or recomplete horizontally e work will be performed or provide olved operations. If the operation re al Abandonment Notices shall be fi for final inspection.)	, give subsurface locations and me e the Bond No. on file with BLM/I esults in a multiple completion or r led only after all requirements, inc	ting date of any proposed work and appro asured and true vertical depths of all perti 31A. Required subsequent reports shall b ecompletion in a new interval, a Form 31 luding reclamation, have been completed ne above referenced nation in total CONS. DIV DIS	inent markers and zones. e filed within 30 days 60-4 shall be filed once , and the operator has	
	TA approved u	Inr. 1 5/1/15	APR 2 4		
	<i>v</i>	Notify NMOCD 24 hrs prior to beginning operations			
14. I hereby certify that the forego	Electronic Submission #	242941 verified by the BLM V ON ENERGY_LC, sent to th cessing by STEVE MASON of	e Farmington		
Name (Printed/Typed) CATH	ERINE SMITH	Title REG	JLATORY		
Signature (Electro	nic Submission)	Date 04/22	/2014		
	THIS SPACE FO	OR FEDERAL OR STAT	E OFFICE USE		
_Approved By_STEPHEN_MAS Conditions of approval, if any, are att certify that the applicant holds legal of which would entitle the applicant to of	ached. Approval of this notice does or equitable title to those rights in the	s not warrant or	EUM ENGINEER	Date 04/23/2014	
Title 18 U.S.C. Section 1001 and Titl States any false, fictitious or fraudu	e 43 U.S.C. Section 1212, make it a lent statements or representations as	crime for any person knowingly a to any matter within its jurisdiction	nd willfully to make to any department or m	agency of the United	
** BLM R	EVISED ** BLM REVISE	D ** BLM REVISED ** BI	LM REVISED ** BLM REVISE	D **	

-

.

. •

NNOCDN

,

Huntington Energy, L.L.C. 908 NW 71st

908 NW 71* Oklahoma City, OK 73116 (405) 840-9876 & Fax # (405) 840-2011

Canyon Largo Unit #455

1285' FSL & 1300' FEL, Sec. 1-25N-7W Rio Arriba Co., New Mexico API #30-039-27749

Procedure to TA:

- 1. MIRU WOR.
- 2. Install 3000 psi BOP.
- 3. TOOH w/2 ³/₈" tubing.
- 4. MIRU W/L truck. RIH & set plug @ 7150'. POOH. RD & Rel W/L truck.
- 5. TIH w/ 2 ³/₈" tubing. CIR & load hole w/treated wtr. SI pipe rams & pretest casing to 500 psi for 30 min. Rel pres.
- 6. ND BOP. NU Valve. RD & Rel all equip.
- 7. Schedule TA test w/NMOCD.
- 8. TA well.

Canyon Largo 455

PROPOSED TA NW SE SE 1 - 25N - 7W Rio Arriba County, New Mexico 1285 FSL 1300 FEL

API: 30039277490000 Today's Date: November 13, 2007 Spud: April 27, 2005 DK Completion: May 26, 2005 set composite Plug 11/13/08 over Encinal

> Formation Tops: Fruitland @ 2594'

Pictured Cliffs @ 2887' Mesaverde @ 4435' Niobrara @ 6288'


Gallup @ 6692'

Dakota @ 7183'

Morrison @ 7508'

Active Perfs: 7184 - 7189' 7280 - 7289' 7310 - 7312' 7323 - 7329' 7348 - 7359' Behind Plug: 7377 - 7400'

Inactive Perfs 7494 - 7507' 7544 - 7548'



KB 6897' DF GR 6881'

8-5/8" 24# csg @ 370' cmt w/280 sx TOC surface

TA Set CBP @ 7150

224 jts 2-3/8" EUE 8rd J-55 4.7# tubing @ 7269'

Composite Bridge Plug @ 7370'

CIBP @ 7480'

CIBP @ 7530'

4-1/2" 11.6# N-80 LT&C csg set @ 7620' cmt w/900 sx 65/35 Poz tail w/900 sx 50/50 Poz. TOC surface