

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: San Juan 29-7 Unit 38A	Facility Type: Gas Well

Surface Owner Public (Private)	Mineral Owner Fee	API No. 3003921615
---------------------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter I	Section 12	Township 29N	Range 07W	Feet from the 1740	North/South Line South	Feet from the 850'	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.73797** Longitude **-107.51559**

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 9.455 BBL	Volume Recovered 0BBL
Source of Release Oil Dump Line Leak	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 04/26/14 @ 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD, Brandon Powell	
By Whom? Lisa Hunter	Date and Hour 04/29/14 @ 8:16 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

OIL CONS. DIV DIST. 3

MAY 09 2014

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Crack in the tank riser from separator dump line caused the leak of approximately 9.455 BBLs of hydrocarbon.

Describe Area Affected and Cleanup Action Taken.*

Third-party Environmental assessed affected area, and excavation to remediate will be scheduled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: **Lisa Hunter**

Approved by Environmental Specialist:

Title: **Field Environmental Specialist**

Approval Date:

5/9/14

Expiration Date:

E-mail Address: **Lisa.Hunter@cop.com**

Conditions of Approval:

Attached ☐

Date: **May 7, 2014**

Phone: **(505) 326-9786**

* Attach Additional Sheets If Necessary

#NLS 1412953 121