

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

1. Type of Well Gas	5. Lease Number NM-12021
2. Name of Operator Max D. Webb	6. If Indian, All. or Tribe Name
3. Address & Phone No. of Operator PO Box 190, Farmington, NM 87499	7. Unit Agreement Name
Location of Well, Footage, Sec., T, R, M 790' FSL & 790' FEL, Section 27, T-27-N, R-13-W,	8. Well Name & Number Federal #3
	9. API Well No. 30-045-22139
	10. Field and Pool WAW PC.
	11. County & State San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -

13. Describe Proposed or Completed Operations

Max Webb proposes to plug and abandon per following:

Pull tubing and remove equipment.

Move on and rig up cementing equipment. Pump 20 bbls water down the 4.5" casing and observe bradenhead valve for flow or blow. Mix and pump 120 sxs Class B cement (15.6 ppg, 1.18 cf/sx) down the 4.5" casing to fill the well with cement; note, after the first 10 sxs, drop 30 frac ball (40 PC perforations reported). WOC. Tag cement in casing and top off is necessary. Cut off wellhead and run 100' of 1.25" poly pipe down the 4.5" x 8.625" annulus and fill with cement, approximately 22 sxs Class B. Install p&a marker and MOL.

14. I hereby certify that the foregoing is true and correct.

Signed Max D. Webb Title Operator Date 4/16/14

(This space for Federal or State Office use)

APPROVED BY Original Signed: Stephen Mason Title _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCDA

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON FIELD OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402

Attachment to notice of

Re: Permanent Abandonment

Intention to Abandon:

Well: 3 Federal

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
3. The following modifications to your plugging program are to be made:
 - a) After plug has set, tag top of cement and refill casing with cement if necessary.
 - b) Since the top of cement behind the 4 1/2" casing is unknown, a cement plug between the 7" and the 4 1/2" casings is required. The Kirtland top is at 192', therefore a surface plug from 242' to surface inside and outside the 4 1/2" would cover the Kirtland, Ojo Alamo and surface casing.

You are also required to place cement excesses per 4.4 and run a cement bond log per 4.6 of the attached General Requirements

Office Hours: 7:45 a.m. to 4:30 p.m.