Conditions of Approval (if any):

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

XTO Energy Inc. Callison #1

May 21, 2014 Page 1 of 1

850' FSL and 990' FWL, Section 29, T-31-N, R-11-W San Juan County, NM Lease Number: FEE API #30-045-20896

Plug and Abandonment Report Notified NMOCD and BLM on 5/16/14

Plug and Abandonment Summary:

- Plug #1 with 28 sxs (33.04 cf) Class B cement inside casing from 2350' to 1334' to cover the Pictured Cliffs and Fruitland tops. Tag TOC at 1464'.
- Plug #2 with 66 sxs (77.88 cf) Class B cement inside casing from 840' to 282' with 2 sxs below, 50 sxs outside, 14 sxs above CR to cover the Kirtland and Ojo Alamo tops. Tag TOC at 586'.
- Plug #3 with 77 sxs (90.86 cf) Class B cement inside casing from 193' to surface to cover the 8-5/8" shoe and surface.
- Plug #4 with 20 sxs Class B cement top off casing and install P&A marker.

Plugging Work Details:

- 5/16/14 Rode rig and equipment to location. Spot in. SDFD.
- 5/19/14 RU. Check well pressures: SICP 230 PSI and SIBHP 10 PSI. RU relief lines. Blow well down. Pump 15 bbls of water down casing to kill well. ND wellhead. MU 2-7/8" x 7-1/16" companion flange. NU BOP and function test. A-Plus wireline PU 2.25" GR to 2360'. TIH with 2-7/8" PW CIBP and set at 2350'. Circulate well clean. RU Blue Jet wireline. Ran CBL from 2350' to surface, good cement in annulus up to 1050' with bridges up to 135'. Attempt to pressure test casing to 500 PSI, bled down. Received verbal approval fr/Monica Kuehling w/NMOCD @ 12:30 p.m. 5/19/14 to combine Plgs #1 & #2. Spot plug #1 with calculated TOC at 1334'. SI well. SDFD.
- 5/20/14 Open up well; no pressures. RU relief lines. Blow well down. TIH and tag TOC at 1464'. Wait on orders. ND BOP and dig out wellhead. Wait on welder. Cut off wellhead. Weld on slip in collar. Perforate 3 bi-wire holes at 840'. Establish circulation. Attempt to pressure test casing to 800 PSI, lost 50 PSI in 3 minutes. TIH with 2-7/8" CR and set at 790'. Spot plug #2 with calculated TOC at 282'. SI well. SDFD.
- 5/21/14 Open up well; no pressures. TIH and tag TOC at 586'. TOH and LD all tubing. Pressure test casing to 800 PSI, OK. Perforate 3 bi-wire holes at 193'. Pump 1 bbl of water down casing with no pressure. Circulate out top of bradenhead. Establish rate of 3 bpm at 0 PSI. Spot plug #3 with calculated TOC at surface. RD. Write Hot Permit. Cut off wellhead. Found cement down 5' in 2-7/8" and 8-5/8" casing. Spot plug #4 top off casings and install P&A marker. RD and MOL.

Monica Kuehling & John Durham, NMOCD representative, was on location.