State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor		STATE OF NEW METICS
David Martin Cabinet Secretary-Designate	Jami Bailey, Division Director Oil Conservation Division	
Brett F. Woods, Ph.D. Deputy Cabinet Secretary	, - -	CONSERVATION DIVISION
New Mexico Oil Conservation Divis	1	
listed below are made in accordance		
and are in addition to the actions	. • •	on the
following <u>3160-4 or .</u>	3160-5 form.	
Operator Signature Date: 6/9/14	!	
Application Type:	!	
	j Change 💹 Rec	omplete/DHC
☐ Location Change ☐ Oth	er:	
Well information:	•	
APIWELL# Well Name Well # Operator Name Typ		
30-045-11147-00-00 UTE INDIANS A 004 XTO ENERGY, INC G Conditions of Approval:	A San Juan U I 35	32 N 14 W
••		
Notify NMOCD 24hrs prior to beginning operation	ns	
Provide CBL to agencies for review/approval prior	to cementing or perforation	ons
Extend plug 1 from 7780 to 7600	t	
Extend Chinle plug to 3922	Ì	
Extend Chime plug to 3722	•	
Add Entrada plug 3440-3540	1	
Extend Morrison/ Dakota plug to 2155 to cover G	raneros	
Add Gallup plug 1395-1495	;	
	1	
B2. 16/1/		
Volande Velle	: 	
NMOCD Approved by Signature Date	<u>14</u>	

Form-3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

14-20-604-62

If Indian, Allottee or Tribe Name

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3	for such proposals. Ute Mountian Ute
SUBMIT IN TRIPLICATE - Other	7. If Unit or CA/Agreement, Name and/or
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator	8. Well Name and No. UTE INDIANS A #4
XTO ENERGY INC. 3a. Address 382 CR 3100 AZTEC, NM 87410	9. API Well No. 3b. Phone No. (include area code) 30-045-11147 505-333-3630 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FEL NESE Sec.35(I)-T	UTE DOME PARADOX
	11. County or Parish, State
	SAN JUAN NM
12. CHECK APPROPRIATE BOX(ES	INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
X Notice of Intent	Deepen Production (Start/Resume) Water Shut-Off
Subsequent Report Casin	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Convert to Injection

Plug and Abandon

Plug Back

XTO Energy Inc. proposes to plug and abandon this well per the attached procedure and will be using a Closed Loop System. Please see also the current and proposed wellbore diagrams.

> OIL CONS. DIV DIST. 3 RECEIVED JUN 3 0 2014

Temporarily Abandon

Water Disposal

SEE ATTACHED **CONDITIONS OF APPROVAL**

Final Abandonment Notice

JUN 1 1 2014

Bureau of Land Management Durango, Colorado

· ·			
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 			
SHERRY J. MORROW	Title	REGULATORY ANALYS	<u>r</u>
Signature Sugney Or mouse	Date	6/9/2014	
THIS SPACE FOR FEDER	RAL OR S	STATE OFFICE USE	
Approved by	- Titl	e bysc	Date 6/24/2014
Conditions of approval if any, are attached: Approval of this notice does not warrant or certify the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	hat Off	TRES RIOS F	FIELD OFFICE
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any fection fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	AOC	willfully to make to any departme	nt or agency of the United States any false,

LWA .	
MTG	
Approved	

NOTE: H2S in well

PLUG AND ABANDONMENT PROCEDURE

May 1, 2014

	Barker Dome Paradox Field 1980' FSL and 660' FEL, Section 35, T32N, R14W San Juan County, New Mexico / API 30-045-11147 Lat: N/ Lat: W
Note:	All cement volumes use 10% excess per 1000 foot of depth or 100% excess outside pipe and 50' excess inside pipe, whichever is greater. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
1.	This project will use A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
2.	Install and test location rig anchors. Comply with all Colorado BLM, NMOCD and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. ND wellhead and NU BOP. Function test BOP.
3.	Rods: Yes, No _X, Unknown; Tubing: Yes _X, No, Unknown, Size2-3/8", Length8200', ; Packer: Yes, No _X, Unknown, Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
	CBL log will be run since cement did not circulate and there is no reference to a log
	being run. This procedure is prepared with the understanding that it may be modified
	based on the TOC from the CBL.
4.	β'Aι Ado X Plug #1 (Dakota perforations and top, 7780' – 7680'): Round trip gauge ring or casing
	scraper to 7780' or as deep as possible. RIH and set 5.5" cement retainer at 7780'. RIH with
	tubing. Pressure test tubing to 1000 PSI. Circulate well clean. <u>Pressure test casing to 800</u>
	PSI. If casing does not test then spot or tag subsequent plugs as appropriate. Sting into CR
	and establish injection. Mix and spot 21 sxs above CR to isolate the Paradox interval. PUH.

- 5. Plug #2 (Hermosa top, 6708' 6608'): Mix and pump 20 sxs Class B cement and spot a balanced plug inside casing to cover the Hermosa top. TOH.
- 6. Plug #3 (Chinle top, 4157' 4057'): Perforate 3 squeeze holes at 4157'. Set 5.5" cement retainer at 4107'. Mix 47 sxs Class B cement squeeze 30 sxs outside casing and leave 17 sxs inside casing to cover the Chinle top. TOH.

- 7. Plug #4 (8-5/8" shoe, Morrison and Dakota tops, 2720' 2250'): Perforate 3 squeeze holes at 2720'. Set 5.5" cement retainer at 2670'. Mix 132 sxs Class B cement squeeze 73 sxs outside casing and leave 59 sxs inside casing to cover through the Dakota top. TOH and LD tubing.
- 8. Plug #5 (Mancos top and 13-3/8" surface casing shoe, 470' Surface): Perforate 3 squeeze holes at 470'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 135 sxs Class B cement and pump down the 5.5" casing to circulate good cement out bradenhead. Shut in well and WOC.
- 9. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

Ute Indian A #04

Current

Barker Dome Paradox Field 1980' FSL, 660' FEL, Section 35, T-32-N, R-14-W

San Juan County, NM, API #30-045-11147

Today's Date: 5/01/14 Spud: 3/5/1948

Completed: 8/30/48 Elevation: 6128' GL

6139' KB

15" hole

Mancos @ 420'

Dakota @ 2270'

Morrison @ 2670'

12.25" hole

7-7/8" hole

Chinle @ 4107' *est

Hermosa @ 6658'

Paradox @ 7830'

13-3/8" 48#, H-40 Casing set @ 335' Cernent with 275 sxs, circulated

2-3/8" tubing at 8200'
(251 jts, T&C upset, 4.7#, J-55 with F nipple and notched collar)

8-5/8" 24#, J-55 Casing set @ 2524' Cement with 300 sxs, circulated

TOC unknown, no circulation or log recorded.

Paradox Perforations: 7830' -- 8035', 8185'- 8360'

5.5", 17#, J-55 Casing set @ 8599' Cement with 970 sxs

TD 8599' PBTD 8540'

Ute Indian A #04 Proposed P&A

Barker Dome Paradox Field

Today's Date: 5/01/14

Spud: 3/5/1948 Completed: 8/30/48 Elevation: 6128' GL 6139' KB 1980' FSL, 660' FEL, Section 35, T-32-N, R-14-W San Juan County, NM, API #30-045-11147

15" hole

Mancos @ 420'

Dakota @ 2270'

12.25" hole

Morrison @ 2670'

Chinle @ 4107' *est

Hermosa @ 6658'

Paradox @ 7830'

13-3/8" 48#, H-40 Casing set @ 335' Cement with 275 sxs, circulated

Perforate @ 470'

Plug #5: 470' - 0' Class B cement, 135 sxs

Plug #4: 2720' - 2250' Class B cement, 132 sxs: 59 inside and 73 outside

Set CR @ 2524'

8-5/8" 24#, J-55 Casing set @ 2524' Cement with 300 sxs, circulated

Perforate @ 2720'

Set CR @ 4107'

Plug #3: 4157' - 4057' Class B cement, 47 sxs: 17 inside and 30 outside

Perforate @ 4157'

TOC unknown, no circulation or log recorded.

> Plug #2: 6708' - 6608' Class B cement, 20 sxs

Set CR @ 7780'

Plug #1: 7780' - 7680' Class B cement, 21 sxs

Paradox Perforations: 7830' - 8035', 8185'- 8360'

5.5", 17#, J-55 Casing set @ 8599' Cement with 970 sxs

7-7/8" hole

TD 8599'

PBTD 8540'

XTO Energy Inc.

Tribal Lease: 14-20-604-62 Well: Ute Indians A #04

Location: 1980' FSL & 660' FEL

Sec. 35, T. 32 N., R. 14 W. San Juan County, NM

Provide a copy of the CBL to this office upon completion of the logging.

Conditions of Approval - Notice of Intent to Abandon:

1. Notify this office at least **72 hours** prior to commencing plugging operations.

For Notification, Operators must talk to BLM personnel directly. Do not leave messages on answering machines. Contact Dan Rabinowitz, BLM Petroleum Engineer: office: 970-385-1363, or Rod Brashear: office: 970-385-1347, and cell: 970-799-1244.

- 2. Approval of this Notice of Intent to Abandon (NIA) is for down hole plugging only.
- 3. Materials used will be accurately measured.
- 4. A tank or approved pit must be used for containment of any fluids from the wellbore during plugging operations. All unattended pits are to be fenced.
- 5. Pits are not to be used for disposal of any unauthorized materials.
- 6. All cement plugs are to be placed through a work string. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
 - 6a. Cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100 ft. of the casing or annular void(s) between casings, plus 10% excess volume per 1000 ft. of depth.
 - 6b. Surface plugs must be a minimum of 50 ft. within casing and annular voids.
 - 6c. Cement plugs placed to fill an open hole shall have sufficient volume to fill a minimum of 100 ft. of open hole, plus 10% excess volume per 1000 ft. of depth.
 - 6d. Tag plug #2.
- 7. The well must be filled with a wellbore mud sufficient to stabilize the wellbore. In the absence of any formation pressure data provided by the operator, this mud will have a minimum weight of **9 ppg**. The mud must be left between all plugs.

- 8. A blowout preventer and related equipment shall be installed and tested prior to working in a wellbore with any exposed zones (a) that are overpressured, (b) where pressures are unknown, or (c) known to contain H_2S .
- 9. All activities must conform to Onshore Order #6, H2S Operations.
- 10. Within 30 days after plugging of the well, file 5 copies of a Subsequent Report of Abandonment (SRA) via Sundry Notice. This report should include the following information:
 - a. Date(s) of plugging operations.
 - b. Procedure used to plug the well.
 - c. Depth of plugs.
 - d. Type and volume of plugs set.
 - e. Casing types/lengths left in the well.

Surface Use Directions:

This approval is for the completion of the downhole plugging only. Surface reclamation must be completed, weed free vegetation established, and site accepted by the BIA prior to closure and bond release.

NOTIFICATION:

- The BLM Colorado Minerals Division Physical Scientist/Natural Resources Specialist (970) 385-1242 shall be notified 5 days prior to the onset of pad/road surface reclamation activity.
- The BLM Colorado Minerals Division Physical Scientist/Natural Resources Specialist (970) 385-1242 shall be notified at least 48 hours prior to commencement of final surface reclamation activities.

REQUIREMENTS AT ALL SITES:

- 1. All tanks on-pad, used in plugging or reclamation activities will employ the use of earthen berms or another appropriate form of secondary containment, capable of holding a minimum of 110% of the contained tank volume(s).
- 2. Any cement wash or other fluids shall be placed in a self-contained tank, surrounded by containment dike of 110% of contained volumes for storage and removed for disposal at an approved location off-site.
- 3. Any free liquid accumulating should be vacuumed off to insure a minimum of 2ft. of freeboard on all tanks consistently and removed to an approved facility with receipts for chain of custody submitted to BLM –Minerals Division.

Continued on Page 3.

4. All stormwater mitigations will be in accordance with BLM gold book BMP standards and practices.

According to the regulations in 43 CFR 3162.3-4, a well site is to be reclaimed and re-vegetated directly following plugging. Onshore Orders #1 stipulates that **surface reclamation** be completed within 180 days of final plugging operation completion. Once notified of plugging, a field inspection will be arranged between the Operator, UMU Tribe, the BLM and the respective BIA agency, so that the well pad can be inspected for reclamation requirements and BLM approval, before release from bond liability.