

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. 14-20-603-1376
2. Name of Operator ConocoPhillips Company		6. If Indian, Allottee or Tribe Name NAVAJO ALLOTTED
3a. Address PO Box 4289, Farmington, NM 87499	3b. Phone No. (include area code) (505) 326-9700	7. If Unit of C/A Agreement, Name and/or No. NAVJO ALLOTTED Com 1
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface UNIT A (NENE), 1100' FNL & 1150' FEL, Sec. 24, T25N, R10W		8. Well Name and No. Navajo Allotted Com 1
		9. API Well No. 30-045-11555
		10. Field and Pool or Exploratory Area BASIN DAKOTA
		11. Country or Parish, State San Juan New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 6/4/14 per the attached report.

OIL CONS. DIV DIST. 3

JUN 27 2014

ACCEPTED FOR RECORD

JUN 25 2014

FARMINGTON FIELD OFFICE
BY: L. Solvers

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) PATSY CLUGSTON		Title STAFF REGULATORY TECHNICIAN
Signature <i>Patsy Clugston</i>		Date 6/16/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Conoco Phillips
Navajo Allotted Com 1

June 4, 2014
Page 1 of 2

1100' FNL and 1150' FEL, Section 24, T-25-N, R-10-W
San Juan County, NM
Lease Number: 1A 14-20603-1376
API #30-045-11555

Plug and Abandonment Report Notified NMOCD and BLM on 5/20/14

Plug and Abandonment Summary:

- Plug #1** with 20 sxs (23.6 cf) Class B cement inside casing from 6425' to 6162' to cover the Dakota and Graneros tops. Tag TOC at 6176'. ✓
- Plug #2** with 20 sxs (23.6 cf) Class B cement inside casing from 5471' to 5208' to cover the Gallup top. Tag TOC at 5270'. ✓
- Plug #3** with 20 sxs (23.6 cf) Class B cement inside casing from 4643' to 4380' to cover the Mancos top. Tag TOC at 4404'. ✓
- Plug #4** with 20 sxs (23.6 cf) Class B cement inside casing from 2782' to 2519' to cover the Mesaverde top. No tag. ✓
- Plug #4a (re-pump)** with 20 sxs (23.6 cf) Class B cement inside casing from 2782' to 2519' to cover the Mesaverde top. Tag TOC at 2530'. ✓
- Plug #5** with 20 sxs (23.6 cf) Class B cement inside casing from 2365' to 2102' to cover the Chacra top. Tag TOC at 2130'. ✓
- Plug #6** with 20 sxs (23.6 cf) Class B cement inside casing from 2015' to 1751' to cover the Pictured Cliffs top. Tag TOC at 1760'. ✓
- Plug #7** with 20 sxs (23.6 cf) Class B cement inside casing from 1733' to 1469' to cover the Fruitland top. Tag TOC at 1485'. ✓
- Plug #8** with 40 sxs (47.2 cf) Class B cement inside casing from 1355' to 829' to cover the Kirtland and Ojo Alamo tops. Tag TOC at 942'. ✓
- Plug #9** with 48 sxs (56.64 cf) Class B cement inside casing from 477' to surface to cover the surface casing shoe with 10 sxs circulated to pit. Tag TOC at 40'. ✓
- Plug #10** with 40 sxs Class B cement top off casings and install P&A marker. ✓

Plugging Work Details:

- 5/21/14 Rode rig and equipment to location. Spot in. SDFD.
- 5/22/14 RU. Check well pressures: bradenhead and tubing 0 PSI, casing 5 PSI. RU relief lines and blow well down. ND wellhead. NU BOP. RU Antelope test equipment. Function test BOP, OK. Pressure test pipe rams to 250 PSI and 1200 PSI. Blind rams to 250 PSI and 1200 PSI, OK. PU on tubing hanger. Tag CIBP at 6425'. Establish circulation. Roll hole with total of 100 bbls of water (didn't test casing because of known casing leak). TOH and tally 2-3/8" 4.7# J-55 EUE tubing as follows: 202 jnts, 1 SN, 1 tail jnt, 1 notched collar total 6391'. SI well. SDFD.
- 5/23/14 Bump test H2S equipment. Open up well; no pressures. Ran CBL from 6425' to surface. Calculated TOC at 2010'. TIH and tag CIBP at 6425'. Establish circulation. Spot plug #1 with calculated TOC at 6162'. WOC. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Conoco Phillips
Navajo Allotted Com 1

June 4, 2014
Page 2 of 2

Plugging Work Details (continued):

- 5/27/14 Bump test H2S equipment. Open up well; no pressures. TIH and tag plug # 1 at 6176'. Establish circulation. Attempt to pressure test casing to 800 PSI, bled down to 400 PSI in 1 minute, no test. Spot plug #2 with calculated TOC at 5208'. WOC. TIH and tag plug #2 with calculated TOC at 5270'. Establish circulation. Spot plug #3 with calculated TOC at 4380'. SI well. SDFD. WOC overnight.
- 5/28/14 Bump test H2S equipment. Open up well; no pressures. TIH and tag plug #3 at 4404'. Establish circulation. Attempt pressure test casing to 800 PSI, bled down to 400 PSI in 1 minute, no test. Spot plug #4 with calculated TOC at 2519'. SI well. WOC. No tag on plug #4. Establish circulation. Circulate well clean. Attempt to pressure test casing to 800 PSI bled down to 75 PSI per minute, no test. Spot plug #4a with calculated TOC at 2519'. SI well. WOC overnight. SDFD.
- 5/29/14 Bump test H2S equipment. Open up well; no pressures. TIH and tag plug #4a at 2530'. Casing pressured up to 800 PSI bled off 75 PSI per minute, no casing test. Spot plug #5 with calculated TOC at 2102'. SI well. WOC. TIH and tag plug #5 at 2130'. RIH with 4.5" GR to 1980'. Perforate 3 HSC squeeze holes at 1962'. Casing pressured to 1000 PSI, unable to establish rate bled off 500 PSI in 1 minute and hold 500 PSI. Note: COPC reg, BLM and NMOCD approved inside plug. Spot plug #6 with calculated TOC at 1751'. SI well. SDFD.
- 5/30/14 Bump test H2S equipment. TIH and tag plug #6 at 1760. Establish circulation. Pressure test casing to 800 PSI, OK. Perforate 3 HSC squeeze holes at 1665'. Establish rate. Note: COPC Reg, BLM and NMOCD approved inside plug. Spot plug #7 with calculated TOC at 1469'. SI well. WOC overnight. SDFD.
- 6/2/14 Bump test H2S equipment. Open up well; no pressures. TIH and tag plug #7 at 1485'. Perforate 3 HSC squeeze holes at 1305'. Pressure up to 1000 PSI establish a rate of 8 bpm bled down to 500 PSI in 2 minutes. Wait on orders. Note: COPC Reg, NMOCD and BLM approved inside plug. TIH open ended to 1355'. Establish circulation. Spot plug #8 with calculated TOC at 829'. TIH and tag plug #8 at 942'. Perforate 3 HSC squeeze holes at 426'. Attempt to establish rate into perfs at 426' pressured up to 1000 PSI bled off to 300 PSI in 3 minutes. Wait on orders. SI well. SDFD.
- 6/3/14 Open up well; no pressures. Attempt to circulate well. Pump 1 bbl of water down casing pressured up to 1000 PSI, bled down to 400 PSI and held. Note: COPC approved procedure change. Perforate 4 HSC squeeze holes at 350'. Wait on orders. Note: COPC Reg approved inside plug. Spot plug #9 with TOC at surface. Dig out wellhead. WOC overnight. SI well. SDFD.
- 6/4/14 Open up well; no pressures. Tag plug #9 at 40'. ND BOP. Fill out Hot Work Permit. RU High Desert. Cut off wellhead. Spot plug #10 top off casings and weld on P&A marker. RD and MOL.

Jamie Joe, BLM representative, was on location. ✓
Darrin Halliburton, BLM representative, was on location. ✓
Vic Montoya, MVCI representative, was on location.