State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

, **Q**,

David Martin

Cabinet Secretary-Designate

Jami Bailey, Division Director Oil Conservation Division



Brett F. Woods, Ph.D. Deputy Cabinet Secretary

New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Sig	nature Date: 6/20/1	4											
	Type: P&A				an	ge [Rec	or	np	let	e/l	DН	IC
Well informa	ation:												
APIWELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E
30-039-21476-00- 00	VALENCIA CANYON UNIT	010	XTO ENERGY, INC	G	A	Rio Arriba	F	Н	34	28	Z	4	w
	of Approval: CD 24hrs prior to be to agencies for revi				me	nting							
Extend top o	f Ojo Alamo plug to	340	0 feet										

NMOCD Approved by Signature

Date

Form 3160-5 (August 2007)

TYPE OF SUBMISSION

Subsequent Report

determined that the final site is ready for final inspection.)

X Notice of Intent

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM APPROVED OMB NO. 1004-013' Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

TYPE OF ACTION

Production (Start/Resume)

Reclamation

Recomplete

Do not use this	form for proposal	s to drill o	r to re-en	ter an
abandoned well.	Use Form 3160-3	(APD) for	such pro	posals.

Acidize

Alter Casing

Casing Repair

6. If Indian, Allottee or Tribe Name

Water Shut-Off

Well Integrity

abandoned well. Use Form 3160-3 (APD) for	r such proposals.	` ` ·		
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No		
Type of Well Oil Well		8. Well Name and No. VALENCIA CANYON UNIT #10		
XTO ENERGY INC. 3a. Address 3b. Phone No. (include area code) 382 CR 3100 AZTEC, NM 87410 505-333-3630 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		9. API Well No. 30-039-21476 10. Field and Pool, or Exploratory Area CHOZA MESA PICTURED CLIFFS		
1830' FNL & 820' FEL SENE Sec.34(H)-T28N-R4W	N.M.P.M.	11. County or Parish, State RIO ARRIBA NM		
12. CHECK APPROPRIATE BOX(ES) TO INI	DICATE NATURE OF NOTICE, REI	PORT, OR OTHER DATA		

Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once

testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

Deepen

Fracture Treat

New Construction

XTO Energy Inc. intends to plug and abandon this well per the attached procedure and will be using a Closed Loop System. Please see also the attached current and proposed wellbore diagrams.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND operator from obtaining any other **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

2014 O 7 2014

SEE ATTACHED FOR E 'LSID AID 'SNOO TIO CONDITIONS OF APPROVAL

Title REGULATORY ANALYST
Date 6/20/2014
AL OR STATE OFFICE USE
Title Petroleum Engineer Date 7/2/2014
Office 7

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

LWA	
MTG	
Approved	

PLUG AND ABANDONMENT PROCEDURE

June 3, 2014

Valencia Canyon Unit #10

Choza Mesa Pictured Cliffs
1830' FNL and 820' FEL, Section 34, T28N, R4W
Rio Arriba County, New Mexico / API 30-039-21476
Lat: / Lat:

lote:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
2.	Rods: Yes, NoX, Unknown Tubing: YesX_, No, Unknown, Size2-3/8", Length4266' Packer: Yes, NoX, Unknown, Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. NOTE: BLM requires a CBL log to be run on all wells where the cement did not

NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or where a T.S. or CBL log was not previously run. The procedure will be modified as necessary based on the CBL.

3. Plug #1 (Pictured Cliffs interval and Fruitland top, 4074' – 3849'): Round trip 4.5" gauge ring to 4074' or as deep as possible. RIH and set 4.5" CR at 4074'. Pressure test tubing to 1000#. Circulate well clean. Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plug as appropriate. Mix and pump 21 sxs Class B cement above CR to isolate the Pictured Cliffs interval and cover the Fruitland top. PUH.

See COA

4. Plug #2 (Kirtland and Ojo Alamo tops, 3734' – 3444'): Mix and pump 21 sxs cement inside casing to cover the Kirtland and Ojo Alamo tops. PUH.

See COA

- 5. Plug #3 (Nacimiento top, 2426'- 2326'): Mix and pump 12 sxs cement inside casing to cover the Nacimiento top. TOH and LD tubing.
- 6. Plug #4 (Surface Casing shoe, 304' to Surface): Perforate 3 squeeze holes at 304'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 110 sxs Class B cement and pump down the 4.5" casing to circulate good cement out bradenhead. Shut in well and WOC.
- 7. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Valencia Canyon Unit #10

Current

Choza Mesa Pictured Cliffs 1830' FNL, 820' FEL, Section 34, T-28-N, R-4-W,

Today's Date: 10/16/12 Spud: 10/14/77

Completed: 12/20/77 Elevation: 7276' GL

7288' KB

1830' FNL, 820' FEL, Section 34, T-28-N, R-4-W Rio Arriba County, NM / API #30-039-21476

12.25" hole

8-5/8", 24#, K-55 Casing set @ 254' Cement with 250 sxs (Circulated to Surface)

TOC unknown, did not circulate and calculated cement should have been to surface. Similar wells have casing issues above the 1100'.

Nacimiento @ 2376' *est

Ojo Alamo @ 3494' *est

Kirtland @ 3684' *est

Fruitland @ 3899 *est

Pictured Cliffs @ 4124'

2-3/8" tubing at 4266'

(137 jts, 4.7#, J-55, SN and notched collar)

Pictured Cliffs Perforations: 4124' – 4272'

7-7/8" hole

TD 4370' PBTD 4346' 4.5", 11.6#/10.5#, K-55 Casing set @ 4369' Cement with 1235 sxs (1729 cf)

Valencia Canyon Unit #10

Proposed P&A:

Choza Mesa Pictured Cliffs

1830' FNL, 820' FEL, Section 34, T-28-N, R-4-W, Rio Arriba County, NM / API #30-039-21476

Today's Date: 10/16/12

Spud: 10/14/77 Completed: 12/20/77 Elevation: 7276' GL 7288' KB

12.25" hole

Nacimiento @ 2376' *est


Ojo Alamo @ 3494' *est

Kirtland @ 3684' *est

Fruitland @ 3899 *est

Pictured Cliffs @ 4124'

7-7/8" hole



TD 4370' PBTD 4346'

8-5/8", 24#, K-55 Casing set @ 254' Cement with 250 sxs (Circulated to Surface)

Set CR @ 304'

Plug #4: 304' - 0' Class B cement, 110 sxs

TOC unknown, did not circulate and calculated cement should have been to surface. Similar wells have casing issues above the 1100'.

See COA

Plug #3: 2426' - 2326' Class B cement, 12 sxs

See COA

Plug #2: 3734' - 3444' Class B cement, 26 sxs

Plug #1: 4074' - 3849' Class B cement, 21 sxs

Set CR @ 4074'

Pictured Cliffs Perforations: 4124' – 4272'

4.5", 11.6#/10.5#, K-55 Casing set @ 4369' Cement with 1235 sxs (1729 cf)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Valencia Canyon Unit #10

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Adjust the placement of plug #2 (3816-3526) ft. to cover the Kirtland and Ojo Alamo tops. Adjust cement volume accordingly.
 - b) Bring the top of plug #3 to 2277 ft. to cover the Nacimiento top. Adjust cement volume accordingly.

Operator will run a CBL to verify cement top. Outside plugs will be required if cement top is not adequate for zonal isolation. Submit electronic copy of the log for verification to the following BLM address: tsalyers@blm.gov

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.