	ubmit 3 Copies To Appropriate District State of New Mexico Energy, Minerals and Natural Resources						Form C-103 June 19, 2008				
District						WELL API NO.					
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION						30-045-29825					
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION						5. Indicat	5. Indicate Type of Lease				
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505						STATE FEE					
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505						6. State Oil & Gas Lease No. E6714-8					
	FORM FOR PRO	OPOSALS TO		DEEPEN (OR PLUG		7. Lease	Name o	r Unit Agro	eement N	ame:
1. Type of Well: Oil Well	1. Type of Well:							8. Well Number			
2. Name of Operat							9. OGRIE) Numb	er		
XTO Energy I							_		380		
3. Address of Ope							10. Pool	name oi	r Wildcat		
382 CR 3100	Aztec, NE	W MEXICO 8	7410		<u>.</u>		FRUITLA	ND SANI) PICTURE	D CLIFF	<u>s</u>
4. Well Location											
Unit Letter _	<u> </u>	1150'	_feet from the	SOT	UTH	line and	1670'	_ feet fr	om the	EAST	lin
Section	32		Township	30N	Range	14W	NMPM		County	/ SAN	JUAN
		11. Ele	evation (Show	whether		B, RT, GR,	etc.)				
				543	36' GTL		··· <u> </u>				
	12 Charle	Annranria	ate Box to Ir	dianta	Moturo	of Motion	Danart as	. Otha	· Doto		
	12. Check	. 7 tpproprie	ic box to it	idicate	rature	or rouce	, report, or	Oulci	Data		
NO	TICE OF IN	NTENTION	N TO:		İ	SU	BSEQUE	NT RE	PORT (DF:	
			AND ABANDO	ABANDON X REMEDIAL WORK			(ALTEF	RING CAS	SING [
TEMPORARILY AB											
I EIVIPURARIL I AD	ANDON [□ CHANG	SE PLANS		СОММЕ	ENCE DRIL	LING OPNS.		P AND	Α .	Г
		_			1		LING OPNS.		P AND	Α .	
PULL OR ALTER C	ASING [_	GE PLANS		1	ENCE DRIL G/CEMENT			P AND	Α .	
PULL OR ALTER C	ASING [_			1				P AND	Α .	
PULL OR ALTER C. DOWNHOLE COMM OTHER:	ASING C	MULTI	PLE COMPL	ots all po	CASING	G/CEMENT	JOB				
OTHER: 13. Describe proportion of starting any or recompletion XTO Energy, Closed Loop Ald Fruit	ASING MINGLE osed or complete proposed worker. Inc. intended System. Plea	eted operation rk). SEE RU	ons. (Clearly st ILE 1103. For and abandon and the att	Multiple this wached c	OTHER ertinent de Comple	etails, and strions: Atta	JOB give pertinent ich wellbore oched processed wellbore sed wellbore och wellbore och beginni	dates, i diagram	including e of propose	stimated ed complete using	etion a
PULL OR ALTER C. DOWNHOLE COMM OTHER: 13. Describe proportion of starting any or recompletion XTO Energy, Closed Loop	ASING MINGLE osed or complete proposed worker. Inc. intended System. Plea	eted operation rk). SEE RU	ons. (Clearly stoller 1103. For and abandon lso, the att	this wached co	OTHER ertinent de Comple	etails, and strions: Atta	give pertinent ich wellbore oched processed wellbor	dates, i diagram	including e of propose and will be grams. ONS. DIV	stimated ed complete using	etion a
PULL OR ALTER C. DOWNHOLE COMM OTHER: 13. Describe proportion of starting any or recompletion XTO Energy, Closed Loop Ald Fruit	ASING MINGLE osed or complete proposed work Inc. intended System. Plea	eted operation rk). SEE RU	ons. (Clearly state of the stat	this wached co	OTHER ertinent de Comple vell per surrent a	etails, and getions: Attache attache attache and proposed pri	give pertinent ich wellbore oched processed wellbor fy NMOCD 24 or to beginni operations	dates, i diagram	including e of propose and will be grams. ONS. DIV	stimated ed complete using	etion a
PULL OR ALTER C. DOWNHOLE COMM OTHER: 13. Describe proportion of starting any or recompletion XTO Energy, Closed Loop Ald Fruit	ASING MINGLE osed or complete proposed work Inc. intended System. Plea	eted operation rk). SEE RU	ons. (Clearly state of the stat	this wached co	OTHER ertinent de Comple vell per current de la se Date:	etails, and getions: Attached the attached proportions and proportions with the second proportion of the second proportio	give pertinent ich wellbore oched processed wellbor fy NMOCD 24 or to beginni operations	dates, i diagram dure arce diagonal hrs ng	including e of propose and will be grams. ONS. DIV	stimated ed complete using	a a
PULL OR ALTER C. DOWNHOLE COMM OTHER: 13. Describe proportion of starting any or recompletion XTO Energy, Closed Loop Ald Fruit	ASING MINGLE osed or complete proposed work Inc. intended System. Please the information	eted operation rk). SEE RU des to plug ease see all on above is to the second s	ons. (Clearly state of the stat	Multiple this wached co	OTHER ertinent de Comple vell per current de la se Date:	etails, and setions: Attached the attached proportions and proportion with the set of the attached proportion with the attached prop	give pertinent ich wellbore oched proces sed wellbor fy NMOCD 24 or to beginni operations	dates, i diagram dure arce diagonal hrs ng	including e of propose and will be prams. ONS. DIV	stimated ed complete using DIST.	a 3
PULL OR ALTER C. DOWNHOLE COMM OTHER: 13. Describe proportion of starting any or recompletion XTO Energy, Closed Loop Ald Fruit Spud Date:	ASING MINGLE osed or complete proposed worker. Inc. intended system. Please the information of the inform	eted operation rk). SEE RU des to plug ease see all on above is to the second s	ons. (Clearly state of the stat	Multiple this wached co	OTHER ertinent de Comple vell per current de la comple de Comple vell per current de la comple d	etails, and getions: Attache attache attache and proposed and proposed and proposed and proposed attached and proposed and proposed attached and proposed and proposed attached and proposed attached attached and proposed attached	give pertinent ich wellbore oched processed wellbor fy NMOCD 24 or to beginni operations dge and believe to the control of the control operations dge and believe to the control operations operations	dates, i diagram dure arce diagonal dia	including e of propose and will be prams. ONS. DIVIUL 02	or/ol	a 3
PULL OR ALTER C. DOWNHOLE COMM OTHER: 13. Describe proportion of starting any or recompletion in the starting and starting any or recompletion in the starting and starting any or recompletion in the starting and starting any or recompletion in the starting and starting an	ASING MINGLE osed or complete proposed worker. Inc. intended system. Please the information of the inform	eted operation rk). SEE RU des to plug ease see all on above is to the second s	ons. (Clearly state of the stat	Multiple this wached co	OTHER ertinent de Comple vell per current de la comple de Comple vell per current de la comple d	etails, and getions: Attache attache attache and proposed and proposed and proposed and proposed attached and proposed and proposed attached and proposed and proposed attached and proposed attached attached and proposed attached	give pertinent ich wellbore och wellbore och wellbore sed wellbor fy NMOCD 24 or to beginni operations	dates, i diagram dure arce diagonal dia	including e of propose and will be grams. ONS. DIVIUL 02	or/ol	a 3

BRB	
MTG	
Approved	

WF State 32 #1 Sec 32, T 30 N, R 14 W San Juan County, New Mexico 6/23/2014

Plug and Abandon Procedure

AFE Number:

1405923

Spud Date:

2/22/1999

Surface Casing:

7", 20#, J-55 csg @ 130'. Cmt'd w/50 sx. Circ 5 bbls cmt to surf.

Production Casing:

4-1/2", 10.5#, J-55 csg @ 1,100'. Cmt'd w/115 sx. Circ 10 bbls cmt to surf.

Capacity: .0159 bbls/ft or .6699 gal/ft

Production Tubing:

2-3/8" string

Rod String:

3/4" string

Pump:

1-1/2" rod insert pump

Perforations:

Pictured Cliffs: 905' - 920'

PBTD:

1,059

Recent Production:

INA since 8/28/2009. 8 mcfpd, 9 bwpd.

Notify NMOCD & BLM 24 hours prior to beginning plugging operations

- 1. Check for COA's and approved NOI before beginning operations.
- 2. Test rig anchors.
- 3. Set flowback tank.
- 4. MIRU completion rig. Review JSA.
- 5. Kill well.
- 6. TOH & LD rods & pump.
- 7. ND WH. NU & FT BOP.
- TOH & LD tubing.
- 9. TIH 3-7/8" bit & 3-7/8" string mill to 905' on 2-3/8" workstring. TOH.
- 10. TIH 4-1/2" CR and set @ ±865'. PT tubing. Sting out of CR and circulate hole clean.

- 11. PT casing and CR to 550 psig. If casing does not test, contact engineer.
- 12. MIRU cement truck. Review JSA.
- 13. **Perforation Isolation Plug (865' 815'):** Pump 10 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 865' 815' (volume calculated with 50' excess).
- 14. **Fruitland Coal Top & Surface Plug (210' Surface):** Pump 20 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 210' Surface' (volume calculated with 50' excess).
- 15. TOH & LD tubing.
- 16. RDMO cement truck.
- 17. WOC 4 hours.
- 18. Cut off WH. Fill in casing as needed with cement. Install above ground P&A marker.
- 19. Cut off anchors and reclaim location.

Checklist

Regulatory:

- 1. NOI to P&A on form C-103
- 2. Submit a post-work sundry on form C-103 which details the P&A work and location work within 30 days of completing all required restoration work.

Equipment:

- 1. 1 flowback tank
- 2. 1,000' 2-3/8" workstring
- 3. 4-1/2" cement retainer
- 4. 3-7/8" string mill
- 5. 30 sx Class "B" cement
- 6. 1 above ground marker

Services:

- 1. Completion rig
- 2. Cement truck



www.peloton.com

XTO - Wellbore Diagram

Well Name: WF State 32-01 API/UW N/S Dist (ft) E/W Dist (ft) N/S Ref Location ield Name County State/Province 30045298250000 1.670.0 FEL 1,150.0 T30N-R14W-S32 FSL Twin Mounds Pictured Cliffs San Juan New Mexico Well Configuration Type XTO ID B Orig KB Elev (ft) Gr Elev (ft) KB-Grd (ft) Spud Date PBTD (All) (ftKB) Total Depth (ftKB) Method Of Production Vertical 77676 5,441.00 5,436.00 1,108.0 5.00 2/22/1999 Original Hole - 1059.0 Beam Well Config: Vertical - Original Hole, 6/25/2014 8:45:17 AM Zones fiKB ftKB Top (ftKB) Btm (ftKB) Zone Schematic - Actual Incl (TVD) (MD) Fruitland Sand 920.0 905.0 **Casing Strings** Casing Description OD (in) Wt (lbs/ft) String Grade Set Depth (ftK., -14 Surface 7 20.00 135.0 J-55 OD (in) String Grade Casing Description Wt (lbs/ft) Top Connection Set Depth (ftK. Production 4 1/2 10.50 J-55 1,105.0 5 Cement Туре String Description **Production Casing Cement** Production, 1,105.0ftKB casing 8 Description Туре String 19 Surface Casing Cement Surface, 135.0ftKB casing Comment 135 Perforations 135 Shot Dens Diamete Phasing Curr. (in) Top (ftKB) Btm (ftKB) (shots/ft) (°) 3/17/1999 920.0 Fruitland Sand 3.0 140 **Tubing Strings** Run Date Set Depth (ftKB) Tubing - Production 987.6 894 **Tubing Components** OD (in) (lbs/... Тор Thread Item Description Jts Model Gra. Len (ft) Top (ftKB) Btm (ftKB) 905 Tubing T&C 2 3/8 4.60 J-55 951.46 5.0 956.5 Top (MD):905, Non-.. Des:Fruitland Sand 956.5 Seat Nipple 2 3/8 1.10 957.6 920 ОЕМА 2 3/8 4.70 J-55 30.00 957.6 987.6 Rods 920 Run Date String Length (ft) Set Depth (ftKB) Rod String 974.50 960.0 **Rod Components** 945 OD (in) Grade Top (ftKB) Btm (ftKB) Model Jts Len (ft) Polished Rod 1 1/4 22.00 -14.5 7.5 Rod Sub 3/4 96 12.00 7.5 19.5 35 WCN-96 Sucker Rod 3/4 96 875.00 19.5 894.5 Sinker Bar 1 1/2 C 25.00 894.5 919.5 948 Shear Tool - 21K 3/4 0.50 919.5 920.0 Sinker Bar 1 1/2 C 25,00 920.0 945.0 Lift Sub 1 1.00 945.0 946.0 956 Spiral Rod Guide 3/4 2.00 946.0 948.0 Rod Insert Pump 1 1/2 12.00 948.0 960.0 958 Stimulations & Treatments Total Prop... AIR (b... ATP (psi) MTP (psi) ISIP (psi) V (slurry) (... rac Start Date Top Perf (ft... Bottom Pe.. 3/18/1999 905 920 960 Comment 988 PBTD. 1.059 1,059 1.105 1.105 1,108 TD, 1,108

> Report Printed: 6/25/2014 Page 1/1

WF Federal 32 #1 Sec 32, T 30 N, R 14 W San Juan County, New Mexico

Proposed P&A Diagram

