Form 3160-5 (August 2007)

1. Type of Well

3a. Address

2. Name of Operator

Oil Well

PO Box 4289, Farmington, NM 87499

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

X Gas Well

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

	_		
5	ĭ	ease Serial No	

NM-03402

Basin FC

SUNDAT NUTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals:

Other

ConocoPhillips Company

6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on page 22 1 7-If-Unit of CA/Agreement, Name and/or No. San Juan 32-8 Unit JUN 18 2018. Well Name and No. San Juan 32-8 Unit 236A Fe Although Fire (95APhWell No. 30-045-32331 Burgan on Lancillians 3b. Phone No. (include area code)

10. Field and Pool or Exploratory Area

11. Country or Parish, State

Unit O (SWSE), 760' FSL & 1530' FEL, Sec. 22, T31N, R8W Surface San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Notice of Intent Acidize Deepen Water Shut-Off Well Integrity Alter Casing Fracture Treat Reclamation Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal

(505) 326-9700

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 5/29/14 per the attached report.

ACCEPTED FOR RECORD

OIL CONS. DIV DIST. 3

JUN 27 2014

JUN 25 2014

FARMINGTON FIELD OFFICE BY: TI Salvers

·									
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)									
·									
Arleen White	Title Staff	f Regulatory <u>T</u>	`echnician						
Signature Ailen White	Date 6[]	8/14	,						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by									
		Title		Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or									
that the applicant holds legal or equitable title to those rights in the subject lease which	Office								
entitle the applicant to conduct operations thereon.									

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Conoco Phillips
San Juan 32-8 Unit 236A

May 29, 2014 Page 1 of 1

760' FSL and 1530' FEL, Section 22, T-31-N, R-8-W San Juan County, NM Lease Number: NM-03402 API #30-045-32331

Plug and Abandonment Report Notified NMOCD and BLM on 5/22/14

Plug and Abandonment Summary:

- Plug #1 with CR at 3035' spot 30 sxs (35.4 cf) Class B cement inside casing from 3035' to 2880' to cover the Pictured Cliffs and Fruitland tops. ✓
- Plug #2 with 51 sxs (60.18 cf) Class B cement inside casing from 2345' to 2081' to cover the Ojo Alamo and Kirtland tops. ✓
- Plug #3 with 30 sxs (35.4 cf) Class B cement inside casing from 866' to 711' to cover the Nacimiento top. ✓
- Plug #4 with CR at 231' spot 122 sxs (143.96 cf) Class B cement inside casing from 284' to surface, 11 sxs below CR, 44 sxs above CR and 67 sxs in annulus to cover the surface casing shoe. Tag TOC at 6'.
- Plug #5 with 34 sxs Class B cement top off casing and install P&A marker.

Plugging Work Details:

- 5/23/14 Rode rig and equipment to location. Spot in and RU. SDFD.
- 5/27/14 Check well pressures: tubing, bradenhead 0 PSI and casing 70 PSI. Bump test H2S equipment. RU relief lines. Blow well down. LD polish rod, 2', 6' and 8' pony TOH LD 135 ¾" rods, 4' pony and rod pump. RD rod equipment. ND wellhead. RU Cameron pressure equipment. ND BOP. Cameron pressure test blind rams, 2-3/8" pipe rams to 300 PSI and 1300 PSI, OK. Pull tubing hanger. TOH and tally 48 stands, 11 jnts, 10' sub, SN 2-3/8" tubing, 2-7/8" MA, total 3407'. Round trip 7" string mill to 3060'. TIH with 7" DHS CR and set at 3035'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Pressure test casing to 800 PSI, OK. SI well. SDFD.
- 5/28/14 Bump test H2S equipment. Open up well; no pressures. Ran CBL from 3035' to surface. TOC to be determined by engineer. Spot plugs #1, #2 and #3. Perforate 4 HSC squeeze holes at <u>284</u>'. TIH with 7" DHS CR and set at 231'. Spot plugs #4 with TOC at surface. SI well. SDFD.
- 5/29/14 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 6. Dig out wellhead. RU High Desert. Cut off wellhead. Spot plug #5 top off casings and install P&A marker. RD and MOL.

Ron Chavez, BLM representative, was on location. Jim Morris, MVCI representative, was on location.