State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary-Designate

NMOCD Approved by Signature

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

	following 3	160-4	or 3160) <u>-5</u> forn	n.					
Operator Signatu	re Date:									
Application Type P&		g/Casi e	Ū	ange		Rec	omple	ete/	DH	IC
Well information	:									
API Well Name	Well Operator Name			irf_Owner U		wp N/S 25 N	Rng W/E	Feet N		
30-045- 34725-00- 00 HUERFANO UNIT	304E BURLINGTON RESOURCES OIL & GAS COMPANY LP	G T	San F Juan	IV	4	23 IN	IOW	0703	800	
Conditions of Ap	•									
An MIT will nee T/A past 12/21/	d to be performed 2014.	and appi	roved pr	or to 12/	21/20	14 to	exten	d the		
•				·						
Bend	Sell 1									

7-7-14

Date

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137. Expires: July 31, 2010

5. Lease Serial No

SF-C	701	24

					S	F-078124		
Do not use abandoned	DRY NOTICES AND Ri this form for proposa well. Use Form 3160-	als to drill o	to re-enter a	ais.	6. If Indian, Allottee or Tribe N	Name		
SU	BMIT IN TRIPLICATE - Othe	r instructions or	page 24 On	2047	7. If Unit of CA/Agreement, N	ame and/or No.		
1. Type of Well			TUCHORS ON PAGE AY 22 2014		Huerfano Unit			
Oil Well X Gas Well Other		her Fé	Famington Field Off		8. Well Name and No. Huerfano Unit 304E			
2. Name of Operator		oure.	au of Land is	halloys	9. API Well No.			
Burling	ton Resources Oil & G	as Compar	ıy LP		30-0)45-34725		
3a. Address PO Box 4289, Farmingto	n, NM 87499		No. (include area c 505) 326-970	,	10. Field and Pool or Explorate Bas	ory Area sin Dakota		
4. Location of Well (Footage, Sec., T., R. Surface Unit M (S.,M., or Survey Description) SWSW) 670' FSL & 800	' FWL, Sec.	4, T25N, R10	W	11. Country or Parish, State San Juan	, New Mexico		
12. CHECK	THE APPROPRIATE BOX	(ES) TO INDIC	CATE NATURE	OF NO	TICE, REPORT OR OTH	ER DATA		
TYPE OF SUBMISSION			TYPE	OF AC	CTION			
Notice of Intent	Acidize	Deepe	-		roduction (Start/Resume)	Water Shut-Off		
	Alter Casing	= '	re Treat		eclamation	Well Integrity		
X Subsequent Report	Casing Repair	<u></u>	Construction	=	ecomplete	X Other		
X subsequent report	Change Plans		and Abandon	=	•	Conduct MIT		
Trial Alas Issues (Nation	l ===			=	emporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug I	заск —————	<u> </u>	Vater Disposal	and Extend TA status		
Burlington Resources wh procedure. アみ	nichs to extend the TA si					Fper the attached		
	OIL CONS. DIV DIST. 3 MAY 27 2014							
14. I hereby certify that the foregoing i	s true and correct. Name (Printed	d/Typed)						
	PATSY CLUGST	ON	Title		STAFF REGULATORY	TECHNICIAN		
Signature Fat	in Clust		Date		5/20/2014	4		
	<u> </u>		RAL OR STA	TE OF	FICE USE			
	l Signed: Stephen Maso			Title	·	DaMAY 2 3 2014		
Conditions of approval, if any, are attact that the applicant holds legal or equitable entitle the applicant to conduct operation. Title 18 U.S.C. Section 1001 and Title	ole title to those rights in the subjects thereon.	ect lease which w	ould	Office	to make to any department or a	ngency of the United States any		
Time to 0.5.C. Section 1001 and Title	ט.ט.ט. טכנווטוו 1212, make It	a ormic for any p	erson knowingry at	wintuny	to make to any department of a	.6007 or the Office Braics any		

ConocoPhillips HUERFANO UNIT 304E Expense - MIT

Lat 36° 25' 28.797" N

Long 107° 54' 26.903" W

PROCEDURE

Notify OCD 24 hours in advance to witness MIT testing

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations.
- 2. MIRU pump truck. Check tubing, casing, intermediate, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact the production engineer to review complete BH history and obtain a gas sample/analysis.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl and corrosion inhibitor, if necessary.
- 5. Load tubing with water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the cement plug at 6,200' to 600 psig for 30 minutes on a 2 hour chart with 1000# spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.