Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| FORM APPROV | /ED |
|-------------------|------|
| OMB NO. 1004-0 | 0135 |
| Expires: July 31. | 201 |

| SUNDRY NOTICES AND REPORTS ON WELLS |
|---|
| Do not use this form for proposals to drill or to re-enter an |
| ahandoned well. Use form 3160-3 (APD) for such proposals |

5. Lease Serial No. NMNM99705

| abandoned well. Use form 3160-3 (APD) for such proposals. | | | 6. If Indian, A | 6. If Indian, Allottee or Tribe Name | |
|--|--|---|---|--|--|
| SUBMIT IN TRIPLICATE - Other instructions on reverse side. | | | 7. If Unit or C | 7. If Unit or CA/Agreement, Name and/or No. | |
| Type of Well ☐ Gas Well ☐ Other | | | 8. Well Name a EAGLE SF | 8. Well Name and No. EAGLE SPRINGS 8 FED 2M | |
| 2. Name of Operator Contact: BUTCH BUTLER HPOC, LLC E-Mail: bbutler@highplainsop.com | | | | 9. API Well No. 30-043-20950-00-S3 | |
| 3a. Address 32700 ASPEN DRIVE BUENA VISTA, CO 81211 | 700 ASPEN DRIVE Ph: 719-395-8059 | | | 10. Field and Pool, or Exploratory ARENA BLANCA | |
| 4. Location of Well (Footage, Sec., 7 | ., R., M., or Survey Description) | | 11. County or | Parish, and State | |
| Sec 8 T19N R4W NWNE 330FNL 2275FWL 35.898269 N Lat, 107.281021 W Lon | | | | SANDOVAL COUNTY, NM | |
| 12. СНЕСК АРРІ | ROPRIATE BOX(ES) TO INDIC | CATE NATURE OF 1 | NOTICE, REPORT, OR C | OTHER DATA | |
| TYPE OF SUBMISSION | TYPE OF ACTION | | | | |
| ☐ Notice of Intent | ☐ Acidize ☐ |] Deepen | ☐ Production (Start/Resu | me) | |
| _ | ☐ Alter Casing ☐ | Fracture Treat | ☐ Reclamation | ■ Well Integrity | |
| Subsequent Report | ☐ Casing Repair | New Construction | Recomplete | ☐ Other | |
| ☐ Final Abandonment Notice | ☐ Change Plans | Plug and Abandon | ☐ Temporarily Abandon | | |
| bl | ☐ Convert to Injection ☐ | Plug Back | ■ Water Disposal | | |
| submitted with the 3160-4 Cor "Downhole Water Sink," or DV create a pressure sink and pre A PDF is attached to this Sund At present, this well is equippe in HPOC's Eagle Springs disp | Bond No. NMB 000457. A PDF with the "as drilled & commpletion Report on June 26, 2014 VS. The purpose of the lower conevent water from coning as severe | The completion desippletion at the oil/transely into the upper oil cut-in waiting on injection at the completion at the | ompletion. JU on capacity in tests have | is. DIV DIST. 3 L 0 3 2014 | |
| 14. I hereby certify that the foregoing is Contain the property of the proper | Electronic Submission #251282 v For HPOC, LLC ommitted to AFMSS for processing | , seht to the Rio Puer | co /01/2014 (14JXL0013SE) | | |
| | | | , | | |
| Signature (Electronic S | ubmission) | Date 06/30/20 | 014 | | |
| | THIS SPACE FOR FED | ERAL OR STATE | OFFICE USE | The state of the s | |
| Approved By ACCEPT | ED | JIM LOVATION Title PETROLE | TO UM ENGINEER | Date 07/01/2014 | |
| conditions of approval, if any, are attached ertify that the applicant holds legal or equal which would entitle the applicant to condu | itable title to those rights in the subject le | | co | | |
| itle 18 U.S.C. Section 1001 and Title 43 | U.S.C. Section 1212, make it a crime for | any person knowingly and | willfully to make to any departn | nent or agency of the United | |

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #251282 that would not fit on the form

32. Additional remarks, continued

the 8 Federal 2M following this. Production tests will be reported via Sundry Notice.

Revisions to Operator-Submitted EC Data for Sundry Notice #251282

Operator Submitted BLM Revised (AFMSS) RCMPL SR RCMPL SR Sundry Type: NMNM99705 Lease: NMNM99705 Agreement: HPOC, LLC 32700 ASPEN DRIVE BUENA VISTA, CO 81211 Ph: 719.935.8059 Fx: 719.395.4046 HPOC, LLO 322 N RAILROAD AVE PO BOX 5046 BUENA VISTA CO 81211 Ph: 719-395-8069 Operator: BUTCH BUTLER MANAGER E-Mail: bbutler@highplainsop.com Cell: 719-207-0164 Ph: 719-395-8059 BUTCH BUTLER MANAGER Admin Contact: E-Mail: bbutler@highplainsop.com Cell: 719-207-0164 Ph: 719-395-8059 BUTCH BUTLER MANAGER BUTCH BUTLER Tech Contact: MANAGER E-Mail: bbutler@highplainsop.com Cell: 719-207-0164 Ph: 719-395-8059 E-Mail: bbutler@highplainsop.com Cell: 719-207-0164 Ph: 719-395-8059 Location: NM SANDOVAL State: County: SANDOVAL Field/Pool: ARENA BLANCA ENTRADA SE ARENA BLANCA EAGLE SPRINGS 8 FEDERAL 2M Sec 8 T19N R4W Mer NMP NWNE 330 FNL 2275FE 35.898269 N Lat, 107.281021 W Lon EAGLE SPRINGS 8 FED 2M Sec 8 T19N R4W NWNE 330FNL 2275FWL 35.898269 N Lat, 107.281021 W Lon Well/Facility:

This document contains the completion details for HPOC's Eagle Springs 8 Federal 2M well. It accompanies BLM Form 3160-5 Sundry Notice submitted to the BLM on June 30, 2014.

The well had two phases of completion. Details from each phase follow.

Completion phase one from December 10-12, 2013.

- 1. Move-in rig and run GR-CCL for correlation with open-hole logs. MIRU Aztec Rig #395. ND WH. NU BOP. MIRU Weatherford WL trk. Ran Gamma Ray/CCL fr/surf 5,713′. POH w/WL. RDMO Weatherford WL trk. Weatherford GR 16′ lower than Halliburton open-hole logs run 2/5/13.
- 2. Run Completion Assembly. PU & TIH w/2-3/8" BP, swell pkr assembly (2 swells on 1 jt 2-3/8"), 2ea jts 2-3/8" tbg, 4-1/2" x 2-3/8" T-2 on/off tl, 4-1/2" x 2-3/8" hydraulic set (straight pull w/40k shear) Tubing Anchor Catcher (TAC), 1ea jt 2-3/8" tbg, 1ea 2-3/8" x 4' pup jt, 78ea jts 2-3/8" tbg, 2-3/8" 2-7/8" XO & 96ea jts 2-7/8" tbg. MIRU Weatherford WL trk. RIH w/GR-CCL & corr to previous depth fr 12/10/13. Set top of upper swell @ 5,580', which correlates to 5,564' on Halliburton open-hole logs (16' depth shift). POH w/WL. RDMO Weatherford WL trk. Drop 1-3/4" dissolvable ball (30 minutes) to set TAC. Attempted to load tbg to pump off ball w/o success. Pmp'd 10+ bbls w/no pressure. Decided to shut down due to cold weather and possible frozen water column in tbg string in the AM if load hole with water.
- 3. Hydraulic shear set TAC won't set. MIRU High Tech press trk. Load tbg & pressure up to 3,500 psi (hydraulic shear set @ 3,075 psi on TAC). Bled of press. Pulled tbg up 20' w/no additional weight pulled. Re-positioned tbg. RU swb tls. RIH w/no-go to SN. Tbg clear. POH w/no-go. RD swb tls. Load & pressure up tbg to 3,500 psi for 15 mins. Increased press to 4,000 psi for 5 mins (no shear). Increased press to 4,500 psi (no shear). Bled of press. RU swb tls. Swb fluid out of 2-7/8" tbg. RD swb tls. Attempted to TOH w/tbg. Moved 14' and pulled 20k over string weight (anchor partially set & stuck on csg collar). Wrk'd tbg to 70k w/o success (3 hrs). After discussion the decision was made to work tbg back to original setting depth & land tbg (5,492'). Landed tbg w/donut. ND BOP. NU WH. RDMO AWS Rig #378. Will allow at least 2 weeks for packers to swell & then bring rig back to continue at the same point of the procedure & complete job.
- 4. <u>Depth adjustment.</u> After review of all past and current logs and casing & tubing tallies, it was determined that the depth of the completion string was shifted down 11' from the Halliburton openhole logs and shifted up 5' from the Weatherford GR-CCL logs. These adjusted depths were reported in the completion report and are reflected in the wellbore diagram submitted.

Completion phase two from January 7-10, 2014.

- 1. Pull equipment above TAC. MIRU AWS Rig #746. ND WH. Pulled donut fr/WH. Pulled 5k over string weight w/no movement. Sat down 5k w/no movement. Rotate pipe to the right & "J" off hydraulic set TAC (swell packers held in place). TOH w/96 ea jts 2-7/8" tbg, XO, 78 ea jts 2-3/8" tbg, 2-3/8" x 4' pup jt & 1 ea jt 2-3/8" tbg.
- 2. Run bottom of completion long string for water sink side of completion. PU & TIH w/2-3/8" x 4-1/2" J-tool, 2-3/8" x 6' tbg sub, 1 ea jt 2-3/8" tbg, 4-1/2" TAC w/downhole swivel section attached @ 35k shear, 78 ea jts 2-3/8" tbg, 2-3/8" 2-7/8" XO & 96 ea jts 2-7/8" tbg. Tag'd @ 5,504' (original hydraulic set TAC). Latch on w/J-tool & set 4-1/2" TAC w/5k tens @ 5,457'. Release upper on-off tool. TOH

- w/96 ea jts 2-7/8" tbg, XO, 78 ea jts 2-3/8" tbg. PU & TIH w/2-3/8" x 4-1/2" on-off tool w/J-slots cut out, 78 ea jts 2-3/8" tbg, XO, 3-1/2" x 2-7/8" no turn tool, PCP Stator & 2 ea jts 2-7/8" tbg.
- 3. Run top of completion long string for water sink side of completion with velocity & capillary strings for oil side of completion. TIH w/96 ea jts 2-7/8" tbg along w/3/4" N2 lift nozzle on 1-1/2" poly flow tbg (2,903') & 3/8" cap string (2,903'). Banding poly flow & cap string to the O.D. of 2-7/8" prod string (2 bands per jt). Assembled B-2 adapter flange. Landed all 3 strings w/B-2 adapter flange (threaded for each string & off set cut). NU WH.
- 4. Run PCP rotor and rods, PCP drivehead. PU & TIH w/rotor, 118 ea 7/8" guided rods, 4 ea 7/8" pony rods (6', 4', 2' & 2'). Installed drive unit & spaced out rods 36" above tag bar. SWI. RDMO AWS Rig #746.

Well left ready to proceed with electrical & wellhead/flowline installation.

Eagle Springs 8 Federal 2M

330' FNL, 2275' FEL, Sec 8-T19N-R4W Sandoval County, NM

API: 30-043-20950

Wellbore Diagram Following January 2014 Operations with Downhole Water Sink Completion

Revision date: June 13, 2014

