District J
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office to accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

•			Rele	ease Notificati	on	and Co	rrective A	etion	l			
				OPERATOR			M Initia	al Report 🔲 Final Repo				
Owned Sul	bsidiary of		(Contact Lisa Hunter								
Address 3401 East 30 th St, Farmington, NM						Telephone No.(505) 326-9786						
Facility Name: San Juan 30-6 Unit 489						Facility Type: Natural Gas						
Surface Owner Federal Mineral Owner						Federal API No.3003924926						
LOCATION OF RELEASE												
Unit Letter K	Section 24	Township 30N	Range 06W	Feet from the Nor		South Line	Feet from the 1465	1	Vest Line Vest	County Rio Arriba		
===	ı = :_	0011		Latitude <u>36.796</u>				<u> </u>	., est	1111111		
NATURE OF RELEASE												
Type of Release Produced Water (chlorides with in bermed area)										me Recovered 0 BBLs		
Source of Release Rainwater soaked bermed location						Date and Hour of Occurrence Unknown			Date and Hour of Discovery October 22, 2013			
Was Immedi	ate Notice (Yes	No Not Require	ed		Whom? Kelly, NMOCD cham, BLM (left	t voice n	nessage)			
By Whom? Lisa Hunter						Date and Hour 10/24/13 @ 9:04 a.m. 10/24/13 @ 9:15 a.m.				RCVD NOV 8'13 OIL CONS. DIV.		
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. DIST. 3						
If a Watercon	urse was Im	pacted, Descri	be Fully.*	•		<u>I</u>				, , , , , , , , , , , , , , , , , , , ,		
Describe Cause of Problem and Remedial Action Taken.* A release of unknown causes was discovered to have traveled off location. Evidence of water had breached the berm through a hole at the base, and water contaminated with chlorides had traveled off location greater than 300 feet. Current investigation has ruled out a tank or pipeline release. Reports of standing water (attributed to rainwater) within the berm during the heavy rains around September 26th were reported. The hole in the berm was repaired, and environmental assessment ordered.												
		and Cleanup A ess the soil to		en.* e a path forward for	clèa	n-up if neco	essary.					
regulations a public health should their cor the environ	Il operators or the envir operations h nment. In a	are required to ronment. The ave failed to a	report an acceptanc dequately CD accep	d/or file certain release e of a C-141 report by investigate and remed	e no the iate	tifications at NMOCD m contaminati	nd perform correct arked as "Final R on that pose a thr	ctive acti leport" d reat to gr	ions for rele oes not reli ound water	eases which may endanger eve the operator of liability c, surface water, human health compliance with any other		
						OIL CONSERVATION DIVISION Approved by Environmental Specialist:						
Printed Name: Lisa Hunter						Approval Date: 8/27/2014 Expiration Date:						
Title: Field Environmental Specialist									Expiration	Date:		
E-mail Addre	ess: Lisa.Hu	inter@cop.con	n		{	Conditions of	Approval:			Attached		
Date: November 5, 2013 Phone: (505) 326-9786										1		

* Attach Additional Sheets If Necessary

nJK1423953933