State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 7/29/2014

Well information:

APIWELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E
30-039-06106-	JICARILLA 123	001	ENERGEN RESOURCES	G	Λ	Rio	J	D	7	25	Ν	4	W
00-00	С		CORPORATION			Arriba							

Application Type: P&A Drilling/Casing Change Recomplete/DHC Location Change Other:
Conditions of Approval:
Notify NMOCD 24hrs prior to beginning operations
Provide CBL to agencies for review/ approval prior to cementing

NMOCD Approved by Signature

8-15-2014 Date Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

		Expires	July	31,	2010
-	Loggo	Carial No			

FORM APPROVED OMB NO. 1004-0137

Lease Serial No	5.	Lease	Serial	No
-----------------------------------	----	-------	--------	----

•		•	Ι,	J. Lease Scii	ui 110.
SUNDRY NOTICES	AND REPORTS	ON WELLS	ن ا	Jicarilla	123
Do not use this form for	proposals to drill	or to re-enter an			Illottee or Tribe Name
abandoned well. Use For					
			, , , , , , , , , , , , , , , , , , , ,	Jicarilla	
SUBMIT IN TRIPLICA	TE - Other instruction	ons on page 2		If Unit or C	A/Agreement, Name and/or N
1. Type of Well		J	UL 29 2014		
Oil Well X Gas Well Other		_	18	. Well Name Jicarilla	
2. Name of Operator		لله من في من المناسبة	(3) ARCTOR 12-8(L30/5) // BUS	Carlila CO.	123 C #1
ENERGEN RESOURCES CORPORATION			the second second second second second	APEWell N	40.
3a. Address		3b. Phone No. (include ar	an andal	30-039-06	
2010 Afton Place, Farmington, NM,		505-325-6800			Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)		Į s	3. Blanco	Pictured Cliffs
930' FNL, 830' FWL, Sec. 7, T25N, 1	R04W (D)		<u> </u>		
				11. County of	r Parish, State
				Rio Arrib	a NM
12. CHECK APPROPRIAT	E BOX(ES) TO IN	DICATE NATURE OF N	NOTICE, REPOR	T, OR OTH	ER DATA
TYPE OF SUBMISSION	T .	TV	DE OF ACTION		
T TPE OF SUBMISSION		11	PE OF ACTION		
X Notice of Intent	Acidize	Deepen	Production (S	Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	ŕ	
Subsequent Report		Fracture Treat	Reclamation		Well Integrity
	Casing Repair	New Construction	Recomplete		Other
Final Abandonment Notice	Change Plans	X Plug and Abandon	Temporarily	Abandon	
	Convert to Injecti	on Plug Back	Water Dispos	sal	
13. Describe Proposed or Completed Operation (clear					
following completion of the involved operations. testing has been completed. Final Abandonment determined that the final site is ready for final insp	Notices shall be filed or pection.)	lly after all requirements, in	cluding reclamation	, have been o	completed, and the operator ha
Energen Resources plans to plug a	and abandon the	Jicarilla 123 C #1	per the attac	hed proce	edure.
This will be a closed loop opera-	tion. NMOOD will	be notified 24 hr	s prior to co	mmencina	operation.
			- pulor 00 00		O F-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0
	011	CONG			
	-	CUIVS. DIV DICT.	-		·
BLM'S APPROVAL OR ACCEPTANCE	OF THIS	CONS. DIV DIST. 3	SEI	EATTA	CHED FOR
ACTION DOES NOT RELIEVE THE LE OPERATOR FROM OBTAINING ANY (LOOLE AND	AUG 08 2014			OF APPROVAL
AUTHORIZATION REQUIRED FOR O		-014	CUMPI	IIIUII I	JE AFFINOVAL.
ON FEDERAL AND INDIAN LANDS	LIGHTONS				
, . .					
14. I hereby certify that the foregoing is true and correct					
Name (Printed/Typed)	•				
Kyle Mason		Title Distri	ct Engineer		
Signature // Popper		Date 07/29/14	1		
THI	S SPACE FOR FED	ERAL OR STATE OF			
Approved by		Title D \ \			Date Ol.
Conditions of approval, if any, are attached. Approval of this no	tice does not warrant or cert	ify that Office	eum Engli	nee5	8 6 2014
the applicant holds legal or equitable title to those rights in the sentitle the applicant to conduct operations thereon.		FFO	_		

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PLUG AND ABANDONMENT PROCEDURE

June 16, 2014

Jicarilla 123 C #1

So. Blanco Pictured Cliffs 930' FNL, 830' FWL, Section 7, T25N, R4W, Rio Arriba County, New Mexico

	API 30-039-06106 / Long / Lat:
Note:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
2.	Rods: Yes
	If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. Note: LD 1-1/4" tubing and PU workstring. Round trip gauge ring or casing scraper to 3350' or as deep as possible.
	NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or where a T.S. or CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
3.	Plug #1 (Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo tops 3350' – 2762'): TIH and set 4.5" CR at 3350'. Pressure test tubing to 1000#. Load casing with water and circulate well clean. Pressure test casing to 800#. If the casing does not test, then spot or tag subsequent plugs as appropriate. Mix 49 sxs Class B cement and spot a balanced plug inside the casing above the CR to isolate the Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo tops. TOH.
	Plug #2 (Nacimiento top 1822' – 1722'): Perforate squeeze holes at 1822'. Attempt to establish rate if the casing pressure tested. TIH and set CR at 1772'. Mix and pump 36 sxs Class B cement, squeeze 24 sxs outside 4.5" casing and leave 12 sxs inside casing to cover the Nacimiento top. TOH and LD tubing.
5. 6.	Plug #3 (7-5/8" surface casing shoe, 160' - Surface): Perforate 3 squeeze holes at 160'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 45 sxs Class B cement and pump down the 4.5" casing to circulate good cement out bradenhead. Shut in well and WOC.
7.	ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Jicarilla 123 C #1

Current

So. Blanco Pictured Cliffs 930' FNL, 830' FWL, Section 7, T-25-N, R-4-W, Rio Arriba County, NM / API #30-039-06106 Lat ______/ Long _____

Today's Date: 6/16/14 Spud: 7/14/56 7-5/8", 24#, J-55 Casing set @ 110' Completed: 8/6/56 Cement with 75 sxs (Circulated to Surface) 12-1/4" hole Elevation: 6993' GL Nacimiento @ 1772' *est TOC unknown did not circulate (Estimated TOC with 75% Calc at 2665') Ojo Alamo @ 2812' Kirtland @ 3036' 1-1/4" 2.3# tubing at 3406' Fruitland @ 3190' Pictured Cliffs Perfs. 3390' - 3444' Pictured Cliffs @ 3388' 4-1/2", 9.5#, used Casing set @ 3513' Cement with 100 sxs (117 cf) 6-3/4" hole

TD 3513' PBTD 3483'

Jicarilla 123 C #1

Proposed P&A

So. Blanco Pictured Cliffs

930' FNL, 830' FWL, Section 7, T-25-N, R-4-W,

Rio Arriba County, NM / API #30-039-06106 Lat _____/ Long _____

Today's Date: 6/16/14

Spud: 7/14/56 Completed: 8/6/56

Elevation: 6993' GL

12-1/4" hole

7-5/8", 24#, J-55 Casing set @ 110' Cement with 75 sxs (Circulated to Surface)

Perforate @ 160'

Plug #3: 160' - surface Class B cement, 45 sxs

Nacimiento @ 1772' *est

Kirtland @ 3036'

Fruitland @ 3190'

Ojo Alamo @ 2812'

Pictured Cliffs @ 3388'

6-3/4" hole

Set CR @ 3350'

Pictured Cliffs Perfs. 3390' - 3444'

4-1/2", 9.5#, used Casing set @ 3513' Cement with 100 sxs (117 cf)

TD 3513' **PBTD 3483**' Sec COA

Plug #2: 1722' -1822' Class B cement, 36 sxs with 24 outside and 12 inside

Set CR @ 1772'

Perforate @ 1822'

TOC unknown did not circulate (Estimated TOC with 75% Calc at 2665')

Plug #1: 3350' -2762' Class B cement, 49 sxs

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	tó	notice	Ġf
Intention to	Αh	andon	•

Re: Permanent Abandonment Well: Jicarilla 123 C #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set plug #2 (1574-1474) ft. Inside/outside to cover the Nacimiento formation top.

Operator will run a CBL from 3350 ft., or as deep as possible, to verify cement top. Outside plugs may be revised, based on CBL result. Submit electronic copy of the log for verification to the following BLM address: tsalyers@blm.gov

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.