Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-021-20603
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, INVI 67303	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS  7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)		Libby Minerals LLC 1931
1. Type of Well: Oil Well Gas Well Other CO2 Well		8. Well Number 9-2-J
2. Name of Operator		9. OGRID Number
Reliant Exploration & Production	n, LLC.	251905
3. Address of Operator 10817 West County Road 60 Midland, TX 79707		10. Pool name or Wildcat
4. Well Location		
Unit Letter J : 1345 feet from the South line and 1331 feet from the East line		
Section 9		1 E NMPM County Harding
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
4451.3		
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
	(	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	<del>-</del>	
TEMPORARILY ABANDON	<u> </u>	DRILLING OPNS. P AND A
PULL OR ALTER CASING [	MULTIPLE COMPL   CASING/CEM	MENT JOB
OTHER:	☐ OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
•		·
C. Astarburant		
See Attachment		
		All AANC DIVINGT 3
		OIL CONS. DIV DIST. 3
		ии <b>в</b> 4 201Д
		JUL <b>2 4</b> 2014
1/2	,	0
the nort TO a	e and are as America	d form.
I hereby certify that the information	on above is true and complete to the best of my know	
	or closed according to NATOCD guidelines , a general perm	
SIGNATURE	TITLE Manage	DATE 7-8-14
· · · · · · · · · · · · · · · · · · ·		
Type or print name Vance Va	nderburg E-mail address: vance@reliantgas	es.com Telephone No.432-559-7085
For State Use Only		
ADDROVED DV. 18 2/18/14		
	TITI E	DATE 9/18/14
Conditions of Approval (if any).	Kell TITLE A	DATE 8/18/14

## · Libby Minerals LLC 1931 9-2-J

## 6/22/14

(08:00) MIRU Reliant Rig #1. KB = 10' AGL.

Inspected rig, drill collars, and drill pipe.

## 6/23/14

Wait on mechanic to correct issue with getting derrick raised up on rig.

# 6/24/14

Wait on leveling block valve assembly.

(18:00) Install new leveling block assembly. Did not correct issue. Could lift derrick if top drive was brought down to top of carousel.

## 6/25/14

Check pressures on main lifting rams. Pressures checked OK. Wait on flow meter to measure hydraulic flow to rams.

#### 6/26/14

Flow checked OK. Determination made that one of the rams is getting weak.

(06:00) Drill 12.25" surface hole from 0' to 753' / Average WOB 8 / 97 RTS / 400 gpm @ 770 psi.

(23:30) Circulate

## 6/27/14

(00:30) TOOH

(02:00) Ran 8.625, 24.0 lb/ft, J-55, ST&C, from 10' to 725'.

(03:30)Circulate

(10:30) MIRU O-Tex to pump surface cement job as follows:

Pressure tested lines to 1500 psi. Pumped 10 bbl spacer. Pumped 440 sks of Class C + 2% Calcium chloride cement at 14.8 ppg at 3.5 BPM and 25 psi. Dropped top plug and pumped 5 bbls displacement. Bridged off @ 880 psi. Removed landing jt and tried to pump displacement. Could not pump.

Cut off and weld on 8 5/8 collar. New 8 5/8 casing tally was 10' to 708'.

(14:30) Drill cement from 0' to210'.

(21:00)MIRU Renegade Wireline to run bond log. Top of cement @ 150'. Shoot four 1" holes @ 140'.

## 6/28/14

Circulate. Full returns to surface.

(07:30) MIRU O-Tex to pump surface cement job as follows:

Pressure tested lines to 500 psi. Pumped 10 bbl spacer. Pumped 100 sks of Class C + 2% Calcium chloride cement at 14.8 ppg at 2 BPM and 300 psi. Pumped 5 bbls H2O displacement. Shut well in with 300 psi. 22 bbls cement to surface. ✓

(13:00) Nipple up BOP.

(14:00)Drill cement from 60' to 708'.

(17:00) Pressure test csg to 1042 psi. Held for 30 minutes. Test ok.

(18:00) Drill 7 7/8 production hole from 708' to 1202' / Average WOB 12 / 120 RTS / 345 gpm @ 645 psi.

# 06/29/14

Dril 7 7/8 production hole from 1202' to 2224' / Average WOB 11 / 125 RTS / 340 gpm @ 1025 psi.

(22:30)Circulate and condition hole.

### 6/30/14

(02:30) TOOH

(05:30)MIRU Weatherford wire line.

(09:00)Ran 5 1/2 casing as follows: 5.5", 15.5#, J-55, 8 RD, casing from 8' to '.



(13:30) Circulate and Condition hole

(18:00)MIRU O-Tex to pump cement as follows:

Pressure tested lines to 2000 psi. Pump 10 bbls spacer. Pumped 345 sks lead cement Class C + 2% GYP + 3%Calcl2 + 2% SM + 1/8 lb per sk celloflake at 11.1 ppg at 4 bpm at 70 psi. Pumped 105 sks tail cement Class C + 2% GYP + 3%Calcl2 + 2% SM + 1/8 lb per sk celloflake at 13.2 ppg at 4 bpm at 70 psi. Dropped top plug. Displaced cement with 51 bbls water at 4 bpm and 450 psi. Bumped plug at 1000 psi.. Float equipment held. <u>Circulated 70 bbls to surface</u>. Plug down at 20:00 hours on 6/30/14. Nipple down BOP equipment and clean pits and location.

(23:30) Test 5 ½ csg to 980 psi. Held for 30 minutes. Test OK.

Rig released at 24:00 hours on 06/30/14. 🗸

