Form 3160-5 (November 1994)

16

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

REE CH	- 1	7.) - 20. T	3 1
りなにった。ハ	1161 FA	الستسا	'ا

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

AUG 29 2014

5.	Lease Serial No.
N	OO-C-14-20-3605

SUNDRY NOTICES AND REPORTS ON WELLS	,,,,		NOO-C-14-20-3605
Do not use this form for proposals to drill or reented	ran, - T		-6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160-3 (APD) for such propos	sals	· •	(Constitution of the Constitution of the Const

abandoned wen.	Ose i Oilli 3100-3 (Al D)	Tor such proposuls.	<u> </u>		
SUBMIT IN TRIPLICATE – Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No. NMNM87132		
1. Oil Well X Gas Well 2. Name of Operator	Other			8. Well Name a	e 5B Com 1
		3b. Phone No. (include area code) 505-632-3476 ext. 201		9. API Well No. 30-045-28507 10. Field and Pool, or Exploratory Area Basin Fruitland Coal	
1030' FNL X 1580' FEL "B" Sec.5-T25N-R11W	, 1.1, 0. 2 10, 2.00 4, 10.1,			11. County or Pa	nrish, State
12. CHECK APPROPRIATE BOX(ESTYPE OF SUBMISSION	S) TO INDICATE NATURE TYPE OF ACTION	OF NOTICE, REPORT,	OR OTHER DA	ТА	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Reclamation Recomplete Temporarily Water Dispo	Abandon	Water Shut-Off Well Integrity Other

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) ROWD SEP 9'14

Elm Rídge Exploration Co., LLC requests permission to plug and abandon the following well according to the OIL COMS. DIV. attached procedure.

SEE ATTACHED FOR **CONDITIONS OF APPROVAL**

Notify NMOCD 24 hrs prior to beginning **operations**

DIST. 3 BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Ti Amy Archuleta	tle Sr. Regulatory Supervisor		
Signature Da	August 22, 2014		
THIS SPACE FOR F	EDERAL OR STATE USE		
Approved by Troy Salvers	Title Petroleum Ena. Date 9 4 2014		
Conditions of approval if any, are attached. Approval of this notice does not warrant o certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

Elm Ridge Resources

Pertinent Data Sheet

Well Name:

Buena Suerte 5B Com #1

Footage:

1030' FNL and 1580' FEL

Location:

NWNE Section 5, T25N, R11W

County:

San Juan County, NM

API#:

Į,

30-045-28507

Field: Basin Fruitland Coal

Elevation: 6271' KB

TD: 1385' KB

PBTD: 1331' KB

Completed: 04/15/1991

Casing Record:

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
8-3/4"	7"	20#	J-55	131'	70.8 cu. ft. (Circ. to surface)
6-1/4"	4-1/2"	11.6#, 10.5#, 9.5#	N-80, J-55	1370'	218 cu. ft. (Circ. to surface)

Tubing: 1-1/2" tubing set at 1212'

Formation Tops:

Nacimiento

Surface 1087'

Fruitland Pictured Cliffs

1220'


Perforations:

Fruitland perforations: 1190'-1208'

Notes:

Wellbore Diagram Buena Suerte 5B Com #1 NWNE Sec. 5, T25N, R11W San Juan County, NM API #30-045-28507

Before



Wellbore Diagram Buena Suerte 5B Com #1 NWNE Sec. 5, T25N, R11W San Juan County, NM API #30-045-28507

After

Nacimiento - surface

8-3/4" OH 7" 20# J-55 set @ 131' Circulated cmt to surface

Fruitland - 1087'

Pictured Cliffs - 1220'

Fruitland perforations: 1190'-1208'

6-1/4" OH 4-1/2" 11.6#, 10.5#, 9.5# set @ 1439' Circulated cmt to surface TD: 1385'

Plugging Program for Buena Suerte 5B Com #1

- 1) MOL RU. TOOH with 1-1/2" tubing.
- 2) PU and TIH with 4-1/2" retainer to 1185'. Squeeze below retainer with 11 sx cmt.
- 3) Sting out, mix and pump 92 sx, or sufficient volume, to bring cement to surface inside 4-1/2" casing.
- 4) Cut off well head 4 feet below surface and remediate location in accordance with regulatory agencies' conditions of approval.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	to	notice	of
Intention to	Ah	andon	

Re: Permanent Abandonment Well: Buena Suerte 5B Com #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.