Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT						OMB N Expires: 5. Lease Serial No.		
Do aba	o not use thi	SUNDRY NOTICES AND REPORTS ON WE not use this form for proposals to drill or to re- doned well. Use form 3160-3 (APD) for such p				6. If Indian, Allottee of EASTERN NAV		
SUE	BMIT IN TRI	PLICATE - Other instruc	ctions on rev	elseside C	EIV	42.7 If Wnit or CA/Agre	ement, Name and/or No.	
I. Type of Well Oil Well Gas Well Other				SEP				
2. Name of Operator BP AMERICA PR	ODUCTION	Contact: CO E-Mail: Toya.Colvi	TOYA COLV	Farmingto	n Field, (9. API Well No. 2616-26326-0)0-D1	
3a. Address 3b. Phon				66-7148				
4. Location of Well (F			11. County or Parish,	and State				
Sec 16 T28N R12W SWNW 1720FNL 0810FWL 36.664730 N Lat, 108.122590 W Lon							SAN JUAN COUNTY, NM RCVD OCT 2'11	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE N					NATURE OF NOTICE, REPORT, OR OTHER DATA DIST. 3			
TYPE OF SUBMI	PE OF SUBMISSION TYPE OF ACTION							
D Nation of Intent		Acidize	🗖 Dee	pen	🗖 Prod	uction (Start/Resume)	□ Water Shut-Off	
Notice of Intent		Alter Casing	🗖 Frac	ture Treat	🗖 Recl	amation	Well Integrity	
Subsequent Report		🗖 Casing Repair	🗖 Nev	Construction	🗖 Reco	omplete	□ Other	
□ Final Abandonment Notice		Change Plans	🛛 Plug	g and Abandon	🗖 Tem	porarily Abandon		
		□ Convert to Injection	🗖 Plug	Plug Back Water Disposal				
If the proposal is to de Attach the Bond under following completion testing has been comp determined that the sit BP America Produ	epen directiona r which the wor of the involved leted. Final Ab te is ready for fi uction Comp	any finds no further poter	give subsurface the Bond No. or sults in a multipled only after all	locations and meas a file with BLM/BI e completion or rec requirements, inclu	ured and tru A. Required completion in ding reclama	e vertical depths of all pertin subsequent reports shall be a new interval, a Form 316 ttion, have been completed,	nent markers and zones. filed within 30 days i0-4 shall be filed once	
requests to plug the Please see attach								
	h NMOCD P	it Rule 19.15.17.9 NMAC	, BP America	Production Co	mpany wil	use a		
SEE ATTACHED FOR CONDITIONS OF APPROVAL Notify NMOCD 24 hrs prior to beginning operations Notify NMOCD 24 hrs prior to beginning operations OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS								
 I hereby certify that t Name (Printed/Typed) 	Co	#Electronic Submission For BP AMERICA mmitted to AFMSS for pro	PRODUCTIO	N CO, sent to th OY SALYERS of	ie Farming	ton 4 (15TS0002SE)		
	THE TREOD							
Signature	(Electronic S	ubmission)		Date 09/17/2	2014			
		THIS SPACE FO	R FEDERA	L OR STATE	OFFICE	USE		
_Approved By_TROY_SALYERS				TitlePETROLEUM ENGINEER Date 10/01/2		Date 10/01/2014		
certify that the applicant ho which would entitle the app	Office Farmington							
Title 18 U.S.C. Section 100 States any false, fictitious	I and Title 43 or fraudulent s	U.S.C. Section 1212, make it a tatements or representations as	crime for any pe to any matter w	rson knowingly an ithin its jurisdiction	d willfully to	make to any department or	agency of the United	


** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

NMOCD₁₀

GCU 214 E-GP

API: 30-045-26326-00 San Juan County, New Mexico Well Flac: 84652301

- 1. Notify NMOCD and BLM about P&A
- 2. MI&RU Service Rig
- 3. Record wellhead pressures
- 4. Blow well down and kill well
- 5. NUBOP. NDWH
- 6. Pull ¾" & 7/8" stick rods and pump out of 2-3/8" short string.
- 7. POOH with short string of 2-3/8" 4.7 lb/ft tubing string at 5380'
- 8. POOH with long string of 2-3/8" 4.7 lb/ft tubing string and LOKset packer at at 5966'
- 9. RIH with bit and scraper for 7"-23 lb/ft J-55 casing to 5700'. POOH
- 10. RIH with cement retainer for 7"-23 lb/ft J-55 casing and set at 5650'.
- 11. Sting into cement retainer and mix and pump 59 sks (12 bbls) of class G cement.
- 12. Un-sting from cement retainer and PU.
- 13. Balance 150 ft cement plug on top of retainer with 31.7 sks (6.5 bbls) class G cement . TOC 5500 ft.
- 14. RIH with second cement retainer for 7"-23 lb/ft J-55 casing and set at 5000'.
- 15. Sting into cement retainer and mix and pump 442 sks (91 bbls) of class G cement.
- 16. Un-sting from cement retainer and PU and reverse circulate well clean.
- 17. RIH on wireline and run radial CBL from 5000' to surface. POOH
- 18. Balance 2800 ft cement plug on top of retainer with 591 sks (121 bbls) class G cement . TOC 2200 ft.
- 19. RIH with wireline and perforate 1300-1305'. POOH
- 20. RIH with cement retainer and set at 1250'
- 21. Sting into cement retainer and establish injectivity
- 22. While stung into retainer, mix and squeeze 193 sks (39.5 bbls) of class G cement below the retainer and the 7" X 8-3/4" annulus to surface'.
- 23. Balance 1250 ft cement plug on top of retainer to surface' with 264 sks (54 bbls) class G cement. TOC surface inside 5-1/2" casing
- 24. Cut well head and weld plate with marker and P&A information



RCVD OCT 2'14 OIL CONS. DIV. DIST. 3

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Gallegos Canyon Unit #214E

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator will a CBL from 5000 ft. to surface, to verify cement top. Outside plugs may be revised, based on CBL result. Submit electronic copy of the log for verification to the following addresses: tsalvers@blm.gov, Brandon.Powell@state.nm.us

Note: H2S has not been reported in this section; however, low concentrations of H2S (<100ppm GSV) have been reported in the SW/NW section 15, 28N, 12W.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

 \mathbf{b}