
UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Sunday Notices and Reports on Wells



AUG 21 2014

		Canary Notices and Ne	٠ ٠٠ - ١	~ Louis	المرام ال
			Eurece o	5	/ (Lease Number NM-12021
	of Well Gas			6.	If Indian, All. or Tribe Name
				7.	Unit Agreement Name
	e of Operator			_	J
Max	D. Webb			8.	Well Name & Number
3. Addr	ess & Phone No. of Opera	ator	<u> </u>	_ 0.	Federal #3
BO	Poy 100 Formington NM	97400		9.	API Well No.
PO Box 190, Farmington, NM 87499					30-045-22139
Location of Well, Footage, Sec., T, R, M				10.	Field and Pool
700,	FSL & 790' FEL, Section 2'	7 T.27.N R.13.W			WAW PC.
	TOL & 790 TEL, Section 2	r, 1-27-IN, IX-10-VV,		11.	County & State San Juan County, NM
12. CHF(CK APPROPRIATE BOX T	O INDICATE NATURE (OF NOTICE, REPORT, OTI	IFR D	ΔΤΔ
	of Submission	Type of Action	J		
	Notice of Intent	X Abandonment	Change of Plans		CVD SEP 17'14
	X Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracture	ina [DIL CONS. DIV.
	<u>A</u> oubsequent report	Casing Repair	Water Shut off	g	DIST. 3
-	Final Abandonment	Altering Casing	Conversion to Inject	ion	
	bl	Other –			
o un				he wel	l as to plugging Il bore. Liability Il is retained until
Plug and A	Abandonment Summary:		surface	resto	ration is completed.
7/23/14	Rode cement equipment to location. Spot in and RU. Open up well; no pressures. Dig out plumb in bradenhead valve. RU 4-1/2" casing head. Blow well down. Pump 15 bbls of water down well. Drop 30 frac balls down well. Pump 15 bbls of water down well. Pressured up to 400 PSI. Spot plug #1 with 117 sxs (138.06 cf) Class B cement pump 10 sxs drop 30 frac balls, pump additional 107 sxs locked up at 500 PSI. SI well. MOL. RU A-Plus wireline. RIH with 3-1/8" HSC and tag TOC high at 55'. POH. Note: J. Hagstorm, BLM and Max Webb approved to use poly pipe. Dig out wellhead. Chip out cement. SI well. SDFD.				
7/24/14	Travel to location. Fill out Hot Work Permit. Monitor well for LEL, no LEL. Cut off wellhead. Tag TOC in 4-1/2" casing at 55', unknown in 8-5/8" casing. Run poly pipe 100' down 8-5/8" casing. Spot plug #2 with 46 sxs (54.28 cf) Class B cement top off with 1" poly pipe down 100' in 8-5/8" casing and install P&A marker. RD and MOL, ✓				
14. I her	eby certify that the forego	ing is true and correct	•		
Signed_(MAX D. Webb	C Title Ope	rator	[Date7/30/14
	ace for Federal or State Offi	ce use)			Dota
APPROV CONDIT	ION OF APPROVAL, if any	Title			Date
			n knowingly to make to any	depart	ment or agency of the
United St	tates any false, fictitious or	fraudulent statements or	representations as to any n	natter	With It it for is the is the interest of the i

SEP 15 2014