

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: EPNG Com B LS 3M	Facility Type: Natural Gas Well Location	
Surface Owner: State	Mineral Owner: State	API No.: 3004533119

**LOCATION OF RELEASE**

Unit Letter L	Section 32	Township T31N	Range R10W	Feet from the 2150	North/South Line South	Feet from the 725	East/West Line West	County: San Juan
------------------	---------------	------------------	---------------	-----------------------	---------------------------	----------------------	------------------------	------------------

OIL CONS. DIV DIST. 3

Latitude 36.85381 Longitude 107.91246

OCT 27 2014

**NATURE OF RELEASE**

Type of Release: Natural Gas	Volume of Release: 520 MCF	Volume Recovered: none
Source of Release: rupture disk	Date and Hour of Occurrence: 10/19/14 10pm to 10/23/14 9am	Date and Hour of Discovery: 10/23/14 9am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith-NMOCD	
By Whom? Courtney Cochran-BP	Date and Hour: 10/23/14 4:15pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Field technician found gas blowing from rupture disk vent pipe on L-PUD separator. Initial thought is the high low valve was allowing gas to leak by while the well was shut-in at the choke. The vessel pressured up and the rupture disk blew. Currently the well is shut-in at the well-head and repairs will be made.

Describe Area Affected and Cleanup Action Taken.\*

No clean-up possible, natural gas dissipated to atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Courtney Cochran		Approved by Environmental Specialist: 	
Title: Environmental Coordinator		Approval Date: 10/26/14	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com		Conditions of Approval:	
Date: 10/23/2014 Phone: 505-326-9457		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

FILES 142.0131708