Form 3160-5 FORM APPROVED DEPARTMENT OF THE INTERIOR (August 2007) OMB No. 1004-0137 SEP . 30 2014 BUREAU OF LAND MANAGEMENT Expires: July 31, 2010 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS SF-077730 6. If Indian, Allottee or Tribe Name RCVD OCT 17'14 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. OH COMS DILL SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. DIST. 3 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Sunray E 1B 9. API Well No. 2. Name of Operator **Burlington Resources Oil & Gas Company LP** 30-045-30913 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 3a. Address PO Box 4289, Farmington, NM 87499 (505) 326-9700 Blanco MV / Basin DK 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Surface UNIT J (NWSE), 1730' FSL & 1900' FEL, Sec. 9, T30N, R10W San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Fracture Treat Reclamation Well Integrity Alter Casing X Subsequent Report Casing Repair New Construction Recomplete Other **Pump Repair** Change Plans Plug and Abandon Temporarily Abandon Sundry Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 9/15/14 - MIRU DWS. ND WH. NU BOPE. PT BOPE. Test OK. TOOH w/ 2 3/8" tubing. CO to PBTD @ 7662'. 9/16/14 - TOOH w/ 2 3/8" tubing 9/18/14 - CO to PBTD @ 7662' 9/19/14 - TIH w/ RBP, set @ 4070'. PT RBP to 600# and 4.5" csg to 575#/30 min. Good Test 9/22/14 - TOOH w/ RBP 9/23/14 - TIH w/ 244 jts., 2 3/8", 4/7#, J-55 tubing set @ 7564' (new set depth) w/ FN @ 7497'. ND BOPE. NU WH. 9/24/14 - TIH w/ Rods & pump, pump seated @ 7523, PT pump & tbg to 1000 #/15 min. Test Good. RD RR @ 18:00 hrs on 9/24/14 ACCEPTED FOR RECORD OCT 1 0 2014 FARMINGTON FIELD OFFICE BY: William Tambekon 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Arleen White** Staff Regulatory Technician Title White White Date Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify Office that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

NMOCDA

(Instruction on page 2)