Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
District I	Energy, Minerals and Natural Resources		October 13, 2009		
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-031-07025		
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE		
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					
PROPOSALS.)			Hospah Sand Unit 8. Well Number #61		
1. Type of Well: Oil Well Gas Well Other					
2. Name of Operator Dominion Production Co. L.I.C.			9. OGRID Number		
Dominion Production Co. LLC 3. Address of Operator			291567 10. Pool name or Wildcat		
1414 W. Swann, Suite 100, Tampa Florida 33606			Hospah		
4. Well Location					
Unit Letter E : 3640' feet from the South line and 1000' feet from the West line					
Section 01 Township 17N Range 9W			NMPM McKinley County		
	11. Elevation (Show whether DR,			· · · · · · · · · · · · · · · · · · ·	County
	7073' GR, 7009' KB			•	
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	Appropriate Box to Indicate Na TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	SUB REMEDIAL WOR COMMENCE DRI CASING/CEMEN	SEQUENT K LLING OPNS.	REPORT OF	
OTHER:		OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.			OIL CONS. DIV DIST. 3		
Please see the attached plugging report.				DEC 0 0 00	14.4
Approved for plugging of wellbore only. Liability under bond is retained pending Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web page under forms www.emnrd.state.us/ocd					
I hereby certify that the information	above is true and complete to the bea	st of my knowledge	e and belief.		
SIGNATURE Type or print name _ David Burns _ For State Use Only APPROVED BY: Conditions of Approval (if any):		dent davidburns@domi Jii. & JAS AISTRICT	nionproduction	OR nsa	832 545 4600 1 0 2014
	/) ' '				

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Dominion Production Co. LLC. **Hospah Sand Unit #61**

October 3, 2014 Page 1 of 2

3640' FSL and 1000' FWL, Section 1, T-17-N, R-9-W McKinley County, NM Lease Number: FEE API #30-031-07025

Cement Services Summary:

Plug #1 with CR at 1500' spot 12 sxs (14.16 cf) Class B cement inside casing from 1500' to 1345'.
Plug #1a with 12 sxs (14.16 cf) Class B cement inside casing from 1322' to 1167'. Tag TOC at 1150'.
Plug #2 with CR at 648' spot 44 sxs (51.92 cf) Class B cement inside casing from 700' to 493' with 5 sxs below the CR, 27 sxs outside and 12 sxs above the CR. Tag TOC at 451'.
Plug #3 with 35 sxs (41.3 cf) Class B cement inside casing from 130' to surface.

Plugging Work Details:

- 9/29/14 Rode wireline equipment to location. RIH with 4-1/2" gauge ring to 1507' and tag up. Attempt to work past 1507' no gain. Wait on orders. Note: B. Powell, NMOCD and R. Espinoza, BLM approved procedure change. RIH with 4-1/2" CR and set at 1500'. POH. SDFD.
- 9/30/14 Rode cement equipment to location. Spot in and RU. PU CR stinger. TIH and tally 47 jnts of 2-3/8" tubing sting into CR at 1500'. Attempt to establish rate, pressured up to 1000 PSI and bled down to 0 PSI in a minute. Establish circulation out casing. Sting out and same results. Circulate well clean with ¼ bbl of water. RU A-Plus wireline. Ran a CBL from 1500' to surface with calculated TOC at 850'. Spot plug #1 with calculated TOC at 1345'. TOH and unscrewed from 35 jnts and dropped into well. TIH with 11 jnts and screw into the fish at 1480'. Attempt to work tubing free, no gain or loss. SDFD.
- 10/1/14 Travel to location. RIH with 2.25 gauge ring to 1338'. POH. RIH with 2-7/8" tubing cutter to 1322' and cut the tubing. POH. PU on the tubing free pipe. TOH with 41 jnts and a 7' cut piece. Spot plug #1a with calculated TOC at 1167'. SDFD.
- 10/2/14 Travel to location. TIH and tag TOC at 1150'. Dig out bradenhead, no bradenhead found install 2" nipple on the bradenhead. RU A-Plus wireline. Perforate 3 HSC squeeze holes at 700'. Establish rate of 2.5 bpm at 550 PSI, pump 50 bbls of water no blow or flow out the bradenhead. Wait on orders. Note: M. Keuhling, NMOCD approved procedure change. RIH with 4-1/2" CR and set at 648'. POH. Establish rate of 2 bpm at 400 PSI. Spot plug #2 with calculated TOC at 493'. TOH and LD all tubing. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Dominion Production Co. LLC. Hospah Sand Unit #61

October 3, 2014 Page 2 of 2

Plugging Work Details (continued):

10/3/14 Travel to location. TIH and tag TOC at 451'. TOH and LD all tubing. Perforate 3 HSC squeeze holes at 130'. Establish rate of 2.5 bpm at 400 PSI. Spot plug #3 with TOC at surface. RD and MOL.

Rick Mahan, Dominion representative, was on location.