

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

DEC 12 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name of Company: BP	Contact: Jeff Peace	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9479	
Facility Name: Barrett LS 4	Facility Type: Natural gas well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 3004510598

LOCATION OF RELEASE

Unit Letter A	Section 20	Township 31N	Range 9W	Feet from the 1,190	North/South Line North	Feet from the 1,190	East/West Line East	County: San Juan
------------------	---------------	-----------------	-------------	------------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.88753 Longitude 107.79856

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 80 Mcf	Volume Recovered: none
Source of Release: cracked weld on inlet pipe to compressor scrubber	Date and Hour of Occurrence: 12/7/2014 – 12/9/2014 – 36 hours	Date and Hour of Discovery: December 9, 2014; 9:45 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Field tech found gas leaking through the cracked weld on the compressor scrubber inlet pipe. The compressor and well were shut in pending repair/replacement of the pipe.		
Describe Area Affected and Cleanup Action Taken.* No clean up was possible since the released gas dissipated into the atmosphere. The cracked pipe will be repaired or replaced.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jeff Peace	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: 1/8/15	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 11, 2014	Phone: 505-326-9479	

* Attach Additional Sheets If Necessary

#NCS 1500 855023

①