

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONFIDENTIAL

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.  
NM 12374 & NMNM 90843

6. If Indian, Allottee or Tribe Name

N/A

RECD OCT 17 '14  
OIL CONS. DIV.

SUBMIT IN TRIPLICATE - Other instructions on page 2

OCT 06 2014

7. If Unit of CA/Agreement, Name and/or No.

DIST. 3

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

Farmington Field Office

Bureau of Land Management

2. Name of Operator  
Encana Oil & Gas (USA) Inc.

8. Well Name and No.  
Nageezi Unit D34-2409 01H

9. API Well No.  
30-045-35440

3a. Address  
370 17th Street, Suite 1700  
Denver, CO 80202

3b. Phone No. (include area code)  
720-876-5867

10. Field and Pool or Exploratory Area  
Basin Mancos Gas Pool & Bisti Lower-Gallup

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
SHL: 1109 FNL and 509' FWL Section 34, T24N, R9W  
BHL: 585' FNL and 349' FWL Section 33, T24N, R9W

11. Country or Parish, State  
San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Completion
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Please see attached sheet detailing completion operations occurring between 9/13/14 - 10/05/14.

ACCEPTED FOR RECORD

OCT 07 2014

FARMINGTON FIELD OFFICE  
BY: William Tambekou

14. I hereby certify that the foregoing is true and correct.  
Name (Printed/Typed)

Cristi Bauer

Title Operations Technician

Signature

Cristi Bauer

Date

10/6/14

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCDA

**Nageezi Unit D34-2409 01H**

**API: 30-045-35440**

**9/13/14**

Set plug @ 10,231'. Perforated stage 1 as follows, 10,000'-10,180', 36 holes.

**9/14/14**

Frac stage #1: 25# 30% X-linkFoamed Gel, 2286 bbls Fresh H2O, 275,900#s of 20/40, 24,420#s of 16/30, N2 400,000 Mscf.

Drop 50 bio-balls to seal off stage #1. PU and perf stage #2 as follows, 9658'-9838', 36 holes.

Frac stage #2: 18# 30% X-link Foamed Gel, 2412 bbls Fresh H2O, 269,080#s of 20/40, 26,065#s of 16/30, N2 401,000 Mscf.

Set cfp @ 9,628' to seal off stage #2. Pull up and perf stage #3 as follows, 9320'-9496', 36 holes.

Frac stage #3: 18# 30% X-link Foamed Gel, 2200 bbls Fresh H2O, 281,560#s of 20/40, 23,221 #s of 16/30, N2 355,000 Mscf.

**9/15/14**

Drop 50 bio-balls to seal off stage #3. PU and perf stage #4 as follows, 8974'-9154', 36 holes.

Frac stage #4: 18# 30% X-linkFoamed Gel, 2245 bbls Fresh H2O, 277,690#s of 20/40, 25,800#s of 16/30, N2 385,000 Mscf.

Set cfp @ 8,944' to seal off stage #4. Pull up and perf stage #5 as follows, 8631'-8811', 36 holes.

**9/16/14**

Frac stage #5: 18# 30% X-linkFoamed Gel, 2087 bbls Fresh H2O, 275,380#s of 20/40, 26,352#s of 16/30, N2 397,000 Mscf.

Drop 50 bio-balls to seal off stage #5. PU and perf stage #6 as follows, 8288'-8468', 36 holes.

Frac stage #6: 18# 30% X-link Foamed Gel, 2130 bbls Fresh H2O, 278,980#s of 20/40, 29,433#s of 16/30, N2 356,000 Mscf.

Set cfp @ 8,258' to seal off stage #6. Pull up and perf stage #7 as follows, 7944'-8124', 36 holes.

Frac stage #7: 18# 30% X-link Foamed Gel, 2293 bbls Fresh H2O, 273,240#s of 20/40, 29,659 #s of 16/30, N2 459,000 Mscf.

**9/17/14**

Drop 50 bio-balls to seal off stage #7. PU and perf stage #8 as follows, 7601'-7781', 36 holes.

Frac stage #8: 18# 30% X-linkFoamed Gel, 2162 bbls Fresh H2O, 272,260#s of 20/40, 25,021#s of 16/30, N2 387,500 Mscf.

Set cfp @ 7571' to seal off stage #8. Pull up and perf stage #9 as follows, 7257'-7437', 36 holes.

Frac stage #9: 18# 30% X-link Foamed Gel, 1852 bbls Fresh H2O, 273,140#s of 20/40, 24,360#s of 16/30, N2 325,000 Mscf.

Drop 50 bio-balls to seal off stage #9. Pull up and perf stage #10 as follows, 6916'-7096', 36 holes.

**9/18/14**

Frac stage #10: 18# 30% X-linkFoamed Gel, 1949 bbls Fresh H2O, 273,660#s of 20/40, 24,650#s of 16/30, N2 333,000 Mscf.

Set cfp @ 6850' to seal off stage #10. Pull up and perf stage #11 as follows, 6577'-6757', 36 holes.

Frac stage #11: 18# 30% X-link Foamed Gel, 1766 bbls Fresh H2O, 275,120#s of 20/40, 27212#s of 16/30, N2 310,000 Mscf.

Drop 50 bio-balls to seal off stage #11. Pull up and perf stage #12 as follows, 6234'-6414', 36 holes.

Frac stage #12: 18# 30% X-link Foamed Gel, 1794 bbls Fresh H2O, 272,720#s of 20/40, 31,073#s of 16/30, N2 287,000 Mscf.

Set cfp @ 6204' to seal off stage #12. Pull up and perf stage #13 as follows, 5892'-6072', 36 holes.

**9/19/14**

Frac stage #13: 18# 30% X-link Foamed Gel, 1582 bbls Fresh H2O, 232,883#s of 20/40, N2 237,300 Mscf.

Drop 50 bio-balls to seal off stage #13. Pull up and perf stage #14 as follows, 5549'-5729', 36 holes.

Frac stage #14: 18# 30% X-link Foamed Gel, 1786 bbls Fresh H2O, 275,337#s of 20/40, 29,607#s of 16/30, N2 283,700 Mscf.

Set kill plug @ 5000'.

**9/30/14**

Mill out kill plug at 5000'.

**10/1/14**

Mill out CFP at 6204'.

**10/2/14**

Mill out CFP at 6850', 7571'.

**10/4/14**

Mill out CFP at 8258'.

**10/5/14**

Mill out CFP at 8944', 9628'.

Tubing details will be provided on a subsequent sundry.