		· · · · · · · · · · · · · · · · · · ·		
	UNITED STATES DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEM	IENT :	FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS NMSF078360				
Do not use this form for proposals to drill or to re-enter an			6. If Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals.			RCUD SEP 23 '14	
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No. NMNM 132829 CA	
			8. Well Name and No. DIST. 3	
Oil Well	Gas Well Other	ONFIDENTIAL	Chaco 2306-19E #189H	
2. Name of Operator WPX Energy Production, LL	с		9. API Well No. 30-043-21188	
3a. Address		înclude area code)	10. Field and Pool or Exploratory Area	
PO Box 640 Aztec, NM	4 87410 505-333-1806	· · · · · · · · · · · · · · · · · · ·	Lybrook Gallup	
4. Location of Well <i>(Footage,</i> SHL: 1757' FNL & 303' FWI BHL: 2196' FNL & 227' FWI			11. Country or Parish, State Sandoval, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA				
TYPE OF SUBMISSION		TYPE OF ACTIO	N	
Notice of Intent	Acidize Deepen	Production (S	tart/Resume) Water Shut-Off	
	Alter Casing Fracture T	reat Reclamation	Well Integrity	
Subsequent Report	Casing Repair New Cons	truction Recomplete	Other <b><u>COMPLETION</u></b>	
	Change Plans Plug and A	Abandon Temporarily A	Abandon	
Final Abandonment	Convert to Plug Back	Water Disposa	al	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)				
7/22/14- MIRU HWS #10 PRESSURE TEST TO 1500 PSI 30 MIN TEST HELD TEST PERFECTLY				
7/23/14- Run Tie back string- 4.5 , N-80 ,11.60 # ,EUE 8 rd,R 3 Casing As Follows Seal Assemley Tie Back no go, @ 5,959' 36jts @ marker jt. 20.10, Top, @ 4,507' 114 jts 14.44- 4.04-2.03 Subs 1jt. w/ 2'sub below Hanger, 30K on Tie Back, 24K on Hanger, 151 jts Totol, w/ 14.5 KB, Antolope pumped casing up to 1,500 psi & charted pressure test on 4.5 x 7' for 30 mins,				
<u>7/27/14-</u> CO to 10733'				
Perf Gallup 1 <sup>st</sup> stage, 10623'-10657' + RSI TOOL @ 10733' (final casing sundry reported 10726') with 18, 0.40" holes				
7/28/14 thru 8/10/14- Pre				
14. I hereby certify that the foreg Name (Printed/Typed)	going is true and correct.			
Larry Higgins	A	Title Regulatory Spec	sialist Sr.	
	14			
Signature Date 9/16/14 THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by				
		Title	Date	
or certify that the applicant holds	e attached. Approval of this notice does not w legal or equitable title to those rights in the su licant to conduct operations thereon.		· · ·	
Title 18 U.S.C. Section 1001 and United States any false, fictitious	Title 43 U.S.C. Section 1212, make it a crim	e for any person knowingly and wins to any matter within its jurisdiction	ilifully to make to any department or agency of the ACCEPTED FOR RECORD	

ā,

4

Copyright 2006 Forms in Word (<u>www.formsinword.com</u>). For individual or single-branch use only.

NMOCD~

$\mathcal{O}$
1
$\sigma$

FARMINGTON FIELD OFFICE BY: William Tambeken

#### Chaco 2306-19E #189H - page 2

# 8/11/14-Frac Gallup 1<sup>st</sup> stage 10,623'-10,733' -with 202,100 # 20/40 PSA Sand

Set flo-thru frac plug @ 10580' MD. Perf 2<sup>nd</sup> 10362'-10524'- with 24 total, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 202,000#, 20/40 PSA Sand Set flo-thru frac plug @ 10315' MD. Perf 3<sup>rd</sup> stage 10111'-10268' -with 24, 0.40" holes.

## 8/12/14-Frac Gallup 3rd stage with 200,300# , 20/40 PSA Sand

Set flo-thru frac plug @ 10070' MD. Perf 4<sup>th</sup> stage 9780'-10012'- with 24, 0.40" holes. Frac Gallup 4<sup>th</sup> stage with 199,800#, 20/40 PSA Sand Set flo-thru frac plug @ 9745' MD. Perf 5<sup>th</sup> stage 9424'-9671'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 199,700#, 20/40 PSA Sand Set flo-thru frac plug @ 9360' MD. Perf 6<sup>th</sup> stage 9113'-9315'- with 24, 0.40" holes. Frac Gallup 6<sup>th</sup> stage with 199,700#, 20/40 PSA Sand

8/13/14-Set flo-thru frac plug @ 9050' MD. Perf 7<sup>th</sup> stage 8857'-9014'- with 24, 0.40" holes.Frac Gallup 7<sup>th</sup> stage with 201,500#,20/40 PSA Sand

Set flo-thru frac plug @ 8810' MD. Perf 8<sup>th</sup> stage 8601'-8758'- with 24, 0.40" holes. Frac Gallup 8<sup>th</sup> stage with 198,000#, 20/40 PSA Sand Set flo-thru frac plug @ 8560' MD. Perf 9<sup>th</sup> stage 8350'-8500'- with 24, 0.40" holes. Frac Gallup 9<sup>th</sup> stage with 197,500#, 20/40 PSA Sand Set flo-thru frac plug @ 8315' MD. Perf 10<sup>th</sup> stage 8074'-8246'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 199,500#, 20/40 PSA Sand Set flo-thru frac plug @ 8010' MD. Perf 11<sup>th</sup> stage 7695'-7975'- with 24, 0.40" holes.

## 8/14/14-Frac Gallup 11<sup>th</sup> stage with 200,000#,20/40 PSA Sand

Set flo-thru frac plug @ 7640' MD. Perf 12<sup>th</sup> stage 7322'-7599'- with 24, 0.40" holes. Frac Gallup 12<sup>th</sup> stage with 198,000# 20/40 PSA Sand Set flo-thru frac plug @ 7264' MD. Perf 13<sup>th</sup> stage 7006'-7216'- with 24, 0.40" holes. Frac Gallup 13<sup>th</sup> stage with 301,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6950'MD. Perf 14<sup>th</sup> stage 6720'-6889'- with 24, 0.40" holes. Frac Gallup 14<sup>th</sup> stage with 300,400#, 20/40 PSA Sand Set flo-thru frac plug @ 6680'MD. Perf 15<sup>th</sup> stage 6424'-6611'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 301,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6680'MD. Perf 15<sup>th</sup> stage 6123'-6325'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 301,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 16<sup>th</sup> stage 6123'-6325'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 300,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 16<sup>th</sup> stage 6123'-6325'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 300,000#, 20/40 PSA Sand

8/15/14 - MIRU HWS #22

8/16/14 - Set 4-1/2" CIPB @ 2040'. TEST BOP, DO CIBP @ 2040'

8/17/14-DO flo thru Frac plug @ 6370', 6680', 6950', 7264', 7640', 8010', 8315', 8560', 8810' and 9050'

8/18/14- DO flo thru Frac plug @ 9360', 9745', 10070', 10315' and 10580'

Flow, test and C/O well 10733' MD

<u>8/19/14-</u>Land well at 5792' w/ 14' KB as follows 1/2 MS, 4 Jt of 2.375" J55 4.7lb 8rnd EUE tbg, 1.50" FN at 5761', 179 Jts of 2.375" J55 4.7lb 8rnd EUE tbg 180 jts total

#### 9/11/14-First deliver Oil to sales

Choke Size= 1", Tbg Prsr= 225 psi, Csg Prsr= 1290 psi, Sep Prsr= 120 psi, Sep Temp= 98 degrees F, Flow Line Temp= 98 degrees F, Flow Rate= 1431 mcf/d, 24hr Fluid Avg= 50 bph, 24hr Wtr= 386 bbls, 24hr Wtr Avg= 16 bph, Total Wtr Accum= 4720 bbls, 24hr Oil= 815 bbls, 24hr Oil Avg= 34 bph, Total Oil Accum= 991 bbls, 24hr Total Fluid= 1201 bbls

NOTE: 4-1/2" tie back string from surface to TOL @ 5960' will be removed at a later date when artificial lift is installed in this well.