Form 3160-5 (April 2004)

JAN 28 2015 FORM APPROVED **UNITED STATES** OM B No. 1004-0137 Expires: March 31, 2007 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 5. Lease Serial No NMSF, 078673 SUNDRY NOTICES AND REPORTS ON WELLS! 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Öil Well 🗆 🗈 ✓ Gas Well 🗆 8. Well Name and No. Schlosser No. 20S 2. Name of Operator M & G Drilling Company, Inc. API Well No 30-045-32481 3b. Phone No. (include area code) 3a Address P.O. Box 5940, Farmington, NM 87499 505-325-6779 10. Field and Pool, or Exploratory Area Basin FtC 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1980' FNL & 660' FWL, Section 10, T-27-N, R-11-W, San Juan County, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Well Integrity Fracture Treat Reclamation Casing Repair New Construction Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) M&G Drilling plugged and abandoned this well on August 18, 2014 per the attached report by A-Plus Well Service. A Closed Loop system was used.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.

P&A marker located at N 36* 35' 20" W 107* 59' 53"

RECEIVED

ACCEPTED FOR RECORD NMOCD

JAN 3 0 2015 DISTRICT III

FARMINGTON FIELD OFFICE BY: To Salvess

Contractor	
>	01/23/2015
STATE OFFIC	E USE
Title	Date
Office	

States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction

(Instructions on page 2)

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

M&G Drilling Company, Inc. Schlosser No. 20S

August 18, 2014 Page 1 of 1

1980' FNL and 660' FWL, Section 10, T-27-N, R-11-W San Juan County, NM Lease Number: NMSF-078673

API #30-045-32481

Plug and Abandonment Summary:

Plug and Abandonment Report Notified NMOCD and BLM on 8/13/14

- Plug #1 with 24 sxs (28.32 cf) Class B cement inside casing from 1918' to 1602' to cover the Fruitland top. ✓
- Plug #2 with 20 sxs (23.6 cf) Class B cement inside casing from 1074' to 811' to cover the Ojo Alamo top.√
- Plug #3 with 64 sxs (75.52 cf) Class B cement inside casing from 307' to surface with 24 sxs in casing and 40 sxs in annulus. ✓
- Plug #4 with 24 sxs Class B cement top off casings and install P&A marker with coordinates 36° 35 29" N 107° 59' 53" W√

Plugging Work Details:

- 8/15/14 Rode rig and equipment to location. Spot in and RU. Open up well; no pressures. Rusted wellhead cap rusted. Hammer off 8-5/8" cap and screw on 8-5/8" flange. NU BOP and Function test. TOH and tally 2-3/8" tubing 4.7#, J-55, EUE 29 stands (58 jnts) tubing, SN, total 1880.89' without KB. PU plugging sub. TIH and tag CIBP at 1918'. Establish circulation. Circulate well clean. Pressure test casing to 800 PSI, OK. Note: Dave Hinson, M&G Drilling, approved test. SI well. SDFD.
- 8/18/14 Open up well; no pressures. Establish circulation. Pressure test casing to 800 PSI, OK. Pressure test bradenhead to 300 PSI, OK. Calculated TOC at 216'. Note: M. Decker, BLM and D. Hinson, M&G request perforations at surface. Spot plugs #1 and #2. RU A-Plus wireline. Perforate 4 bi-wire holes at 257'. POH. Attempt to establish circulation out bradenhead locked up at 500 PSI. Note: M. Decker, BLM and D. Hinson, M&G approved procedure change. RU A-Plus wireline perforate 4 bi-wire holes at 157'. Establish circulation. TIH open-ended to 307'. Establish circulation. Spot plug #3 with TOC at surface. ND BOP and companion flange. Dig out wellhead. Check well for LEL. No LEL. Fill out Hot Work Permit. Cut off wellhead. Found cement down 45' in casing and 6' in bradenhead. Spot plug #4 top off with poly pipe and install P&A marker. RD and MOL.

Dave Hinson, M&G Drilling representative, was on location. Mark Decker, BLM representative, was on location. ✓