OIL CONS. DIV DIST. 3

	UNITED STATES NOV 2 4 2 EPARTMENT OF THE INTERIOR UREAU OF LAND MANAGEMENT			14 FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS 1.37 2 3 2514					
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit o	f CA/Agreement, Name and/or No.
1. Type of Well				0 111 1131	
Oil Well Gas Well Other				8. Well Name and No. Chaco 2308-04P #406H 9. API Well No.	
Name of Operator WPX Energy Production, LLC				30-045-35587	
3a. Address PO Box 640 Aztec, NM 8	3b. Phone No. <i>(include area code)</i> 505-333-1816		10. Field and Pool or Exploratory Area Basin Mancos (660')		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1323' FSL & 208' FEL SEC4 T23N R8W BHL:1052' FSL & 230' FWL SEC 4 23N 8W				11. Country or Parish, State San Juan, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Produc (Start/Resu		Water Shut-Off
Laborat	Alter Casing	Fracture Treat	Reclar	nation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recon	•	Other <u>COMPLETION</u>
23 Subsequent Report	Change Plans	Plug and Abandon	Lll Tempo Abandon	orarily	
Final Abandonment Notice	Convert to Injection	Plug Back		Disposal	
all pertinent markers and zone subsequent reports must be file	al is to deepen directionally s. Attach the Bond under wl ed within 30 days following , a Form 3160-4 must be fil	or recomplete horizontally, giv hich the work will be performed completion of the involved op- ed once testing has been complete.	re subsurface loca d or provide the B erations. If the op leted. Final Aband	tions and me ond No. on f eration result lonment Noti	asured and true vertical depths of ile with BLM/BIA. Required s in a multiple completion or ces must be filed only after all
10/22/14- RUN TIE BACK STRIN 1/2" 11.6# N80 casing, 17.95' \(\) 2.55' casing sub, and casing har with 40K on liner top and leavi Psi tested 7" X 4 1/2" to 1500 p	(4 1/2" 11.6# N80 casir nger. Total length of all T ng 12K on hanger. Antel	ng sub/ Marker Jt set @ 451 Tubulars ran in well = 5746 ope psi test 4 1/2" casing to	.3.42' - 4531.37' 31' . Had an up o 1500 psi, held	, 121 Jts 4 1 wt of 60K a for 30 minu	1/2" 11.6# N80 casing, 1 X and down wt of 52K. Landed
<u>10/23/14</u> -CO to 10420'					NOV 2 1 28.4
10/24/14-RD HWS #23		CONFI	DENTIA		FARMINGTON-FIELD OFFICE BY William Tambeke
14. I hereby certify that the foregoing Name (<i>Printed/Typed</i>)	is true and correct.				iii geroonalii
Lacey Granillo		Titl	e Permitting	Гесh	·
Signature ###			te 11/19/14		
Approved by	THIS SPACE FO	OR FEDERAL OR STA	T OFFICE	USE	
Прриотеа бу	V		Title	١,	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					
Title 18 U.S.C. Section 1001 and Title United States any false, fictitious or fr				to make to an	y department or agency of the
(Instructions on page 2)					

Chaco 2308-04P #406H - page 2

11/4/14-Perf Gallup 1st stage, 10174'-10358'- RSI WOULD NOT OPEN (FINAL CASING SUNDRY REPORTED RSI @ 10420') with 18, 0.40" holes

11/7/14-Frac Gallup 1st stage 10174'-10358'- with 196,600 # 20/40 PSA Sand

Set flo-thru frac plug @ 10100' MD. Perf 2nd 9888'-10074'- with 24 total, 0.40" holes. Frac Gallup 2nd stage with 206,000#, 20/40 PSA Sand Set flo-thru frac plug @ 9850' MD. Perf 3rd stage 9602'-9788'- with 24, 0.40" holes. Frac Gallup 3rd stage with 200,600#, 20/40 PSA Sand Set flo-thru frac plug @ 9550' MD. Perf 4th stage 9316'-9502'- with 24, 0.40" holes.

11/8/14- Frac Gallup 4th stage with 211,000#, 20/40 PSA Sand

Set flo-thru frac plug @ 9260' MD. Perf 5th stage 8985'-9216'-with 24, 0.40" holes. Frac Gallup 5th stage with 201,000#, 20/40 PSA Sand Set flo-thru frac plug @ 8955' MD. Perf 6th stage 8654'-8885'- with 24, 0.40" holes. Frac Gallup 6th stage with 200,500#, 20/40 PSA Sand Set flo-thru frac plug @ 8620' MD. Perf 7th stage 8308'-8554'- with 24, 0.40" holes. Frac Gallup 7th stage with 202,510#, 20/40 PSA Sand Set flo-thru frac plug @ 8240' MD. Perf 8th stage 8022'-8208'- with 24, 0.40" holes. Frac Gallup 8th stage with 200,600#, 20/40 PSA Sand Set flo-thru frac plug @ 7936' MD. Perf 9th stage 7736'-7922'- with 24, 0.40" holes. Frac Gallup 9th stage with 198,400#, 20/40 PSA Sand Set flo-thru frac plug @ 7680' MD. Perf 10th stage 7420'-7636'- with 24, 0.40" holes. Frac Gallup 10th stage with 201,500#, 20/40 PSA Sand Set flo-thru frac plug @ 7380' MD. Perf 11th stage 7107'-7320'- with 24, 0.40" holes. Frac Gallup 11th stage with 243,000#, 20/40 PSA Sand

11/9/14-Set flo-thru frac plug @ 7080' MD. Perf 12th stage 6800'-7035'- with 24, 0.40" holes. Frac Gallup 12th stage with 228,120# 20/40 PSA Sand

Set flo-thru frac plug @ 6750′ MD. Perf 13th stage 6487′-6703′- with 24, 0.40″ holes. Frac Gallup 13th stage with 238,500#, 20/40 PSA Sand Set flo-thru frac plug @ 6450′ MD. Perf 14th stage 6201′-6387′- with 24, 0.40″ holes. Frac Gallup 14th stage with 241,800#, 20/40 PSA Sand Set flo-thru frac plug @ 6150′ MD. Perf 15th stage 5912′-6100′- with 24, 0.40″ holes. Frac Gallup 15th stage with 238,500#, 20/40 PSA Sand Set 4-1/2″ CIPB @ 5020′

11/10/14-MIRU HWS #10

11/11/14-TEST BOP, DO CIBP @ 5020'

DO flo thru Frac plug @ 6150' and 6450'

11/12/14-lost circulation, MU string shot, RIH to SF, SU rig pump at 2 bpm, open SF and drop WL through, set on collar, set torque in tbg, fire string shot and back off tbg, POOH w/ WL, RD swivel. RU swivel and WL tools, MU string shot and RIH w/ WL to 5100' at top of curve, set torque in tbg, fire string shot and back off tbg, POOH w/ WL, RD swivel, PU 2.5" pwr swivel, MU kelly hose, SU N2, break circ at 1450 psi, unload well to FB tanks, flow until stable, then lost circ again, pump sweep and regain very little circ, heavy sand in returns, lost circ, pump 4 bbl sweep, regain circ, prsr increase to 500 psi and stabilized at 480 psi, circ well clean, bypass N2

11/13/14- Unable to TOOH w/ tbg due to lost circ, tbg beginning to stick and unable to establish circ, MIRU WL Specialties, MU string shot, RIH w/ WL to 5100', set torque in tbg, fire string shot and back off fish, POOH w/ WL and RD, PU 2.5" pwr swivel and MU kelly hose, SU N2, unload well at 5200' above TOF, heavy sand in returns, circ well clean. Tally, drift, and PU 12 jts of 2.375" PH6 DP w/ 2.5" pwr swivel, chase fish to top of CBP #4 at 6750', sting into fish and establish circ through mill, flow well until stabilized, MU into fish and torque against plug, well flowing stable.

DO flo thru Frac plug @ 6750', 7080', 7380', 7680', 7936' and 8240'

11/14/14-DO flo thru Frac plug @ 8620', 8955', 9260', 9550', 9850' and 10100' Flow, test and C/O well 10358' MD

Land well at 5516' w/ 14.5' KB as follows 1/2 MS, 1 Jt of 2.375" J55 4.7lb 8rnd EUE tbg, 1.50" FN at 5586', 179 Jts of 2.375" J55 4.7lb 8rnd EUE tbg 180 jts total

11/17/14-First deliver oil to sales

Choke Size=54/64", Tbg Prsr= 500 psi, Csg Prsr= 1030psi, Sep Prsr= 100 psi, Sep Temp= 115 degrees F, Flow Line Temp= 86 degrees F, Flow Rate= 595 mcf/d, 24hr Fluid Avg= 37 bph, 24hr Wtr= 166 bbls, 24hr Wtr Avg= 7 bph, Total Wtr Accum= 3221 bbls, 24hr Oil= 722 bbls, 24hr Oil Avg= 30 bph, Total Oil Accum= 1417 bbls, 24hr Total Fluid= 888 bbls

NOTE: 4-1/2" tie back string from surface to TOL @ 5745' will be removed at a later date when artificial lift is installed in this well.