Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			OMB1	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010	
			NMSF078580/	•	
			6. If Indian, Allottee	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse sid			7. If Unit or CA/Agr	eement, Name and/or No.	
I. Type of Well ☐ Oil Well ☐ Gas Well ⊠ Other: COAL BED METHANE			8. Well Name and No MOORE A 8		
2. Name of Operator BP AMERICA PRODUCTI	DYA COLVIN Øbp.com	9. API Well No. 30-045-27337-	9. API Well No. 30-045-27337-00-S1		
3a. Address 501 WESTLAKE PARK BL HOUSTON, TX 77079	b. Phone No. (include area code) Ph: 281-366-7148	10. Field and Pool, c BASIN FRUIT			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish	a, and State	
Sec 4 T30N R8W SWNE 1 36.843277 N Lat, 107.676		FEB 18 2015	SAN JUAN CO	DUNTY, NM	
12. CHECK A	PPROPRIATE BOX(ES) TOT	Earningeon Ficio Un NDICATENATURE OF I Iroau Ctilene Meneo	ICE NOTICE, REPORT, OR OTHI	ER DATA	
TYPE OF SUBMISSION		TYPE O	TYPE OF ACTION		
Notice of Intent	 Acidize Alter Casing 	Deepen	 Production (Start/Resume) Reclamation 	 Water Shut-Off Well Integrity 	
Subsequent Report	Casing Repair	□ New Construction		□ Other	
Final Abandonment Notice	e Change Plans	Plug and Abandon Plug Back	 Temporarily Abandon Water Disposal 		
If the proposal is to deepen direc Attach the Bond under which the following completion of the invo	I Operation (clearly state all pertinent d tionally or recomplete horizontally, giv e work will be performed or provide the blved operations. If the operation result al Abandonment Notices shall be filed of for final inspection.)	ve subsurface locations and measu e Bond No. on file with BLM/BIA ts in a multiple completion or reco	ared and true vertical depths of all pert A. Required subsequent reports shall b pompletion in a new interval, a Form 31	inent markers and zones. be filed within 30 days 60-4 shall be filed once	
BP America Production Co well. Please see the attach	ompany respectfully requests to ned procedure including wellbor	deepen and install liner in re diagrams and C-102 plat	the subject		
In accordance with NMOC closed-loop system during	D Pit Rule 19, 15.17.9 NMAC BI operations.	P America Production Com	pany will use a		
	CEIVED R 0 6 2015 MOCD	ACT OPF AUT ON	BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS		
14. I hereby certify that the foregoin	ng is true and correct. Electronic Submission #292 Eor BP AMERICA P Committee to AFMSS for proces	RUDULIIUN CU., sent to th	e Farmington		
Name(Printed/Typed) TOYA	COLVIN				
Signature (Electro	nic Submission)	Date 02/18/2	Date 02/18/2015		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By_TROY_SALYERS				Date 03/05/2015	
	ached. Approval of this notice does no or equitable title to those rights in the su conduct operations thereon.	ibject lease	Office Farmington		
	e 43 U.S.C. Section 1212, make it a cri lent statements or representations as to			or agency of the United	
	EVISED ** BLM REVISED *			ED **	

KP


Moore A 008 Coal API # 30-045-27337-00 Unit G - Sec 04 - T30N - R08W San Juan County, New Mexico


Reason/Background for Job

The proposed work is to pull existing liner, deepen the well to provide additional rathole and re-install liner to effectively produce the Fruitland Coal formation

Basic job procedure

- 1. Pull tubing
- 2. Pull liner
- 3. Deepen well to ± 3200' a mudloger will be on location while drilling
- 4. Run liner either pre-slotted or perforate after installation; liner might be run with bit and sub on bottom
- 5. Run tubing
- 6. Return well to production





Created by Neevia Document Converter trial version http://www.neevia.com