

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: San Juan 28-7 129F	Facility Type: Gas

Surface Owner: State	Mineral Owner: 016608	API No. 3003926966
-----------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter A	Section 02	Township 27N	Range 07W	Feet from the 770'	North/South Line FNL	Feet from the 545'	East/West Line FEL	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude **36.6080611** Longitude **-107.53521**

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 190 bbl	Volume Recovered 0
Source of Release Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1/17/2015 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith (OCD)	
By Whom? Lindsay Dumas	Date and Hour 1/17/2015 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
On 1/8/15 at approximately 1300, CIC doing routine inspection on separator and tank, found the swedge on the back side of the tank leaking. CIC contacted area supervisor and MSO. 10' X 5' area of contaminated soil identified. MSO immediately headed to location to place plug and dike to stop the leak. The loss of condensate was being investigated as possible vandalism or theft and then on 1/17/15 through soil sampling it was discovered it was a spill. Investigation is ongoing.

Describe Area Affected and Cleanup Action Taken.*
The area below the tank is contaminated. Excavation is underway.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 3/13/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/26/2015	Phone: (505) 599-4089	

* Attach Additional Sheets If Necessary

#NCS 15072 48091

①