

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS

abandoned well. Use Form 3160-3 (APD) for such proposals.

MAR 05 2015

5. Lease Serial No.

126

6. If Indian, Allottee, or Tribe Name

Jicarilla Apache Tribe

7. If Unit or CA/Agreement Name and/or No.

SUBMIT IN TRIPLICATE - Other Instructions on page 2.

1. Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

8. Well Name and No.

Apache No. 17

2. Name of Operator

Enervest Operating, LLC

9. API Well No.

30-030-039-21271

3a. Address

1001 Fannin St., Suite 800 Houston, TX 77002-6707

3b. Phone No. (include area code)

713-659-3500

10. Field and Pool, or Exploratory Area

So. Blanco P.C.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1850' FSL and 790' FEL (UL I) Section 11, T24N, 4W

11. County or Parish, State

Rio Arriba County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

st Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration if the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with the BLM/BIA. Required subsequent reports must be filed within 30 following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed c testing has been completed. Final Abandonment Notice must be filed only after all requirements, including reclamantion, have been completed, and the operator h determined that the site is ready for final inspection.)

EnerVest Operating, LLC proposes to plug and abandon this well.

P&A will commence prior to June 2015. The start and completion of this work is subject to changes due to rig availability, weather and road conditions.

A Closed-Loop System will be used for this operation. Attached are procedure and Wellbore Diagrams.

OIL CONS. DIV DIST. 3

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

MAR 19 2015

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Michelle Doescher

Title

Regulatory Consultant

Signature

Michelle Doescher

Date

March /04/2015

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Troy Salvers

Title PE

Date 3/16/2015

Conditions of approval, if any are attached. Approval of this notice does not warrant or c that the applicant holds legal or equitable title to those rights in the subject lease which w entitle the applicant to conduct operations thereon.

Office FFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the Unit fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD

KC

6

PLUG AND ABANDONMENT PROCEDURE

February 23, 2015

Apache #17

South Blanco Pictured Cliffs
1850' FSL and 790' FEL, Section 11, T24N, R4W
Rio Arriba County, New Mexico / API 30-039-21271
Lat: N 36.32209/ Lat: W -107.21815 (nad 27)

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

1. This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
3. Rods: Yes____, No X, Unknown____.
Tubing: Yes X, No____, Unknown____, Size 1.5", Length 2951'
Packer: Yes____, No X, Unknown____, Type____.
If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

TOH and LD 1.5" tubing. PU 2-3/8" tubing workstring.

4. **NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.**
5. **Plug #1 (Pictured Cliffs Interval, Fruitland, Kirtland and Ojo Alamo tops, 2899' – 2220'):** Round trip gauge ring or casing scraper to 2899', or as deep as possible. RIH and set 4.5" cement retainer at 2899'. Pressure test tubing to 1000 PSI. Load casing with water and circulate well clean. Pressure test casing to 800#. **If the casings do not test, then spot or tag subsequent plugs as appropriate.** Circulate well clean. Mix 56 sxs Class B cement to isolate the Pictured Cliffs Interval and tubing stub and cover through Ojo Alamo interval. TOH.
6. **See COA**
Plug #2 (Nacimiento top, 1030' – 930'): Perforate HSC squeeze holes at 1030'. Establish injection rate. RIH and set CR at 980'. TIH with tubing and sting into CR. Establish rate. Mix 51 sxs Class B cement, squeeze 39 sxs outside casing and leave 12 sxs inside casing. TOH.
7. **Plug #3 (8.625" Surface casing shoe, 201' – 0'):** Perforate 3 squeeze holes at 101'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix

approximately 75 sxs Class B cement and pump down the 4.5" casing to circulate good cement to surface. Shut in well and WOC.

8. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Apache #17

Current

South Blanco Pictured Cliffs

1850' FNL, 790' FEL, Section 11, T-24-N, R-4-W,

Rio Arriba County, NM / API #30-039-21271

Lat 36.32209 / Long -107.21815 (nad 27)

Today's Date: 2/23/15

Spud: 9/6/76

Completed: 9/22/76

Elevation: 6795' GL
6807' KB

Nacimiento @ 980' *est

Ojo Alamo @ 2270'

Kirtland @ 2636'

Fruitland @ 2850'

Pictured Cliffs @ 2948'

12.25" hole

8.625" 24#, Casing set @ 151'
Cement with 150 sxs, circulated to surface

1.5" tubing at 2951'


TOC unknown, did not circulate

Pictured Cliffs Perforations:
2949' - 2987'

4.5", 10.5#, K-55 Casing set @ 3079'
Cement with 150 sxs

7.875" hole

TD 3128'
PBTD 3049'



Apache #17

Proposed P&A

South Blanco Pictured Cliffs

1850' FNL, 790' FEL, Section 11, T-24-N, R-4-W,

Rio Arriba County, NM / API #30-039-21271

Lat 36.32209 / Long -107.21815 (nad 27)

Today's Date: 2/23/15

Spud: 9/6/76

Completed: 9/22/76

Elevation: 6795' GL
6807' KB

12.25" hole

Nacimiento @ 980' *est


Ojo Alamo @ 2270'

Kirtland @ 2636'

Fruitland @ 2850'

Pictured Cliffs @ 2948'

7.875" hole



8.625" 24#, Casing set @ 151'
Cement with 150 sxs, circulated to surface

Perforate @ 201'

Plug #3: 201' - 0'
Class B cement, 75 sxs

Set CR @ 980'

Perforate @ 1030'

TOC unknown, did not circulate

Plug #1: 2899' - 2220'
Class B cement, 56 sxs

Set CR @ 2899'

Pictured Cliffs Perforations:
2949' - 2987'

4.5", 10.5#, K-55 Casing set @ 3079'
Cement with 150 sxs

TD 3128'
COTD 2843'

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: Apache #17

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
3. Set plug #2 (1105-1005) ft. inside/outside to cover the Nacimiento formation top. BLM picks top of Nacimiento at 1055 ft.

Operator will run a CBL from 2899 ft., or as deep as possible, to verify cement top. Outside plugs may be revised, based on CBL result. Submit electronic copy of the log for verification to the following BLM and NMOCD address: tsalyers@blm.gov, Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.