

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P O Box 420, Farmington, NM 87499-0420	Telephone No.	505-326-4548
Facility Name	Anabel #1	Facility Type	Oil Well
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-045-24907

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	25N	8W	700	North	600	East	San Juan

Latitude 36.36278 Longitude -107.67924

**NATURE OF RELEASE**

Type of Release	crude oil	Volume of Release	Approx 10 bbls	Volume	None
Source of Release	Hammer union at wellhead	Date and Hour of Occurrence	03-12-15 time unknown	Date and Hour of Discovery	03-12-15 @ 1300 hrs
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Shari Ketchum (BLM) & Jonathan Kelly (NMOCD)		
By Whom?	Rodger Mullins	Date and Hour	3-12-15 @ 1545 hrs		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**OIL CONS. DIV DIST. 3**

**MAR 19 2015**



Describe Cause of Problem and Remedial Action Taken.\*

Oil was released from a loose hammer union at the wellhead. Pump unit was shut down and hammer union was tightened. All hammer unions will be checked for tightness on a regular basis.

Describe Area Affected and Cleanup Action Taken.\*

(On Location) - Oil was on ground on the NW (front) and SW (left side) of pump jack. (Off Location) - Oil ran off SW side of location approximately 400 feet then ran over a cliff and stopped on a flat spot at bottom of cliff. Narrow stream from 6" to 18" wide. Contaminated soil will be removed and replaced with clean soil. Sand stone will be scrubbed with simple green.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rodger Mullins	Approved by Environmental Specialist: 	
Title: Production Foreman	Approval Date: <u>4/7/15</u>	Expiration Date:
E-mail Address: rmullins@duganproduction.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: March 17, 2015 Phone: 505-325-1821		

\* Attach Additional Sheets If Necessary

#NCS 150973112

①