		· · · ·	•- • ·	· •	·	
	UNITED STA EPARTMENT OF TH JREAU OF LAND M	IE INTERIOR	DE	<b>C</b> 16 201	-	FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007
			•••		5: Lease Se	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
·	IT IN TRIPLICATE - Ot		<u> </u>	115.	7. If Unit of	CA/Agreement, Name and/or No.
1. Type of Well					132829	
Oil Well Gas Well Other					8. Well Name and No. NE CHACO COM #177H	
2. Name of Operator WPX Energy Production, LLC					9. API Well No. 30-039-31252	
3a. Address         3b. Phone No. (include           PO Box 640         Aztec, NM 87410         505-333-1816				ode)	10. Field and Pool or Exploratory Area Chaco Unit NE HZ (OIL)	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1132' FNL & 755' FWL SEC 6 T23N R6W BHL: 1348' FNL & 230' FWL SEC 1 23N 7W					11. Country or Parish, State Rio Arriba, NM	
12. CHECK T	HE APPROPRIATE BOX(	ES) TO INDICATE NA	TURE (	OF NOTICE, RI	EPORT OR C	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen		Start/Resu		Water Shut-Off
	Alter Casing	Fracture Treat		Reclar		Well Integrity Other
Subsequent Report	Casing Repair	New Constructio		Recom	•	Other COMPLETION
Final Abandonment Notice	Change Plans	Plug and Abando	on	Abandon	Janiy	
subsequent reports must be file recompletion in a new interval, requirements, including reclam 11/19/14- MIRU HWS #10 11/20/14-CO to 11469' 11/21/14-Ran a 4-1/2" packer at 61 the packer held good at 1500 psi fo good above the packer at 1500 psi fo 11/24/14-Run Tie Back String-Seal / 11/25/14-Pressure tested 7" x 4-1/. 1600 psi for 30 minutes – good test RD HWS #10 11/29/14-Perf Gallup 1 <sup>st</sup> stage, 113-	a Form 3160-4 must be file ation, have been completed 100' below the top of liner a r 30 min. Next we ran the p for 30 min. Assy/ nogo, 39jts of 4.5-11. 2" tieback backside to 1600	ed once testing has been of and the operator has det and tested below to 1500 backer to 6199' to ensure 50# P110-LTC casing,w/ 2 psi for 30 minutes – goo	complet ermined D psi and e that w 20' marl od test.	ed. Final Aband that the site is i l lost 600 psi in e were below th ker jt,@ 4496- 4 Pressure tested	lonment Notic ready for fina 6 min indicat he 7" interme 516 high 4-1/2" t	ces must be filed only after all l inspection.) ing a potential wet shoe. Above ediate casing point, which held ieback with packer set at 5465' to
14. I hereby certify that the foregoing Name ( <i>Printed/Typed</i> )	is true and correct.					
Lacey Granillo	~-//		Title	Permit Tech	<u>1</u>	<u>CONFIDENTIA</u>
Signature				12/16/14	. <u> </u>	OIL CONS. DIV DIST
	THIS SPACE FO	OR FEDERAL OR	STA	TE OFFICE	USE	DEC 1 9 2014
Approved by	$\sim$			<b>T</b> :41 -		
Conditions of approval, if any, are attactive applicant holds legal or equitable to applicant to conduct operations thereor	tle to those rights in the subje			Title Office	Į L	Date
Title 18 U.S.C. Section 1001 and Title United States any false, fictitious or fra					to/maketto?an	y department of agency of the
(Instructions on page 2)						
		magda			FARMING BY: WL	TOM FIELD OFFICE Riam Tambekou
Co	opyright 2006 Forms in Word	(www.formsinword.com)	. For inc	lividual or single	-branch use o	nly.

# NE CHACO COM #177H - page 2

#### 11/30/14-12/2/14- prepare for frac

# 12/3/14-Frac Gallup 1st stage 11347'-11473'- with 211,080 # 20/40 PSA Sand

Set flo-thru frac plug @ 11310' MD. Perf 2<sup>nd</sup> 11076'-11247'- with 24 total, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 214,224#, 20/40 PSA Sand Set flo-thru frac plug @ 11050' MD. Perf 3<sup>rd</sup> stage 10805'-10976'- with 24, 0.40" holes. Frac Gallup 3<sup>rd</sup> stage with 213,759#, 20/40 PSA Sand Set flo-thru frac plug @ 10760' MD. Perf 4<sup>th</sup> stage 10519'-10705'- with 24, 0.40" holes.

### 12/4/14- 12/6/14-wait on equipment

### 12/7/14-Frac Gallup 4<sup>th</sup> stage with 215,249#, 20/40 PSA Sand

Set flo-thru frac plug @ 10490' MD. Perf 5<sup>th</sup> stage 10143'-10419'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 215,083#, 20/40 PSA Sand Set flo-thru frac plug @ 10090' MD. Perf 6<sup>th</sup> stage 9737'-10043'- with 24, 0.40" holes. Frac Gallup 6<sup>th</sup> stage with 215,572#, 20/40 PSA Sand Set flo-thru frac plug @ 9690' MD. Perf 7<sup>th</sup> stage 9361'-9631'- with 24, 0.40" holes.

# 12/8/14- Frac Gallup 7th stage with 215,757# , 20/40 PSA Sand

Set flo-thru frac plug @ 9315' MD. Perf 8<sup>th</sup> stage 9070'-9255'- with 24, 0.40" holes. Frac Gallup 8<sup>th</sup> stage with 214,033#, 20/40 PSA Sand Set flo-thru frac plug @ 9025' MD. Perf 9<sup>th</sup> stage 8804'-8975'- with 24, 0.40" holes. Frac Gallup 9<sup>th</sup> stage with 213,321#, 20/40 PSA Sand Set flo-thru frac plug @ 8770' MD. Perf 10<sup>th</sup> stage 8533'-8704'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 214,776#, 20/40 PSA Sand Set flo-thru frac plug @ 8470' MD. Perf 11<sup>th</sup> stage 8247'-8433'- with 24, 0.40" holes.

## 12/9/14-Frac Gallup 11<sup>th</sup> stage with 216,125#, 20/40 PSA Sand

Set flo-thru frac plug @ 8210' MD. Perf 12<sup>th</sup> stage 7961'-8147'- with 24, 0.40" holes. Frac Gallup 12<sup>th</sup> stage with 215,500# 20/40 PSA Sand Set flo-thru frac plug @ 7898' MD. Perf 13<sup>th</sup> stage 7682'-7861'- with 24, 0.40" holes. Frac Gallup 13<sup>th</sup> stage with 214,925#, 20/40 PSA Sand Set flo-thru frac plug @ 7620' MD. Perf 14<sup>th</sup> stage 7404'-7575'- with 24, 0.40" holes.

# 12/10/14-Frac Gallup 14<sup>th</sup> stage with 263,991#, 20/40 PSA Sand

Set flo-thru frac plug @ 7360' MD. Perf 15<sup>th</sup> stage 7133'-7305'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 265,785#, 20/40 PSA Sand Set flo-thru frac plug @ 7100' MD. Perf 16<sup>th</sup> stage 6847'-7033'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 241,628#, 20/40 PSA Sand Set flo-thru frac plug @ 6810' MD. Perf 17<sup>th</sup> stage 6538'-6747'- with 24, 0.40" holes. Frac Gallup 17<sup>th</sup> stage with 266,081#, 20/40 PSA Sand Set flo-thru frac plug @ 6480' MD. Perf 18<sup>th</sup> stage 6206'-6431'- with 24, 0.40" holes.

12/11/14-Frac Gallup 18<sup>th</sup> stage with 264,166#, 20/40 PSA Sand Set 4-1/2" CIPB @ 4980'

12/12/14- MIRU HWS #10 TEST BOP, DO CIBP @ 4980'

12/13/14-DO flo thru Frac plug @ 6480', 6810', 7100', 7360', 7620', 7898', 8210', 8470', 8770' and 9025'

12/14/14- DO flo thru Frac plug @ 9315', 9690', 10090', 10490', 10760', 11050' and 11310' Flow, test and C/O well 11473' MD

12/15/14-Land well at 5821' w/ 14.5' KB as follows 1/2 MS, 1 Jt of 2.375" J55 4.7lb 8rnd EUE tbg, 1.50" FN at 5853', 178 Jts of 2.375" J55 4.7lb 8rnd EUE tbg 179 jts total

NOTE: will file flow back test info on delivery sundry

NOTE: 4-1/2" tie back string from surface to TOL @ 6025' will be removed at a later date when artificial lift is installed in this well.