OIL CONS. DIV DIST. 3

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

APR 01 2015

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

MAR 2 7 2015 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS N0-G-1401-1868 Do not use this form for proposals to drill or to result and Manage not If Indian, Allottce or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well 8. Well Name and No. Chaco 2308 08A #285H Oil Well Gas Well Other 2. Name of Operator 9. API Well No. WPX Energy Production, LLC 30-045-35643 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-333-1808 Nageezi Gallup / Basin Mancos 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State SHL:328' FNL & 334' FEL SEC 8 T23N R8W San Juan, NM BHL: 380' FSL & 230' FWL SEC 5 T23N R8W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production Water Shut-Off Acidize Deepen (Start/Resume) Notice of Intent Alter Casing Well Integrity Fracture Treat Reclamation Other Casing Repair New Construction Recomplete FINAL CASING Subsequent Report Temporarily Plug and Abandon Change Plans Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 3/21/15 thru 3/22/15 - Drill 6-1/8" lateral. 3/23/15-TD 6-1/8" lateral @ 10437' (TVD 5156'). 3/24/15 -Run 107jts, 4-1/2", P-110, 11.6#, LT&C. 8RD, CSG set @ 10432', LC @ 10388', RSI tool #1 @ 10328' & RSI tool #2 @ 10319, TOL @ 5634'. Test lines to 5400/psi & N2 lines to 6000/psi. Started pumping @ 4bbls/min, 10bbls FW, 40bbls tuned spacer @ 10.5ppg, 10bbls FW. Lead #1 35sx (6.0bbls) Elastiseal mixed @ 13.0ppg, YD 1.44CUFT/sx, water 6.92gal/sx, additives: 1% bentonite, 0.3% Halad R-567, 0.25% versaset, 0.10% HR-601, .05% SA-1015, Lead #2 239/sx (61bbls) mixed @ 13.0ppg foamed T/9.0ppg, YD 1.44 CUFT/sxs, water 6.92 gal/sx additives: 1% bentonite, 0.3% halad-567, 0.25% versaset, 0.05% HR-601. Tail 100/sx (23bbls) mixed @ 13.5ppg, YD 1.3CUFT/sx, water 5.81gal/sx, 1% bentonite, .25% Hal-567, .2% versa, .1% HR-601, .05% SA1015. Shutdown. Dropped dart. Displaced w/ 40bbls MMCR, 20bbls of 2% KCL (inhibited) 30bbls of FW, 37bbls of 2% KCL. Total 126bbls, Bumped plug @ 12:28 3/24/15. To 2200psi, prior psi 1568. Bled back 1.5bbls floats held. Dropped 1.75 setting ball, wait 30/mins pressure up 3815psi. Set liner, pull up to (165K) 50K over, slacked off to Neutral, confirm tool set. Rotate & release set tool. Circ., @ .5bbls/min pull out of liner then raise rate to 6bbls/min, roll hole with KCL. After tuned spacer shut annular and divert to blow tank. Circ., Obbls of foamed cement back to surface. With annular shut, pressured up to 1500psi & held for 30min-(test good). Bleed off psi, RD HES. LD cmt head. Notified BLM & NMOCD to inform, no cement to surface. Received verbal approval from BLM to continue with completions & no further requirement is needed. NMOCD is requiring WPX to run a CBL log on the 4 1/2" casing, prior to completions. 3/25/15 - PU/MU Seal assembly. TIH, run in w/ Tie back string. Seal assembly 126jts, 4 ½", P-110, casing 4 pup joints for space out, 1 full casing joint, mandrel. Land in PBR w/ seal assembly psi up on inside of 4 ½" casing verify seal assembly landed. TOOH 3 joints casing. TIH w/ 4 pup joints & full joint on top. Install landing mandrel. PU landing joint & land tie back w/ 49K on seal assembly. Test inside casing string @ 1500psi for 30mins-Held Good. Tested back side @ 1500psi for 30mins-Held Good. Left pressure up on back side. LD landing joint & antelope tested equipment. Install well cover. Rig released @ 07:00. 14. I hereby certify that the foreg Name (Printed/Typed) Marie E. Jaramillo Title Permit Tech Signature SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Date Title

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal

or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

(Instructions on page 2)

MAR 3 1 200

Office