

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
RECEIVED
FEB 13 2015

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Field Office
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. **SF-078096**

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Mudge B 100S

2. Name of Operator

ConocoPhillips Company

9. API Well No.

30-045-34876

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

10. Field and Pool or Exploratory Area

Basin Fruitland Coal

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit I (NESE), 1333' FSL & 670' FEL, Sec 21, T31N, R11W

11. Country or Parish, State

San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1/30/15 Contacted Brandon Powell/OCD (Mark Decker/BLM onsite) re Plug 1. Attempted to set CR @ 2150' & spot balance plug inside csg to cover tops/perfs. Stacked out @ 8'. BLM wants to set balance plugs w/out CR across & on top of perfs, doubling cmt, WOC over weekend & tag up to see if it's where it should be. Rec'd verbal approval w/call back to Brandon on Monday.

2/2/15 Tagged @ 1912'. PT was 810#/5min., no leaks. Contacted Brandon, okay to proceed.

OIL CONS. DIV DIST. 3

The subject well was P&A'd on 2/3/15 per the notifications above and the attached report.

MAR 30 2015

ACCEPTED FOR RECORD

MAR 24 2015

**FARMINGTON FIELD OFFICE
BY: T. Salyers**

**Approved as to plugging
of the well bore. Liability
under bond is retained until
surface restoration is completed.**

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Dollie L. Busse

Title **Staff Regulatory Technician**

Signature

Date

2/11/15

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Conoco Phillips

Mudge B 100S

February 3, 2015

Page 1 of 1

1333' FSL and 670' FEL, Section 21, T-31-N, R-11-W

San Juan County, NM

Lease Number: SF-078096

API #30-045-34876

Plug and Abandonment Report

Notified NMOCD and BLM on 12/31/14

Plug and Abandonment Summary:

- Plug #1** with 42 sxs (49.56 cf) Class B cement inside casing from 2450' to 1897' to cover the Pictured Cliffs top. Tag TOC at 1912'. ✓
- Plug #2** with 21 sxs (24.78 cf) Class B cement inside casing from 990' to 714' to cover the Kirtland and Ojo Alamo tops. ✓
- Plug #3** with 26 sxs (30.68 cf) Class B cement inside casing from 189' to surface to cover the surface casing shoe. Tag TOC at 8'. ✓
- Plug #4** with 38 sxs Class B cement top off casings and weld on P&A marker with coordinates 36° 52.859' N / 107° 59.395' W. ✓

Plugging Work Details:

- 1/29/15 Rode rig and equipment to location. Spot in and RU. Check well pressures: tubing and bradenhead 0 PSI, casing 140 PSI. RU relief lines. Blow well down. ND wellhead. NU BOP and kill spool. RU Well Check. Pressure test blind rams to 300 PSI and 1300 PSI, OK. RD Well Check. SI well. SDFD.
- 1/30/15 Bump test H2S equipment. Check well pressures: tubing and bradenhead 0 PSI, casing 140 PSI. RU relief lines. Blow well down. Function test BOP. TOH and tally 34 stds, 10 jnts, 2' sub, 1 jnt, SN, MS 2-3/8" tubing, tally total 2453'. PU 4-1/2" string mill. Attempt to TIH, stacked out at 8'. Wait on orders. Note: BLM approved procedure change. Spot plug #1 with calculated TOC at 1897'. SI well. SDFD.
- 2/2/15 Bump test H2S equipment. Check well pressures: no tubing, casing 10 PSI and bradenhead 0 PSI. Function test BOP. TIH and tag TOC at 1912'. Establish circulation. Pressure test casing to 800 PSI, OK. Establish circulation. Wait on orders. Spot plugs #2 and #3. Dig out wellhead. SI well. SDFD.
- 2/3/15 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 8'. ND BOP and kill spool. RU High Desert. Cut off wellhead. Found cement at surface in 4-1/2" casing and down 15' in annulus. Spot plug #4 top off casings and weld on P&A marker with coordinates 36° 52.859' N / 107° 59.395' W. RD and MOL. ✓

Jim Morris, MVCI representative, was on location.

Mark Decker, BLM representative, was on location. ✓

Don Sheets, Gomez Consulting, was on location 2/3/15.