

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

MAY 11 2015 State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Benson-Montin-Greer Drilling Corp.	Contact	Zach Stradling
Address	4900 College Blvd., Farmington, NM 87402	Telephone No.	(505) 325-8874
Facility Name	Native Son B #3	Facility Type	Oil Well
Surface Owner	Mineral Owner		API No. 30-039-23614

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	33	25N	2W	1850	FSL	790	FEL	Rio Arriba

Latitude N36.35036 Longitude W107.04966

#### NATURE OF RELEASE

Type of Release	Mixture of oil/condensate/produced water	Volume of Release	~80 bbls	Volume Recovered	0
Source of Release	Hole in production tank	Date and Hour of Occurrence		Date and Hour of Discovery	9:30 am 4/24/15
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Called Cory Smith at NMOCD immediately after incident was discovered		
By Whom?	Zach Stradling	Date and Hour	11:30 am on 4/24/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Source of problem was a hole near bottom of tank due to rust. The rest of the contents of the tank (1'-6") was removed and placed into another tank on location. Tank will be inspected and coated to prevent any further issues.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was inside the tank berm. Animas Environmental Services was contacted to investigate and collect soil samples to be lab analyzed. Lab results will be emailed to NMOCD once complete. Contaminated soil was removed from the location and taken to BMG's landfarm. NMOCD will be notified by BMG prior to backfilling the excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature:

Printed Name: Zach Stradling

Title: Operations Manager

E-mail Address: zstradling@bmgdrilling.com

Date: 5/7/15

Phone: (505) 325-8874

Approved by Environmental Specialist:

Approval Date: 5/12/15

Expiration Date:

Conditions of Approval:

Attached ☐

BMG LAND FARM

Must Be Able to Accept  
Waste And Be An Approved  
Facility

#NCS 1513238534

\* Attach Additional Sheets If Necessary