

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OIL CONS. DIV DIST. 3

Form C-141
Revised August 8, 2011

APR 06 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America	Contact: Jeff Peace
Address: 200 Energy Court, Farmington, NM 87401	Telephone No. (505) 326-9479
Facility Name: State Gas Com K 1M	Facility Type: Natural Gas Well

Surface Owner: State	Mineral Owner: State	API No. 3004531406
----------------------	----------------------	--------------------

LOCATION OF RELEASE

Unit Letter E	Section 16	Township 31N	Range 11W	Feet from the 2,105	North/South Line North	Feet from the 660	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	------------------------	---------------------------	----------------------	------------------------	--------------------

Latitude 36.89989 Longitude 108.0025

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 171 Mcf	Volume Recovered: None
Source of Release: failed rupture disk on separator	Date and Hour of Occurrence: 3/26/15; 5:00 PM	Date and Hour of Discovery: 3/30/2015; 11:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

BP Field tech visited well site after it had logged off and noticed the rain cap was off of the separator low side rupture disk. Upon further investigation he noticed the rupture disk had failed. The well was shut in.

Describe Area Affected and Cleanup Action Taken.*

The released gas dissipated into the atmosphere. No cleanup action was possible. The rupture disk will be replaced after an investigation has been completed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jeff Peace	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: 5/8/15	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 2, 2015 Phone: (505) 326-9479		

* Attach Additional Sheets If Necessary

#NCS 15 121856005