Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

尺匠	C	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals PR 1 6 2015					6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well		• •	Farmingto	n Field Offic	e n&nWell Name and No.		
☑ Oil Well ☐ Gas Well ☐ Oth	ner		Duleau Oi La	ild Mailego	n en Well Name and No. LYDIA RENTZ 11	A	
2. Name of Operator FOUR STAR OIL AND GAS C	9. API Well No. 30-039-2537			00-S1			
3a. Address HOUSTON, TX 77252	3b. Phone No. Ph: 505-33)	10. Field and Pool, or Exploratory W LINDRITH			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish,	and State	
Sec 19 T25N R3W NESW 849 36.378525 N Lat, 107.189315					RIO ARRIBA COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	☐ Dee	oen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclam	ation	■ Well Integrity	
Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	olete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempor	arily Abandon		
BO	Convert to Injection	Plug	Back	☐ Water I	Disposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f HOLE IN TUBING REPAIR 4/ 4/4/2015	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re pandonment Notices shall be fil inal inspection.)	, give subsurface the Bond No. or esults in a multipl	locations and measu file with BLM/BI/ e completion or rece	ired and true ve A. Required sub completion in a r	ertical depths of all pertin osequent reports shall be new interval, a Form 316	ent markers and zones. filed within 30 days 0-4 shall be filed once	
MIRU. R/U hot oiler & pump 4	Obbls 200deg 2% KCl do	own casing. P	ump additional 2	25bbls 200de	eg 2% KCl		
POOH w/ 44 rods (1100') & rods. Pump down tubing with hot oiler - to 1000psi -no bleed off. Pump 40bbls 200deg 2% KCL down casing. Pulled a total 112 of 7/8" rods & 1 of 3/4" rod. 4/5/2015 POOH w/ 410ft 1/4" capillary string banded to 2-3/8" production tubing. RIH & tag fill @8058' (PBTD 8090'). Pumped 20bbls 200deg 2% KCl down casing with hot oiler. Laid down total of 91jts to							
rod back-off point Pump 40bbls 200deg 2% KCl 2-3/8" equipment, lay down 3	down casing, perform ba	ack-off. POOH		•			
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission # For FOUR STAR Of mmitted to AFMSS for pro-	IL AND GAS C	DMPANY, sent to	the Rio Pue	rco		
Name (Printed/Typed) JIM MICIKAS			Title PRODUCTION ENGINEER				
Signature (Electronic S	Submission)		Date 04/16/2	015			
	THIS SPACE FO	OR FEDERA	-		SE	<u></u>	
Approved By ACCEPTED			TROY SA _{Title} PETROLE		YERS M ENGINEER Date 04/20		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Rio Pue	rco			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #298406 that would not fit on the form

32. Additional remarks, continued

Switch to 3/4" rod handling equipment. Perform back-off in tension. Laid down additional 35 rods. SWIFN. 4/6/2015

4/0/2015
POOH & laid down 31jts tubing to rod back off.
Perform rod back off in tension - came free. Laid down 1 joint tubing - picked up rod string - pulling free. Continue POOH & laid down remainder of rod string. Pump locking device parted.
POOH remainder of production string. Pump stuck unable to free it.
P/U & RIH w/ mule shoe, SN, 35jts new 2-3/8" L80, & TAC. Continue P/U w/ 85jts new 2-3/8" L80.

SWIFN.

4/7/2015

Install injection sub & RIH while banding capillary string. Mandrel valve set to open at 1400psi. RIH to 8052' (EOT) & set TAC (6883'). Injection sub @3911'.

Land tubing w/ 12,000lbs tension. Pressure test void to 1500psi - good.

New rod pump 2"x1-1/4"x20'x20'3" RHBC-Z w/ shear tool set @21,000lbs. RIH w/ 32 of 7/8" rods, 173 of 3/4" rods, & 114 of 7/8" rods. Space out. SWIFN.

4/8/2015

Pump 50gal corrosion inhibitor (25csg/25tbg)- chase w/10 bbls 2% KCl down both sides. Seat pump, test tubing to 500psi. Pump action - good. RDMO. WELL BORE DIAGRAM ATTACHED



Wellbore Schematic

