

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: San Juan 28-6 149M	Facility Type: Gas

Surface Owner BLM	Mineral Owner SF-079050-C	API No. 3003929270-
--------------------------	----------------------------------	----------------------------

LOCATION OF RELEASE

26251

Unit Letter O	Section 27	Township 28N	Range 6W	Feet from the 1120	North/South Line FSL	Feet from the 1845	East/West Line FEL	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude **36.628261** Longitude **-107.45151**

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release 7.45 bbl	Volume Recovered 25 gal
Source of Release Oil/Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 4/13/2015 3:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

MSO found liquid on the ground around production tank. Leak appears to be from bottom of tank. Well was shut in and remaining oil in tank was transported to different tank.

OIL CONS. DIV DIST. 3

MAY 07 2015

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 6/22/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/23/2015	Phone: (505) 599-4089	

* Attach Additional Sheets If Necessary

#NCS 1517349609