

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BP	Contact: Jeff Peace	
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9479	
Facility Name: Schwerdtfeger Gas Com 1	Facility Type: Natural gas well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 3004527382

LOCATION OF RELEASE

Unit Letter G	Section 27	Township 30N	Range 9W	Feet from the	North/South Line South	Feet from the	East/West Line West	County: San Juan
------------------	---------------	-----------------	-------------	---------------	---------------------------	---------------	------------------------	------------------

Latitude 36.87129 Longitude 107.76574

NATURE OF RELEASE

Type of Release: oil/condensate	Volume of Release: unknown	Volume Recovered: none
Source of Release: production pipeline	Date and Hour of Occurrence: June 4, 2015	Date and Hour of Discovery: June 4, 2015; 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith	
By Whom? Jeff Peace	Date and Hour: June 4, 2015; 1:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



OIL CONS. DIV DIST. 3

JUN 05 2015

Describe Cause of Problem and Remedial Action Taken.* Liquids were observed on the surface of a dry arroyo near the Schwerdtfeger Gas Com 1, apparently from a leak in a pipeline coming from the well. All visibly impacted soil was picked up by shovels and removed. Soil impacts were limited to less than one inch below the surface. Less than three cubic yards were removed and will be hauled to IEI landfarm.

Describe Area Affected and Cleanup Action Taken.* BP will use a hydrovac to find the leak in the pipeline and repair it. Samples will be taken of the remaining soil in the arroyo to determine if cleanup is complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jeff Peace	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>6/22/15</u>	Expiration Date:
E-mail Address: peace.jeffrey@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 5, 2015	Phone: 505-326-9479	

* Attach Additional Sheets If Necessary

#NCS 1517350 704