Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FEB 12 2015

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					Expires. Marc	131, 2007	
					5. Lease Serial No. NMSF-078359		
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No. 132829		
1. Type of Well							
Oil Well Gas Well Other					8. Well Name and No. NE Chaco Com #200H		
Name of Operator WPX Energy Production, LLC					Well No.		
3a. Address 3b. Phone No. (inc				30-039-31246 wea code) 10. Field and Pool or Exploratory Area			
PO Box 640 Aztec, NM 8	505-333-1816			Chaco Unit NE HZ (oil)			
4. Location of Well <i>(Footage, Sec., T.,R.,M., or Survey Description)</i> SHL:1417' FSL & '241' FWL SEC 8 T23N R6W BHL: 1436' FSL & 763' FWL SEC 7 T23N R6W				11. Cou	11. Country or Parish, State Rio Arriba, NM		
12. CHECK T	HE APPROPRIATE BOX(ES) TO INDICATE NAT	URE (OF NOTICE, REPORT C	R OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent	Acidize	Deepen		Production (Start/Resume)	me) water Shut-Off		
	Alter Casing	Fracture Treat		Reclamation	Well Integ	grity	
. ,	Casing Repair	New Construction		Recomplete	Other COMPLE	TION	
Subsequent Report	Temp			Temporarily	-		
	Change Plans	Plug and Abandor	1	Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal			
13. Describe Proposed or Complete duration thereof. If the proposa all pertinent markers and zones subsequent reports must be file recompletion in a new interval, requirements, including reclam 1/21/15- MIRU HWS #23 P110 4 1/2 tie back string, Drift, Tal 41 Jts 4 1/2" 11.6# p110 casing, 20 subs, , 1 X 2.44" casing sub, and cas on liner top and leaving 12K on har	I is to deepen directionally of Attach the Bond under who within 30 days following a Form 3160-4 must be file ation, have been completed by, PU, TIH with seal assembly X 4 1/2" 11.6# P110 casing ing hanger. Total length of	or recomplete horizontally ich the work will be performed the involve completion of the involved once testing has been countries and the operator has determined by, No-Go, and 4 1/2" P1: g sub/ Marker Jt set @ 39 all Tubulars ran in well = 5	y, give ormed of oper omplet of casi 10 casi 181.13.	subsurface locations and or provide the Bond No. ations. If the operation reted. Final Abandonment 1 that the site is ready for ng as follows; Seal Asser ' - 4003.13', 91 Jts 4 1/2" 4. Had an up wt of 68K	measured and true on file with BLM/ sults in a multiple Notices must be fil final inspection.) mbly with No-Go 5 11.6# P110 casin and down wt of 56	e vertical depths of BIA. Required completion or ed only after all .85" OD 4.00" ID, g, 195' casing SK. Landed with 44K	
1/22/15-CO.to 9984'						RECEIVED	
RD HWS #23					/-		
1/23/15-Perf Gallup 1 st stage, 9742'-9907' + RSI TOOL @ 9988' with 18, 0.40" holes				OUNEIL	FNTA	FEB 1 9 2015	
1/24/15-2/2/15- prepare for frac				1111	LIVIYAL	NIMOCD	
14. I hereby certify that the foregoing	is true and correct.					DISTRICTIU	
Name (Printed/Typed) Lacey Granillo			Title	Permit Tech III		Castillet in	
Signature				2/12/15			
	THIS SPACE FO	R FEDERAL OR	STA	TE OFFICE USE			
Approved by	W						
				Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certif the applicant holds legal or equitable title to those rights in the subject lease which would entiapplicant to conduct operations thereon.				Office			

Copyright 2006 Forms in Word (www.formsinword.com). For individual or single-branch use only.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

william Tambekou

NE CHACO COM #200H - page 2

2/3/15-Frac Gallup 1st stage 9742'-9988'- with 212,768 # 20/40 PSA Sand

Set flo-thru frac plug @ 9710' MD. Perf 2^{nd} 9396'-9636'- with 24 total, 0.40" holes. Frac Gallup 2^{nd} stage with 212,111#, 20/40 PSA Sand Set flo-thru frac plug @ 9360' MD. Perf 3^{rd} stage 9050'-9296'- with 24, 0.40" holes. Frac Gallup 3^{rd} stage with 223,882#, 20/40 PSA Sand Set flo-thru frac plug @ 8980' MD. Perf 4^{th} stage 8708'-8950'- with 24, 0.40" holes. Frac Gallup 4^{th} stage with 201,294#, 20/40 PSA Sand Set flo-thru frac plug @ 8640' MD. Perf 5^{th} stage 8416'-8604'-with 24, 0.40" holes.

2/4/15-Frac Gallup 5th stage with 216,438#, 20/40 PSA Sand

Set flo-thru frac plug @ 8390' MD. Perf 6^{th} stage 8132'-8318'- with 24, 0.40" holes. Frac Gallup 6^{th} stage with 208,180#, 20/40 PSA Sand Set flo-thru frac plug @ 8100' MD. Perf 7^{th} stage 7846'-8032'- with 24, 0.40" holes. Frac Gallup 7^{th} stage with 212,643#, 20/40 PSA Sand Set flo-thru frac plug @ 7800' MD. Perf 8^{th} stage 7560'-7747'- with 24, 0.40" holes. Frac Gallup 8^{th} stage with 224,005#, 20/40 PSA Sand Set flo-thru frac plug @ 7500' MD. Perf 9^{th} stage 7274'-7459'- with 24, 0.40" holes.

2/5/15-Frac Gallup 9th stage with 270,684#, 20/40 PSA Sand

Set flo-thru frac plug @ 7235' MD. Perf 10th stage 6943'-7174'- with 24, 0.40" holes. Frac Gallup 10th stage with 262,031#, 20/40 PSA Sand Set flo-thru frac plug @ 6920' MD. Perf 11th stage 6612'-6843'- with 24, 0.40" holes. Frac Gallup 11th stage with 266,043#, 20/40 PSA Sand Set flo-thru frac plug @ 6550' MD. Perf 12th stage 6311'-6512'- with 24, 0.40" holes. Frac Gallup 12th stage with 250,868# 20/40 PSA Sand Set flo-thru frac plug @ 6240' MD. Perf 13th stage 6010'-6211'- with 24, 0.40" holes.

2/6/15-Frac Gallup 13th stage with 276,864#, 20/40 PSA Sand Set 4-1/2" CIPB @ 5000'

2/8/15- pressure test 1500# good test MIRU HWS #6 TEST BOP, DO CIBP @ 5000'

2/9/15-DO flo-thru Frac plug @ 6240', 6550', 6920', 7235', 7500', 7800', 8100', 8390', 8640', 8980' and 9360'

2/10/15- DO flo thru Frac plug @ 9710'

C/O well to RSI tool @ 9988'

Pull tie back: 11.6# 4.5 P110 with seal assembly, No-Go, and 4 1/2" P110 casing as follows; Seal Assembly with No-Go 5.85" OD 4.00" ID, 41 Jts 4 1/2" 11.6# P110 casing, 20' X 4 1/2" 11.6# P110 casing sub/ Marker Jt, 91 Jts 4 1/2" 11.6# P110 casing, 1..95' casing subs, , 1 X 2.44" casing sub, and casing hanger.

NOTE: Delivery and flow back info will be reported on delivery sundry.