Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMSF078487A 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.	
Type of Well				SRM1535 8. Well Name and No.		
🗋 Oil Well 🛛 Gas Well 🔲 Other			JONES COM 4M			
2. Name of Operator Contact: TOYA COLV BP AMERICA PRODUCTION CO. E-Mail: Toya.Colvin@bp.com			IN	9. API Well No. 30-045-32197-00-C1		00-C1
3a. Address 200 ENERGY CT. FARMINGTON, NM 87401		3b. Phone No. (include area code) Ph: 281-366-71			10. Field and Pool, or Exploratory BASIN DAKOTA BLANCO MESAVERDE	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description		JUN 1 0 2015		11. County or Parish, and State		
Sec 31 T29N R8W NENW 95 36.687043 N Lat, 107.722370				SAN JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	Farmington Fie	Id Office NOTICE R anagement	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Dee	pen	Product	tion (Start/Resume)	U Water Shut-Off
□ Subsequent Report	□ Alter Casing	🗖 Frac	Fracture Treat		ation	U Well Integrity
	Casing Repair	_	_		Recomplete Dther	
□ Final Abandonment Notice	 Change Plans Convert to Injection 		g and Abandon g Back	_ 1 5		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Al determined that the site is ready for f BP America Production Comp	operations. If the operation re andonment Notices shall be fil inal inspection.) any respectfully requests	sults in a multipled only after all	the subject well	ompletion in a ding reclamatio	new interval, a Form 316 n, have been completed,	0-4 shall be filed once
the Blanco-Mesaverde only. P In accordance with NMOCD F closed-loop system during op	it Rule 19.15.17.9 NMAC	, BP America	Production Cor	0	se a	
	OILC	ONS. DIV	dist. 3	BLM'S A	PPROVAL OR ACCE	DPANOE OF STREET
SEE ATTACHED FOR JUN 1			BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND			
CONDITIONS OF A	ify NMOCD 2 ior to beginn operations	OCD 24 hrs eginning ON EEDEDAL ON REQUIRED FOR OPERATIONS				
 I hereby certify that the foregoing is Con 	true and correct. Electronic Submission # For BP AMERICA nmitted to AFMSS for prod	304524 verifie A PRODUCTIO cessing by TR	d by the BLM We N CO., sent to th DY SALYERS on	ell Information ne Farmingto 06/11/2015 (1	n System n 15TLS0273SE)	
Name(Printed/Typed) TOYA CO				LATORY AN		
Signature (Electronic Submission)			Date 06/10/2015			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE	
			THEFTOOL			Date 06/11/2015
Approved By_TROY_SALYERS Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lear which would entitle the applicant to conduct operations thereon.						
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a	crime for any post to any matter w	erson knowingly and	d willfully to m	ake to any department or	agency of the United
	ISED ** BLM REVISE				D ** BLM REVISE	D** XC

8

R

NMOCD

Jones Com 004M-MV/DK

API # 30-045-32197-00 Location: C SEC. 31, T29N, R08W San Juan County, New Mexico

Reason/Background for Job


The proposed work is to plug & abandon the Dakota formation and produce the well efficiently from the Mesaverde formation.

Currently there is a fish in hole across the Dakota formation. Tbg parted during a workover in 2014 and fishing attempts failed to retrieve the fish. Since then, formation sand is believed to have packed off around & above the fish, effectively isolating the Dakota perfs and causing the well to log off.

Basic job procedure

- 1. Pull tubing
- 2. RIH to set CIBP @ +/- 6,710'
- 3. RIH w/ 4-1/2" pkr and pressure test CIBP to 500psig
- 4. Pump 150' cement above CIBP (TOC ~ 6,560')
- 5. Land tubing @ +/- 4735'
- 6. Return well to production

TOC @ 2864' - CBL 8/26/04



BLM CONDITION OF APPROVAL

CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs. If a CBL or other logs are run, provide this office with a copy.
- 2. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minute test period. Provide test chart with your subsequent report of operations
- 3. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 4. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.