

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

BU	REAU OF LAND MANAGE	VIENT Farmington Freid	Office	105. 1441011 51, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No. NMNM 033003		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well				9	
Oil Well Gas Well Other			8. Well Name and No. NW Lybrook UT # 289H		
2. Name of Operator			9. API Well No.		
WPX Energy Production, LLC 3a. Address 3b. Phone No. (include area code)			30-045-35529	30-045-35529 10. Field and Pool or Exploratory Area	
PO Box 640 Aztec, NM 87410 505-333-1808			Lybrook Unit NW HZ(oil)		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Parish, State		
SHL: 255' FSL & 374' FWL, SEC 25, T24N, R8W BHL: 1010' FSL & 1051' FWL SEC 30 T24N R7W			San Juan, NM Rio Arriba, NM		
12. CHECK	THE APPROPRIATE BOX(ES) TO	INDICATE NATURE OF NOTIC	E, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize Deepen	Production (St	art/Resume)	Water Shut-Off	
Notice of intent	Alter Casing Fracture	Treat Reclamation		Well Integrity	
Subsequent Report	Casing Repair New Con	struction Recomplete		Other COMPLETION	
	Change Plans Plug and Abandon Temporarily Abandon		bandon		
Notice Final Abandonment.	Convert to Plug Back	k POOL NAME	CHANGE	•	
all pertinent markers and zon subsequent reports must be f recompletion in a new interv requirements, including recla 1/7/15- MIRU HWS #6 Run Tie Back String-No-Go, and 4 11.6# P-110 casing sub/ marker J	osal is to deepen directionally or recomnes. Attach the Bond under which the value of within 30 days following completival, a Form 3160-4 must be filed once the amation, have been completed and the 4½"11.6# P-110 casing as follows; Seal of the within 30 days follows; Seal of within 30 days following complete and the within 30 days follows; Seal of within 30 days follows; Se	work will be performed or provide ion of the involved operations. If the esting has been completed. Final A operator has determined that the sign of t	the Bond No. on file the operation results in Abandonment Notices ite is ready for final in .00" ID, 31 Jts 4 ½" 1: .5.95', 3.02', 2.10', c.	with BLM/BIA. Required in a multiple completion or smust be filed only after all inspection.) 1.6# P-110 casing, 20' X 4 1/2" asing subs, 1 jt 4 ½" 11.6# P-110	
1/8/15 - Pressure test 4.5" casing chart. All tests were good. RU &	g to 1500 psi, held for 30 minutes, and CO to 11924'	recorded on chart. PSI tested 7" >	〈 4 ½" to 1500 psi, he	eld for 30mins and recorded on	
	Perf Gallup 1 st stage, 11715'-11857' + I	RSI TOOL @11927' (final csg sundi	ry rpt'd 11926'), with	n 18, 0.40" holes	
<u>1/10/15 – 1/11/15</u> - Prepare for for	rac			PECELVES	
14. I hereby certify that the foregoin Name (Printed/Typed) Marie E. Jaramillo	ng is true and correct.	Title Permit Tech III		FFR 0 d 2016	
Signature		Date 1/28/15	\	7 2 2 2 2 2 2 3 3	
Olgitataro	THIS SPACE FOR FE	DERAL OR STATE OFF	ICE USE	NMOCD	
Approved by				DISTRICT	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Title	Da	te	
			ACCEP*	TED FOR RECORD	
Title 18 U.S.C. Section 1001 and Tit United States any false, fictitious or	itle 43 U.S.C. Section 1212, make it a crin fraudulent statements or representations	ne for any person knowingly and wil as to any matter within its jurisdiction	Ifully to make to any c	department or agency of the	

(Instructions on page 2)

Copyright 2006 Forms in Word (www.formsinword.com). For individual or single-branch use only.



NW Lybrook UT #289H - page 2

1/12/15-Frac Gallup 1st stage 11715'-11927'- with 205,134 # 20/40 PSA Sand

Set flo-thru frac plug @ 11650' MD. Perf 2nd stage11403'-11615'- with 24, 0.40" holes. Frac Gallup 2nd stage with 257,192#, 20/40 PSA Sand

1/13/15-

Set flo-thru frac plug @ 11340' MD. Perf 3rd stage 11181'-11302'- with 24, 0.40" holes. Frac Gallup 3rd stage with 220,000#, 20/40 PSA Sand Set flo-thru frac plug @ 11150' MD. Perf 4th stage 10866'-11094'- with 24, 0.40" holes. Frac Gallup 4th stage with 221,455#, 20/40 PSA Sand Set flo-thru frac plug @ 10800' MD. Perf 5th stage 10531'-10758'-with 24, 0.40" holes.

1/14/15-Frac Gallup 5th stage with 219,612#, 20/40 PSA Sand.

Set flo-thru frac plug @ 10460' MD. Perf 6^{th} stage 10216'-10413'- with 24, 0.40'' holes. Frac Gallup 6^{th} stage with 211,032#,20/40 PSA Sand Set flo-thru frac plug @ 10154' MD. Perf 7^{th} stage 9929'-10116'- with 24, 0.40'' holes. Frac Gallup 7^{th} stage with 226,381#, 20/40 PSA Sand Set flo-thru frac plug @ 9860' MD. Perf 8^{th} stage 9642'-9829'- with 24, 0.40'' holes.

1/15/15-Frac Gallup 8th stage with 214,500#, 20/40 PSA Sand.

Set flo-thru frac plug @ 9590' MD. Perf 9th stage 9350'-9547'- with 24, 0.40" holes. Frac Gallup 9th stage with 228,569#, 20/40 PSA Sand Set flo-thru frac plug @ 9290' MD. Perf 10th stage 9053'-9250'-with 24, 0.40" holes.

1/16/15 - Frac Gallup 10th stage with 213,743#, 20/40 PSA Sand

Set flo-thru frac plug @ 9010' MD. Perf 11th stage 8756'-8949'- with 24, 0.40" holes. Frac Gallup 11th stage with 227,132#, 20/40 PSA Sand Set flo-thru frac plug @ 8700' MD. Perf 12th stage 8459'-8656'- with 24, 0.40" holes. Frac Gallup 12th stage with 218,915# 20/40 PSA Sand Set flo-thru frac plug @ 8400' MD. Perf 13th stage 8165'-8359'- with 24, 0.40" holes.

1/17/15-Frac Gallup 13th stage with 220,646#, 20/40 PSA Sand

Set flo-thru frac plug @ 7560' MD. Perf 14th stage 7318'-7498'- with 24, 0.40" holes. Frac Gallup 14th stage with 267,646#, 20/40 PSA Sand Set flo-thru frac plug @ 7260' MD. Perf 15th stage 7034'-7216'- with 24, 0.40" holes. Frac Gallup 15th stage with 270,165#, 20/40 PSA Sand Set flo-thru frac plug @ 6980' MD. Perf 16th stage 6752'-6934'- with 24, 0.40" holes.

1/18/15-Frac Gallup 16th stage with 264,033#, 20/40 PSA Sand

Set flo-thru frac plug @ 6720' MD. Perf 17th stage 6440'-6652'- with 24, 0.40" holes. Frac Gallup 17th stage with 265,448#, 20/40 PSA Sand Set flo-thru frac plug @ 6380' MD. Perf 18th stage 6113'-6340'- with 24, 0.40" holes. Frac Gallup 18th stage with 281,572#, 20/40 PSA Sand

1/19/15-Set 4-1/2" CBP @ 5000'. RDMO Frac & WL.

1/20/14- MIRU HWS #6. Pressure Test BOP- OK.

1/21/15-DO CBP @ 5000'. DO flo-thru Frac plug @ 6380', 6720', 6980', 7260', and 7560'.

1/22/15 - DO flo-thru Frac plug @ and 8400', 8700', 9010', 9290', and 9590'.

1/23/15 - DO flo-thru Frac plug @ 9860', 10154'.

1/24/15 - DO flo-thru Frac plug @ 10460', 10800', 11150', 11340', and 11650'. C/O well to RSI tool @ 11927'.

1-25/15-Pulled and landed tieback string.

1/26/15 - RIH w/ gas lift & tubing. Land tbg at 6,060' as Follows, Hanger, KB 14.50' 36jts., of 2 7/8" 6.5# J-55tbg, GLV #9 @ 1,183' 24jts of 2.7/8" 6.5# J-55tbg, GLV #8 @ 1,955' 19jts of 2.7/8" 6.5# J-55tbg, GLV #7 @ 2,565' 17jts 2.7/8" 6.5# J-55tbg, GLV #6 @ 3,110' 16jts of 2.7/8" 6.5# J-55tbg, GLV #5 @ 3,622' 16jts of 2.7/8" 6.5# J-55tbg, GLV #4 @ 4,134' 16jts of 2.7/8" 6.5# J-55tbg, GLV #3 @ 4,651' 15jts of 2.7/8" 6.5# J-55tbg, GLV #2 @ 5,134' 16jts of 2.7/8" 6.5# J-55tbg, 5,651' pro-nipple 2.31, 5jts of 2.7/8" 6.5# J-55tbg, GLV #1 @ 5,817' 1jt of 2.7/8" 6.5# J-55tbg, @ 5,849' 4' Pup jt, 7"X 2.7/8" T-2 ON &Off Tool, w/ 2.25 F- nipple @ 5,855, 7"X 2.7/8 Arrowset 1- X 10 K packer, @ 5,863' X over 5jts 2.375tbg, @ 6,025', 2.375 X 1.79 " X Nipple @ 6,027', 1jt of 2.375 4.7# J-55tbg @ 6,059', 2.375 1/2 Mull shoe @ 6,060' EOT, Packer was set at 10K tension, Total 175jt 2.7/8 6.5# J-55 8rd tbg, Total 6jt 2.375 4.7# J-55 EUE 8rd, 70% Degrees. RD rig & Equipment.

NOTE: Delivery and flowback test information will be reported on delivery sundry.