Submitted in lieu of Form 3160-5 (June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

RECEIVED

JUL 13 2015

FORM APPROVED

Bureau or Land Management Farmington Field Office

Budget Bureau No. 1004-0135

Expires: March 31, 1993

1. Type of Well:		5. Lease Number:
Gas		SF-076958 6. If Indian, allottee or Tribe Name:
2. Name of Operator:	9 CAC COMPANY LD	
BURLINGTON RESOURCES OIL & GAS COMPANY LP 3. Address and Phone No. of Operator: P. O. Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec. T, R, U: FOOTAGE: 790' FSL & 1615' FEL S: 15 T: 029N R: 010W U: O		7. Unit Agreement Name: NMNM -76/68 MV NMNM -73965-DK 8. Well Name and Number: ALBRIGHT 8E 9. API Well No. 3004525056
		11. County and State: SAN JUAN, NM
12. CHECK APPROPRIATE BOX TO INDIC.	ATE NATURE OF NOTICE, RE	PORT, OTHER DATA
Notice of Intent X Subsequent Report Final Abandonment Abandonment	Recompletion Plugging Back Casing Repair Altering Casing X Other- Re-Delivery	Change of Plans New Construction Non-Routine Fracturing Water Shut Off Conversion to Injection
		Conversion to injection
	rations and produced natural gas and	
This well was re-delivered on 7/8/2015	rations and produced natural gas and	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT
This well was re-delivered on 7/8/2015 Notes: REDELIVERED ON 7/8/15	rations and produced natural gas and AFTER BEING SHUT-IN FOR	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT OIL CONS. DIV DIST. 3
This well was re-delivered on 7/8/2015 Notes: REDELIVERED ON 7/8/15 ISSUES.	rations and produced natural gas and AFTER BEING SHUT-IN FOR	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT OIL CONS. DIV DIST. (
This well was re-delivered on 7/8/2015 Notes: REDELIVERED ON 7/8/15 ISSUES. TP: 308 CP: 3	rations and produced natural gas and AFTER BEING SHUT-IN FOR	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT OIL CONS. DIV DIST. 3
This well was re-delivered on 7/8/2015 Notes: REDELIVERED ON 7/8/15 ISSUES. TP: 308 CP: 3 Meter No.: 14633270	rations and produced natural gas and AFTER BEING SHUT-IN FOR	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT OIL CONS. DIV DIST. (
This well was re-delivered on 7/8/2015 Notes: REDELIVERED ON 7/8/15 ISSUES. TP: 308 CP: 3 Meter No.: 14633270 Gas Co.: BR	rations and produced natural gas and AFTER BEING SHUT-IN FOR 310 Initial MCF: 5	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT OIL CONS. DIV DIST. 3 56 JUL 17 2015
This well was re-delivered on 7/8/2015 Notes: REDELIVERED ON 7/8/15 ISSUES. TP: 308 CP: 3 Meter No.: 14633270 Gas Co.: BR Proj Type.: REDELIVERY 14. I Hereby certify that the foregoing is true. Signed Also My	rations and produced natural gas and AFTER BEING SHUT-IN FOR 310 Initial MCF: 5	entrained hydrocarbons. MORE THAN 90 DAYS DUE TO SURFACE EQUIPMENT OIL CONS. DIV DIST. 3 56 JUL 17 2015