# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB NO. 1004-0135

	Expires:		
Lease Seri	al No.		

5.	Lease Serial No.
	NMSF080247

		Expirçs.	July	
5.	Lease Seri	al No.		
	NIMOLOG	02474		

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals \$\text{\$\sigma}\$ \$\frac{1}{20}\$			NMSF080247A  6. If Indian, Allottee of	т Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side. Farmington Field Office			-	ement, Name and/or No.		
1. Type of Well		•			18/1Well Name and No.	
Oil Well Gas Well Oth		DODALEN ( )			SIMMONS 7	
DJ SIMMONS INC	2. Name of Operator Contact: RODNEY L SEALE DJ SIMMONS INC E-Mail: rseale@djsimmons.com			9. API Well No. 30-045-11866-0		
3a. Address FARMINGTON, NM 87499			. (include area code) 26-3753 Ext: 119 7-4659		10. Field and Pool, or BLANCO PICTU	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	1)	=	. ,	11. County or Parish,	and State
Sec 25 T29N R9W SENE 168 36.699036 N Lat, 107.726288					SAN JUAN COL	JNTY, NM -
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURÉ OF N	IOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Frac	cture Treat	☐ Reclam	ation	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ Nev	v Construction	☐ Recomp	olete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	🛛 Pluş	g and Abandon	☐ Tempor	arily Abandon	
BP	☐ Convert to Injection	- 🗖 Plug	g Back	☐ Water I	Pisposal	
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab- determined that the site is ready for fi	ally or recomplete horizontally, it will be performed or provide operations. If the operation re bandonment Notices shall be fil	, give subsurface e the Bond No. or esults in a multip	locations and measur in file with BLM/BIA. le completion or recon	ed and true ve Required sub impletion in a r	rtical depths of all pertinosequent reports shall be new interval, a Form 316	ent markers and zones. filed within 30 days 0-4 shall be filed once
Please see attached files:					OIL CO	INS. DIV DIST. 3
150616 Simmons 7 Intent sundry proc.pdf containing the procedural steps to plug the well.			JL <b>29</b> 2015			
150616 Simmons 7 Current Condition Sketch.pdf containing a sketch of the current well configuration.						
150616 Simmons 7 Proposed after plugging.	Sketch.pdf containing a	sketch of the	proposed configu			EDTANCE OF THIS
SEE ATTACHED FOR Notify NMOGD ACTION DOES NOT RELIEVE THE LESSEE AND			VE THE LESSEE AND			
CONDITIONS	OF APPROVAL		beginning rations	AUTHO	RÍZATION REQUIR DERAL AND INDIAN	ED FOR OPERATIONS
14. I hereby certify that the foregoing is	Electronic Submission #				System	
Cor	For DJ Si nmitted to AFMSS for pro	immons inc, cessing by TR	sent to the Farmir OY SALYERS on 0	ngton 17/24/2015 (1	5TLS0322SE)	
Name (Printed/Typed) RODNEY	L SEALE		Title AGENT			
Signature (Electronic S			D . 00/40/00			
Signature (Electronic S	THIS SPACE FO	OR FEDERA	Date . 06/16/20		SF	· · · · · · · · · · · · · · · · · · ·
	THIS SI AGE I'M		LONGIAIL			
_Approved_By_TROY_SALYERS	`		TitlePETROLE	JM ENGINE	EER	Date 07/24/2015
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent to conduct the applicant	uitable title to those rights in th		Office Farming	-0.0		

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



H<sub>2</sub>S POTENTIAL EXIST



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# Simmons #7 (PC)

#### Procedure:

- 1) Back drag and clean location for crew & rig safety.
- 2) Move in well service unit and rig up with associated plugging equipment.
- Check pressure on tubing, casing and bradenhead. Bleed pressure off well. Nipple down wellhead and nipple up BOP.
- 4) Tag for fill with less than 2 jts. Trip out of hole with 99 jts 2 3/8" tubing with SN on bottom set at 3034'KB in April 1996.
- 5) Trip in with 3 7/8" bit and casing scraper for 4 1/2" 10.5# casing to bottom perforation at 3024'. **Do not attempt to load well.** If we need to circulate, we'll use air.
- 6) Trip out of hole.

# Pictured Cliffs - 2958', Fruitland Coal - 2666', Kirtland - 2058' and Ojo Alamo - 1948' Plug #1

- 7) Trip in hole with tubing to set cement retainer at 2940',
- 8) Load casing and circulate clean. Test casing to 300psi. Test tubing to 1,000psi.
- 9) Sting into retainer and inject 10 sx 15.6 ppg cement below retainer, sting out of retainer and spot 80 sx class B cement at 15.6 ppg, 1.18 cuft/sx on top to 1900'+/-. Split plug into parts if necessary, but leave a continuous plug. Total plug of 1124'+/- from 1900'+/- to 3024' with 4 sx through perfs. Minimize displacement through perfs to protect very near by coal bed methane well.
- 10) Circulate tubing clear. Wait on cement and tag if casing did not pass pressure test. Add cement as needed to protect Ojo Alamo top at 1948'+/-.
- 11) Mix 21 barrels inhibited water and spot from 1900'+/- to 600'+/-.
- 12) Trip out laying down tubing to land at 600'+/-.

#### Surface Plug #2

- 13) With tubing at 600'+/-, spot 46 sx class B cement at 15.6 ppg, 1.18 cuft/sx from 600'+/- to surface.
- 14) Trip out of hole.
- Refill tubing displacement.
- 16) Cut off wellhead and casings. Top off 4 1/2" casing and 8 5/8" casing filling to surface.
- 17) Install marker as indicated in stipulations.

Remove equipment and remediate location as indicated in lease agreements, conditions of approval and stipulations.



## Simmons #7 (PC)

Elevation: 6472' GL 6482' KB

8 5/8" CSA 120' w/ 150sx, circ

Location:

Surface: 1680' FNL, 880' FEL, Sec

25, T29N, R9W, San Juan

County, New Mexico

Field:

Blanco

Zone:

Pictured Cliffs Sand

API#:

03-045-11866

Spud Date: November 10, 1966

#### Directions to well:

From Bloomfield, NM go east on US Hwy 64 to 1/2 mile past mile post 81. Turn right to west on major lease road. Climb hill to right and then left for 1/2 mile. Keep straight taking right fork. Continue southerly for 6/10ths mile keeping straight taking left fork. Continue 1/10th mile taking left fork. Continue 1/4 mile taking right fork. Continue 1/2 mile keeping straight taking right fork. Continue 1/4 mile taking left fork. Continue 4/10ths mile taking left fork. Continue 9/10ths mile keeping straight on right fork. Continue 4/10ths mile. Turn left to south for 3/10ths mile passing through Simmons S #1 location to location.

9/22/1993; Cut and pulled 9# csg from 470', replace with 4 1/2" 10.5# csg and cement thru casing patch w/ 150sx, circ

9/23/1993; Squeeze 30sx. Initial pressure test fail. After drill out and retest to pass.

4/10/1996: Resqueeze 474'-479' with 50sx, drill out pressure test OK.

TOC: 990' by CBL on 9/17/1993 Petro Wireline

4/15/1996: 99 jts 2 3/8", SN w/ EOT at 3034'KB'

Perf 1 JSPF 2965'-3024', Reperf 2 JSPF in 1994 over same interval

PBTD: 3082'

4 1/2" at 3120' with 300 sx, TOC: unknown

TD:3145' PBTD: 3082'



### Simmons #7 (PC)

Elevation: 6472' GL 6482' KB

8 5/8" CSA 120' w/ 150sx, circ

Location:

Surface: 1680' FNL, 880' FEL,

Sec 25, T29N, R9W, San Juan

County, New Mexico

Field:

Blanco

Zone:

Pictured Cliffs Sand

API#:

03-045-11866

Spud Date: November 10, 1966

#### Surface Plug #2

With tubing at 600'+/-, spot 46 sx class B cement at 15.6 ppg, 1.18 cuft/sx from 600'+/- to surface.

9/22/1993: Cut and pulled 9# csg from 470', replace with 4 1/2" 10.5# csg and cement thru casing patch w/ 150sx, circ 9/23/1993: Squeeze 30sx. Initial pressure test fail. After drill out and retest to pass. 4/10/1996: Resqueeze 474'-479' with 50sx, drill out pressure test OK.

TOC: 990' by CBL on 9/17/1993 Petro Wireline

Mix 21 barrels inhibited water and spot from 1900'+/- to 600'+/-.

Pictured Cliffs - 2958', Fruitland Coal - 2666', Kirtland - 2058' and Ojo Alamo - 1948' Plug #1

Sting into retainer and inject 10 sx 15.6 ppg cement below retainer, sting out of retainer and spot 80 sx class B cement at 15.6 ppg, 1.18 cuft/sx on top to 1900'+/-. Split plug into parts if necessary, but leave a continuous plug. Total plug of 1124'+/- from 1900'+/- to 3024' with 4 sx through perfs. Minimize displacement through perfs to protect very near by coal bed methane well.

Trip in hole with tubing to set cement retainer at 2940',

Perf 1 JSPF 2965'-3024', Reperf 2 JSPF in 1994 over same interval

PBTD: 3082'

4 1/2" at 3120' with 300 sx, TOC: unknown

\* TD:3145' PBTD: 3082'

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	to notice of
Intention to	Abandon:

Re: Permanent Abandonment Well: Simmons PC #7

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a) Bring the top of plug #1 to 1804 ft. to cover the Pictured Cliifs, Fruitland, Kirtland and Ojo Alamo tops. Adjust cement volume accordingly.

Note: The CBL ran 9/17/1993 will suffice for plugging proposes.

Note: Low concentrations of H2S (2 ppm - <100 ppm GSV) have been reported in several wells within a 1 mile radius of this location

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.