

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

AUG 11 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: Mudge C1	Facility Type: Natural gas well

Surface Owner: Federal	Mineral Owner: Federal	API No. 3004510598 <b>23951 CS</b>
------------------------	------------------------	------------------------------------

## LOCATION OF RELEASE

Unit Letter M	Section 9	Township 31N	Range 11W	Feet from the 875	North/South Line South	Feet from the 875	East/West Line West	County: San Juan
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.90809°

Longitude -108.0117°

## NATURE OF RELEASE



Type of Release: natural gas	Volume of Release: 254 Mcf	Volume Recovered: none
Source of Release: Separation of ferule connection on intercooler piping.	Date and Hour of Occurrence: 7/30/2015 at ~1:00 PM	Date and Hour of Discovery: August 2, 2015 at 3:57 PM – 71 hours
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Field tech found gas leaking through a separated ferule connection on the compressor intercooler pipe. The compressor and well were shut in pending repair/replacement of the pipe connection.

Describe Area Affected and Cleanup Action Taken.\* No clean up was possible or necessary as the released gas dissipated into the atmosphere. The pipe connection will be repaired or replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: 8/2/15	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 6, 2015	Phone: 505-326-9497	

\* Attach Additional Sheets If Necessary

#NCS 1522443115