Form 3160-5

UNITED STATES

CON 04 127 T

MAY 1 1 2015

(February 2005)	DEPARTMENT O		R	1.41 0 ·		OMB No. 1004-0137	
	UREAU OF LANI				I	Expires: March 31, 2007	
			Farr	mington Fie	5. Lease Serial	No.	
SUNDRY NOTICES AND REPORTS ON WELLSureau of Land N					an No-G-7401	-1876	
Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name		
abandoned well. Use Form 3160-3 (APD) for such proposals.					791-91		
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA	A/Agreement, Name and/or No.	
1. Type of Well							
					8. Well Name and No.		
Oil Well Gas Well Other					Chaco 2308 04L #283H		
2. Name of Operator					9. API Well No.		
WPX Energy Production, LLC					30-045-35608		
3a. Address PO Box 640 Aztec, NM 87410		3b. Phone No. (include area code) 505-333-1808			10. Field and Pool or Exploratory Area Nageezi Gallup / Basin Mancos		
4. Location of Well (Footage,				11. Country or Parish, State			
SHL: 2431' FSL & 405' FWL, SEC 4, T23N, R8W					San Juan, NM		
BHL: 2225' FNL & 231' FWL SEC 5, T23N, R8W							
12. CHEC	CK THE APPROPRIAT	E BOX(ES) TO IND	ICATE NATURE	E OF NOTICE	, REPORT OR	OTHER DATA	
TYPE OF SUBMISSION TYPE OF AC				OF ACTION			
	Acidize	Acidize Deepen		roduction (Start	art/Resume) Water Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat	Reclamation Well Integrity		Well Integrity		
	Casing Repair	New Construc			Other COMPLETION		
Subsequent Report	Change Plans	Plug and Abar		emporarily Aba	endon		
Final Abandonment	Convert to						
Notice	Injection	Plug Back	P(OOL NAME C	HANGE		
proposal is to deepen direction Bond under which the work w of the involved operations. If	nally or recomplete horizon ill be performed or provide the operation results in a mu	tally, give subsurface loc the Bond No. on file wi ultiple completion or rec	cations and measured th BLM/BIA. Requi completion in a new i	d and true vertica ired subsequent r interval, a Form	al depths of all per reports must be file 3160-4 must be file	I approximate duration thereof. If the tinent markers and zones. Attach the ed within 30 days following completion led once testing has been completed. determined that the site is ready for final	
<u>.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>							
	f 4 ½" casing , casing sul g wt. Pressure tested 4	b (below hanger), cas ½" casing to 1500psi	ing hanger; Total	length of all to	ubular 5731.68,	8.85-4270.57, 95jts jts 4 ½", 2 landed w/ 44,000# on liner top, od. Pressure tested 7" intermediate	
4/6/15-TIH w/ 2-3/8" PH6 wor	k string & CO to 10343'.				AAH	IDENTIAL	
4/7/15-Nipple down BOP, Nipp	ole up frac valve. Rig do	wn HWS#17.			LUM	'IVENTIAL	
4/11/15-Perf Gallup 1 st stage,	10161'-10284' + RSI TO	OL @10345' with 18,	0.40" holes. RD.				
4/12/15-4/19/15- Prepare for							
14. I hereby certify that the foreg	oing is true and correct.	1					
Name (Printed/Typed) Marie E. Jaramillon				Title Permit Tech III			
Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	1				T		
			Title			Date 5/4/15	
Conditions of approval, if any, are or certify that the applicant holds	e attached. Approval of the	is notice does not warn	rant Office				

(Instructions on page 2)

lease which would entitle the applicant to conduct operations thereon.



ACCEPTED FOR RECORD



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Chaco 2308 04L #283H - page 2

4/20/15-Frac Gallup 1st stage 10161'-10345'- with 218,339# 20/40 PSA Sand

Set flo-thru frac plug @ 10110' MD. Perf 2nd stage 9875'-10061'- with 24, 0.40" holes. Frac Gallup 2nd stage with 215,741#, 20/40 PSA Sand Set flo-thru frac plug @ 9820' MD. Perf 3rd stage 9589'-9775'- with 24, 0.40" holes. Frac Gallup 3rd stage with 215,091#, 20/40 PSA Sand Set flo-thru frac plug @ 9540' MD. Perf 4th stage 9306'-9489'- with 24, 0.40" holes.

4/21/15-Frac Gallup 4th stage with 215,926#, 20/40 PSA Sand.

Set flo-thru frac plug @ 9240′ MD. Perf 5th stage 9017′-9203′-with 24, 0.40″ holes. Frac Gallup 5th stage with 216,280#, 20/40 PSA Sand Set flo-thru frac plug @ 8970′ MD. Perf 6th stage 8731′-8917′- with 24, 0.40″ holes. Frac Gallup 6th stage with 212,814#, 20/40 PSA Sand Set flo-thru frac plug @ 8680′ MD. Perf 7th stage 8445′-8631′- with 24, 0.40″ holes. Frac Gallup 7th stage with 212,696#, 20/40 PSA Sand Set flo-thru frac plug @ 8398′ MD. Perf 8th stage 8159′-8345′- with 24, 0.40″ holes. Frac Gallup 8th stage with 215,764#, 20/40 PSA Sand

4/22/15 -Set flo-thru frac plug@8090' MD. Perf 9th stage 7873'-8055'- with 24, 0.40" holes. Frac Mancos 9th stage with 217,776#,20/40 PSA Sand

Set flo-thru frac plug @ 7810′ MD. Perf 10th stage 7587′-7773′- with 24, 0.40″ holes. Frac Mancos 10th stage with 215,850#, 20/40 PSA Sand Set flo-thru frac plug @ 7550′ MD. Perf 11th stage 7301′-7490′- with 24, 0.40″ holes. Frac Mancos 11th stage with 212,940#, 20/40 PSA Sand Set flo-thru frac plug @ 7250′ MD. Perf 12th stage 7015′-7201′- with 24, 0.40″ holes. Frac Mancos 12th stage with 268,653# 20/40 PSA Sand Set flo-thru frac plug @ 6970′ MD. Perf 13th stage 6729′-6917′- with 24, 0.40″ holes

4/23/15- Frac Gallup 13th stage with 263,427#, 20/40 PSA Sand.

Set flo-thru frac plug @ 6680′ MD. Perf 14th stage 6447′-6629′- with 24, 0.40″ holes. Frac Mancos 14th stage with 263,266#, 20/40 PSA Sand Set flo-thru frac plug @ 6380′ MD. Perf 15th stage 6157′-6343′- with 24, 0.40″ holes. Frac Mancos 15th stage with 263,238#, 20/40 PSA Sand Set flo-thru frac plug @ 6112′ MD. Perf 15th stage 5871′-6055′- with 24, 0.40″ holes. Frac Mancos 15th stage with 253,990#, 20/40 PSA Sand Set 4-1/2″ CBP @5300′.

4/24/15-RDMO Frac & WL.

4/27/15- MIRU HWS #10. Pressure Tested BOP- OK.

4/28/15- DO CBP @ 5300'. DO flo-thru Frac plug @ 6112', 6380', 6680', 6970', 7520', 7550', 7810', 8090', and 8398'.

4/29/15- DO flo-thru Frac plug @ 8680', 8970, 9240', 9540, 9820', 10110', Circ., & CO well to 10343'.

Pulled and landed tieback string.

4/30/15- Land tbg @ 5,848', Start in hole w/ Gas lift system as follows, half mule shoe @ 5848', 1jt 2 3/8 tubing, 1.875 XN nipple w. 1.82 NOGO @ 5814', 4jts of 2 3/8 tubing, 2 3/8 x 2 7/8 V-Over, 7'X2 7/8 arrow-set packer @ 5684', on/off tool w/ 2.25F profile @ 5676, 1 4' 2 7/8 pup jt, 1jt 2 7/8 6.5# J-55 tubing, GLV #1 12jts 2 7/8, 2 7/8 2.313X Nipple @ 5266', 11jts GLV#2, 15jts, GLV#3, 14jts, GLV#4, 17jts, GLV#5, 16jts, GLV#6, 19jts GLV#7, 19jts GLV#8, 22jts GLV#9 37jts, Set packer and pack off 30K over, re-land hanger w/ 12K tension on packer, Hanger, 14.5 KB.

NOTE: Delivery and flowback test information will be reported on delivery sundry.