Form 3160-5

## UNITED STATES

FORM	[A]	PPR	OV	ED
OMB I	No.	100	4-0	137
Expires:	Ma	rch	31.	200

(February 2005)	DEPARTMENT O	F THE INTERIOR		52	OMB No. 1004-0137	
	BUREAU OF LAN	D MANAGEMENT			Expires: March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELL Sarmington Field			5. Lease Serial No. NMNM 109399			
Do not use this form for proposals to drill or to re-enter an			6. If Indian, Allottee or Tribe Name			
abandoned well. Use Form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of C	A/Agreement, Name and/or No.		
1. Type of Well			page 2.			
Oil Well Gas Well Other			8. Well Name and No. Chaco 2308 06I # 397H			
2. Name of Operator			9. API Well No.			
WPX Energy Productio  3a. Address	3b. Phone No. (include area code)		30-045-35639 10. Field and Pool or Exploratory Area			
PO Box 640 Azte	ec, NM 87410	505-333-1808	505-333-1808		Nageezi Gallup	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 2100' FSL & 325' FEL, SEC 6, T23N, R8W BHL: 2414' FSL & 458' FWL SEC 6, T23N, R8W			11. Country or Parish, State San Juan, NM			
	HECK THE APPROPRIAT	TE BOX(ES) TO INDICAT	TE NATURE OF NOTIC	E, REPORT OR	OTHER DATA	
TYPE OF SUBMISSIO	N	TYPE OF ACTION				
Acidize		Deepen	Deepen Production (Sta		art/Resume) Water Shut-Off	
Notice of Intent Alter Casing	Fracture Treat	Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete		Other COMPLETION	
	Change Plans	Plug and Abandon	Temporarily A	bandon		
Final Abandonment Notice	Convert to Injection	Plug Back	POOL NAME	CHANGE		
proposal is to deepen dire Bond under which the we of the involved operation Final Abandonment Noti inspection.)	ectionally or recomplete horizon ork will be performed or providence. If the operation results in a m	ntally, give subsurface location e the Bond No. on file with BL ultiple completion or recomple equirements, including reclam	s and measured and true vert M/BIA. Required subsequent etion in a new interval, a Fort	rical depths of all porter reports must be firm 3160-4 must be	nd approximate duration thereof. If the ertinent markers and zones. Attach the filed within 30 days following completion filed once testing has been completed. s determined that the site is ready for final	
for spacing (9.95, 9.85, 5.5	5, 2.05 and 1.85 ) 1jt of 4 ½ ressure tested 4 ½" casing t	" casing, 1 casing pup jt, c o 1500psi. Charted record	asing hanger, Casing land	ded @ 5533.68, I	, 101jts 4 ½" casing, 4 casing pup jts Landed casing w/ 28,000# on liner essure tested 7" intermediate casing	
4/22/15-TIH w/ 2-3/8" PH	6 work string & CO to 1034	4'. Shut in well.				
4/23/15 – Nipple down BC	P. Nipple up frac valve. RD	MO		CONFIL	SENTIAL	
4/28/15 - Perf Gallup 1st sta	age, 10140'-10265' + RSI TO	OOL @10347', with 18, 0.40	0" holes. RD	AAIII II	A SELL I I LANG	
5/1/15-5/3/15- Prepare fo	or frac.				OIL CONS. DIV DIST	
14. I hereby certify that the f	oregoing is true and correct.	/			MAY 1 8 2015	
Name (Printed/Typed) Marie E. Jaramillo	1	Titl	e Permit Tech III			
Signature	. 1	Dai				
	THIS SPA	CE FOR FEDERAL	L OR STATE OFF	ICE USE		
Approved by	WP YVI	W	Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office			
Title 18 U.S.C. Section 1001 United States any false, ficti					any department or agency of the	

(Instructions on page 2)

NMOCDITY

## Chaco 2308 06I #397H - page 2

5/4/15-Frac Gallup 1st stage 10140'-10437'- with 212,360# 20/40 PSA Sand

Set flo-thru frac plug @ 10080' MD. Perf 2<sup>nd</sup> stage 9768'-10014'- with 24, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 221,180#, 20/40 PSA Sand Set flo-thru frac plug @ 9725' MD. Perf 3<sup>rd</sup> stage 9467'-9668'- with 24, 0.40" holes. Frac Gallup 3<sup>rd</sup> stage with 217,580#, 20/40 PSA Sand Set flo-thru frac plug @ 9435' MD. Perf 4<sup>th</sup> stage 9166'-9367'- with 24, 0.40" holes. Frac Gallup 4<sup>th</sup> stage with 218,260#, 20/40 PSA Sand. Set flo-thru frac plug @ 9110' MD. Perf 5<sup>th</sup> stage 8865'-9066'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 223,080#, 20/40 PSA Sand Set flo-thru frac plug @ 8810' MD. Perf 6<sup>th</sup> stage 8564'-8763'- with 24, 0.40" holes.

## **5/5/15**-Frac Gallup 6<sup>th</sup> stage with 215,560#, 20/40 PSA Sand

Set flo-thru frac plug @ 8504′ MD. Perf 7<sup>th</sup> stage 8261′-8464′- with 24, 0.40″ holes. Frac Gallup 7<sup>th</sup> stage with 219,614#, 20/40 PSA Sand Set flo-thru frac plug @ 8210′ MD. Perf 8<sup>th</sup> stage 7962′-8163′- with 24, 0.40″ holes. Frac Gallup 8<sup>th</sup> stage with 220,840#, 20/40 PSA Sand Set flo-thru frac plug @ 7910′ MD. Perf 9<sup>th</sup> stage 7660′-7862′- with 24, 0.40″ holes. Frac Gallup 9<sup>th</sup> stage with 216,340#, 20/40 PSA Sand Set flo-thru frac plug @ 7600′ MD. Perf 10<sup>th</sup> stage 7360′-7561′- with 24, 0.40″ holes. Frac Gallup 10<sup>th</sup> stage with 219,620#, 20/40 PSA Sand Set flo-thru frac plug @ 7310′ MD. Perf 11<sup>th</sup> stage 7059′-7260′- with 24, 0.40″ holes. Frac Gallup 11<sup>th</sup> stage with 263,900#, 20/40 PSA Sand Set flo-thru frac plug @ 7030′ MD. Perf 12<sup>th</sup> stage 6758′-6959′- with 24, 0.40″ holes. Frac Gallup 12<sup>th</sup> stage with 260,560# 20/40 PSA Sand Set flo-thru frac plug @ 6725′ MD. Perf 13<sup>th</sup> stage 6454′-6658′- with 24, 0.40″ holes. Frac Gallup 13<sup>th</sup> stage with 265,340#, 20/40 PSA Sand Set flo-thru frac plug @ 6400′ MD. Perf 14<sup>th</sup> stage 6141′-6357′- with 24, 0.40″ holes.

5/6/15-Frac Gallup 14<sup>th</sup> stage with 263,060#, 20/40 PSA Sand

Set flo-thru frac plug @ 6090' MD. Perf 15<sup>th</sup> stage 5810'-6043'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 260,240#, 20/40 PSA Sand

5/7/15-RDMO Frac & WL.

5/8/15- MIRU Halliburton coil tbg. NU and Pressure Tested BOP- OK.

5/9/15 - DO flo-thru Frac plug @ 6090', 6400', 6725', 7030', 7310', and 7600'.

5/10/15-DO flo-thru Frac plug @ 7910', 8210', 8504', 8810', 9110', and 9435'.

5/11/15- DO flo-thru Frac plug @ 9725'and 10080'. Circ., & CO well to 10344'.

5/12/15-Pulled and landed tieback string.

Land tbg @ 5687', as Follows: Start in hole w/ Gas lift system as follows, half mule shoe @ 5687', 1jt 2 3/8 tubing, 1.875 XN nipple w/ 1.82 NOGO @ 5655', 7jts of 2 3/8 tubing, 7' X 2 7/8 arrowset packer @ 5438', on/off tool w/ 2.25 F profile @ 5431', 1 4' 2 7/8 pup jt, 1jt 2 7/8 6.5# J-55 tubing, GLV#1, 4jts 2 7/8, 2 7/8 2.313X nipple @ 5267', 14jts, GLV #2, 15jts, GLV #3, 14jts, GLV #4, 15jts GLV #5 17jts, GLV#6, 16jts, GLV #7, 19jt, GLV #8, 23jts, GLV #9, 37jts, hanger 14.5 KB.

NOTE: Delivery and flowback test information will be reported on delivery sundry.